

Locate A CFedS

Name (CFedS Number)	Contact Information	Licenses	Continuing Education (Credits Earned)
Daniel W. Ackerman (1011)	<p>Daniel W. Ackerman</p> <p>Bonneville Power Administration</p> <p>3315 X St</p> <p>Vancouver, WA 98663</p> <p>360-843-3585</p> <p>E-mail: dackerman@q.com</p>	WA PLS - 39572	<p>2013 OIT Land Surveyor's Workshop - Delzell (1)</p> <p>2013 OIT Land Surveyor's Workshop - Tussio (1)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1)</p> <p>Landslides & Moving Monuments – LSAW WA 2019 (1)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Eric Jason Ackerman (1609)	<p>Eric Jason Ackerman</p> <p>Gromatici Land Surveying, Inc P.O Box 650</p> <p>Los Olivos, CA 93441 805-691-9112</p> <p>E-mail: eackerman@gromatici.com</p>	<p>AZ RLS - 69068</p> <p>CA PLS - 8226</p> <p>CO PLS - 38714</p> <p>ID PLS - 18767</p> <p>NV PLS - 26941</p>	<p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Steve Ackerman (1051)	<p>Steve Ackerman</p> <p>Ackerman Survey Ltd. 8044 182 Ave SE</p> <p>Wahpeton, ND 58075</p> <p>701-899-4273</p> <p>E-mail: steve@ackermansurvey.com</p>	<p>MN RLS - 17005</p> <p>ND PLS - 2958</p> <p>SD PLS - 5226</p>	<p>2014 South Dakota SPLS Presentation - Hillstrom (2)</p> <p>2018 Minneapolis - Discrepancies (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Boundary Evidence Standards Documents (1)</p> <p>CIM Quiz (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>

			The PLSS Datum and the Local Surveyor (1) William D. Brown 137 IBLA 31 (1) Working Group - Salt Lake City, Utah 2009 (1) Working Group - San Diego 2011 (1)
Robert Neal Adams (1354)	Robert Neal Adams Omega Surveying 13646 Proctor Valley Road Jamul, CA 91935 619-669-1589 E-mail: bobelda@cox.net	CA PLS - 7638	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The PLSS Datum and the Local Surveyor (1) Working Group - San Diego 2011 (1)
Douglas Ryan Allred (1195)	Douglas Ryan Allred 1235 N 700 E P.O. Box 852 Duchesne, UT 84021 435-738-5352 E-mail: drallred@ubtanet.com	UT PLS - 376084-2201	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) Utah 2017 "Discrepancies in the Official Record" (2)
Jerry Douglas Allred (1080)	Jerry Douglas Allred 668 N 500 E P.O. Box 605 Duchesne, UT 84021 435-738-5352 E-mail: jdallred@ubtanet.com	CO RLS - 13448 UT RLS - 148951-2201	Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Keith Andersen (1068)	Keith Andersen ANDERSEN ENGINEERS, Inc. 27360 S. Flat Top Road Edgemont, SD 57735 605-662-7136 E-mail: flatop@gwtc.net	SD PLS - 2842 WY PLS - 2374	2014 South Dakota SPLS Presentation - Hillstrom (2) Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)

Kurt R Andersen (1751)	Kurt R Andersen Oregon Department of Transportation 1675 Madison St NE Salem, OR 97301 503-877-7648 E-mail: krapacker@aol.com E-mail: Kurt.R.Andersen@odot.state.or.us	OR PLS - 89970	William D. Brown 137 IBLA 31 (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) The Landslide Report (2)
Anthony Paul Anderson (1284)	Anthony Paul Anderson Anderson Surveying Inc. 6701 Hilltop Road Van Buren, AR 72956 479-474-4247 E-mail: tony@and-survey.com	AR PLS - 1272 OK PLS - 1423	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Elizabeth Anne Anderson (1810)	Elizabeth Anne Anderson State of Alaska Dept. of Natural Resources PO Box 77 Girdwood, AK 99587 907-244-8009 E-mail: bethanne_ak@yahoo.com E-mail: elizabeth.anderson@alaska.gov	AK PLS - 121416	7 States Western Virtual Conference - 3/29/21 (2) Specifications for Descriptions of Land (1) The Landslide Report (2)
Eric Walker Ansart (1794)	Eric Walker Ansart City of Aurora, CO 1572 E. Northridge Dr. Highlands Ranch, CO 80126 E-mail: eansart@auroragov.org	CO PLS - 38356	Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
John Hayes Ashley (1820)	John Hayes Ashley Maricopa County Department of Transportation 2901 W. Durango St Phoenix, AZ 85009 602-506-8647 E-mail: john.ashley@maricopa.gov	AZ RLS - 54704	
Jerron R Atkin II (1206)	Jerron R Atkin II 10818 S. Gresham Drive South Jordan, UT 84009 801-243-7859 E-mail: jerrocoop@gmail.com	ID PLS - 20142 PA PLS - SU075405 UT PLS - 5992544	2018 Western Regional Survey Conference_Workshop (2) Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1) Working Group - Salt Lake City, Utah 2009 (1)
Jeffrey W. Austin (1012)	Jeffrey W. Austin J.W. Austin Associates LLC 10865 River Pine Rd. P.O. Box 111 Minocqua, WI 54548 715-482-6506 E-mail: jeff@resurvey.org	AK PLS - 8031 AZ PLS - 34403 ID PLS - 6723 WI PLS - 1885	2018 Western Regional Survey Conference_Workshop (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1)

			<p>Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Shaun Christopher Axton (1273)	<p>Shaun Christopher Axton</p> <p>Mark Deal & Associates P.O. Box 6578 Norman, OK 73070 405-681-3325x202 E-mail: shaun@rpls.net</p>	<p>AR PLS - 1583</p> <p>CO PLS - 38173 KS PLS - 1456 MO PLS - 2009016943 OK PLS - 1494 TX PLS - 6008</p>	<p>February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
David Paul Baalman (1552)	<p>David Paul Baalman</p> <p>Rogers Surveying Inc., P.S.</p> <p>1455 Columbia Park Trail</p> <p>Suite 201 Richland, WA 99352 509-783-4141</p> <p>E-mail: dbaalman@rogerssurveying.com</p>	<p>ID PLS - 12594</p> <p>MT PLS - 19029</p> <p>OR PLS - 86848PLS</p> <p>WA PLS - 41028</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Stephen Douglas Babb (1355)	<p>Stephen Douglas Babb</p> <p>Babb Land Surveying, Inc.</p> <p>622 Alice Drive Great Falls, MT 59405-3750</p> <p>406-788-6896</p> <p>E-mail: babbsurvey@bresnan.net</p>	<p>AZ RLS - 26917</p> <p>MT RLS - 11699</p>	<p>2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Randy D Bacon (1043)	<p>Randy D Bacon</p> <p>Helms and Associates</p> <p>379306 S Shore Dr</p> <p>Aberdeen, SD 57401 605-380-2576 E-mail: baco4423@outlook.com</p>	<p>ND RLS - 3213</p> <p>SD RLS - 4423</p>	<p>2014 South Dakota SPLS Presentation - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3)</p>

			<p>NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Russell Eugene Badgley (1514)	<p>Russell Eugene Badgley BTS Surveying</p> <p>PO Box 222</p> <p>Roseburg, OR 97471 541-673-0966 E-mail: rbadgley12458@gmail.com</p>	<p>ID PLS - 12458 OR PLS - 70716</p>	<p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p>
Joshua Allen Bagley (1081)	<p>Joshua Allen Bagley h2 Surveying</p> <p>7600 N. Mineral Drive</p> <p>Suite 900</p> <p>CDA, ID 83815 208-772-6600 E-mail: jbagley@h2survey.com</p>	<p>AZ PLS - 40343 ID PLS - 12110</p> <p>MT PLS - 18985</p> <p>OR PLS - 80086LS</p> <p>WA PLS - 42105</p>	<p>2015 - LSAW Hillstrom (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Chance D Bainum (1356)	<p>Chance D Bainum</p> <p>Bainum Land Surveying</p> <p>PO Box 892</p> <p>Winchester, CA 92596 951-965-2590 E-mail: cbainum@mw2o.com</p> <p>E-mail: bainumlandsurveying@verizon.net</p>	<p>CA PLS - 8305</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Dennis Ray Baker (1534)	<p>Dennis Ray Baker</p> <p>Daley-Morrow-Poblete, Inc.</p> <p>19004 108th St Ct E Bonney Lake, WA 98391 253-208-7758 E-mail: dennisgeomatics@gmail.com</p>	<p>WA PLS - 35972</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p>

			Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Matthew Shaun Baker (1421)	Matthew Shaun Baker 366 Washington Ave. Pocatello, ID 83201 208-380-9871 E-mail: summitlandsurveying@gmail.com	ID PLS - 13023 UT PLS - 9441859-2201	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Wilbert Alan Baker (1699)	Wilbert Alan Baker High Country Engineering 1517 Blake Street Glenwood Springs, CO 81601 970-945-8676 E-mail: bbaker@hceng.com	CO PLS - 23875	2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) February 2021 RMSS Virtual Conference Workshop (2) Non-Rectangular Surveys (9) Special Boundary Problems I (3)
Edwin Michael Balliet (1422)	Edwin Michael Balliet Pathway Land Surveys, LLC 2321 E. Winston Dr. Phoenix, AZ 85042 E-mail: edb@pathway-ls.com E-mail: edwin234@me.com	AZ RLS - 31587	Advanced Topics and Cases in Mineral Surveys (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
Kenneth Banks (1553)	Kenneth Banks Dept. of Fish and Wildlife 370 collins toledo, WA 98591 360-520-2446 E-mail: knnthbank@msn.com E-mail: kenneth.banks@dfw.wa.gov	WA PLS - 40518	2015 - LSAW Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Danilo Marquez Baquing (1774)	Danilo Marquez Baquing CalTrans District 12 Surveys P.O. Box 3060 Tustin, CA 92781 E-mail: Danilo.Baquing@outlook.com E-mail: Danilo.Baquing@dot.ca.gov	CA PLS - 8576	Discrepancies in the Official Record (2) Resurveying an Entire GLO Township (2) The 2009 Manual of Surveying Instructions (2)
Ron Barbala (1082)	Ron Barbala Geomatics Consulting Group 1745 W. Deer Valley Rd. Suite 118 Phoenix, AZ 85027 623-580-0921 E-mail: rbarbala@geomaticsconsultinggroup.com	AZ RLS - 33307 CA PLS - 7988 NM PLS - 21525 NV PLS - 17024	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)

			Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Gilbert Marshall Barish (1515)	Gilbert Marshall Barish Geodetic Designs Incorporated 2300 North Grand River Avenue Lansing, MI 48906 517-908-0008 E-mail: gil.barish@geodeticdesigns.com	LA PLS - 5006 MI PLS - 4001047942 OH PLS - 8203 WI PLS - S-2821	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Stephan L. (Pat) Barott (1083)	Stephan L. (Pat) Barott Stephan Barott Land Surveying 1446 St. Andrew Way Medford, OR 97504 541-776-1272 E-mail: sbarott@charter.net E-mail: sbls2332@gmail.com	ID PLS - 14293 OR PLS - 2332 OR Other - CWRE294	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Oregon: PLSO Annual Conference – Jan 21-23, 2015 (1) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jacob Benoni Barowsky (1646)	Jacob Benoni Barowsky 241 Camino De San Francisco Placitas, NM 87043 E-mail: barowsky@gmail.com E-mail: jbarowsky@blm.gov	AK PLS - 112377 AZ RLS - 52575 TN PLS - 2958 TX RLS - 6688	2018 Denver, CO: Resurveying an Entire GLO Township (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Richard Francis Barton (1140)	Richard Francis Barton 7622 East Windlawn Way Parker, CO 80134 303-841-4869	CO PLS - 9872 NE PLS - 688 SD PLS - 10152	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1)

	E-mail: pls9872@gmail.com		Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Sidney Glenn Bechtolt (1357)	Sidney Glenn Bechtolt Agate Land Surveying PLLC PO Box 246 Shelton, WA 98584 360-426-4172 E-mail: sid@agateland.com	WA PLS - 28237	2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2018 Western Regional Survey Conference Workshop (2) 2019 LSAW: PLSS Calculations & Case Studies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Patrick Joseph Beehler (1705)	Patrick Joseph Beehler WA DNR 904 Cardigan St NW Olympia, WA 98502 360-515-6143 E-mail: pjbeehler@comcast.net E-mail: patbeehler@dnr.wa.gov	WA PLS - 17656	2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Conference (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jeffrey S. Bell (1763)	Jeffrey S. Bell IMEG PO Box 10603 Kalispell, MT 59904 406-314-1550 E-mail: jeffbellsurv@yahoo.com E-mail: jeffrey.s.bell@imegcorp.com	MT PLS - 15853	Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)
Shane Anthony Bender (1769)	Shane Anthony Bender 33756 Mckenny Place Yucaipa, CA 92399 909-702-9326 E-mail: sb.surveying@hotmail.com	CA PLS - 9197 ND RLS - 28716	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3)
Brian J. Benedict (1775)	Brian J. Benedict 4707 E. Lewis Avenue Phoenix, AZ 85008 E-mail: bbenedict001@gmail.com	AZ RLS - 32222	Hillstrom 180 IBLA 388 (2) Resurveying an Entire GLO Township (2) The 2009 Manual of Surveying Instructions (2)
Alan Robert Benham (1013)	Alan Robert Benham Bohannon Huston, Inc. 7500 Jefferson St. NE Albuquerque, NM 87109	AZ PLS - 47283 CA PLS - 8700 CO PLS - 37976 NM PE - 14940	7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1)

	505-798-7899 E-mail: abenham@bhinc.com	NM PLS - 15700 NV PLS - 19554 TX RLS - 5814 WY PLS - 13418	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Obert DeWayne Bennett (1045)	Obert DeWayne Bennett Bennett - Morris & Associates P.O. Box 131 Madill, OK 73446 580-564-4458 E-mail: bennett1471@att.net	OK PLS - 1471	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Samantha R Bianco (1597)	Samantha R Bianco 15812 66th St E Sumner, WA 98390 503-969-0101 E-mail: samanthabianco@comcast.net	OR PLS - 61303LS UT PLS - 9089579-2201 WA PLS - 44334	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Standards for Boundary Evidence (3)
C Scott Bishop (1706)	C Scott Bishop 1342 N 450 W Pleasant Grove, UT 84062 801-369-3221 E-mail: sbishop@horrocks.com	AZ RLS - 53078 CO PLS - 0038690 NM PLS - 25341 NV PLS - 21166 UT PLS - 6077910	2018 Western Regional Survey Conference_Workshop (2) 2021 RMSS Conference (2) 7 States Western Conference (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Resurveying an Entire GLO Township (2) The Landslide Report (2) UCLS_St. George, UT 2/20/2020 Workshop (2) Utah 2017 "Discrepancies in the Official Record" (2)
Dusty Lane Bishop (1712)	Dusty Lane Bishop Ensign Engineering 283 South 1200 East Payson, UT 84651 801-509-2232 E-mail: dbishop@ensignutah.com E-mail: dbishopsurveyor@gmail.com	UT PLS - 4938720	2018 Western Regional Survey Conference_Workshop (2) Advanced Topics and Cases in Mineral Surveys (2) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)
George Bisset (1317)	George Bisset P.O. Box 2112 Petersburg, AK 99833 907-772-9350	AK PLS - 10391	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2)

	<p>E-mail: gbisset@gci.net</p> <p>E-mail: george.bisset@usda.gov</p>		<p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
John Malcolm Blaikie (1204)	<p>John Malcolm Blaikie S&F Land Services</p> <p>2808 NE 144th Street 400 E. Evergreen Blvd, Suite 1</p> <p>vancouver, WA 98686 360-910-8644 E-mail: john.blaikie@sflands.com E-mail: jblaikie@comcast.net</p>	<p>OR PLS - 81640 WA PLS - 42667</p>	<p>2021 RMSS Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Alternate Credit (3)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Scott Landon Blake (1573)	<p>Scott Landon Blake BKF Engineers</p> <p>3938 Kimball Lane</p> <p>Stockton, CA 95206 209-676-1538 E-mail: lblake@bkf.com E-mail: sunburned.surveyor@gmail.com</p>	<p>CA PLS - 8489 NV PLS - 20909</p>	<p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Brendan Blansett (1753)	<p>Brendan Blansett</p> <p>ODOT</p> <p>P.O. Box 235</p> <p>Antlers, OK 74523 580-298-7535 E-mail: bblansett@odot.org E-mail: bblansett_pls@yahoo.com</p>	<p>OK PLS - 1561</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Specifications for Descriptions of Land (1)</p>
Benjamin Michael Blazek (1754)	<p>Benjamin Michael Blazek 1638 Alta Vista Drive</p> <p>Vista, CA 92084 760-419-2396 E-mail: CAPLS9460@gmail.com</p>	<p>CA PLS - 9460</p>	<p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Jason Boehler (1720)	<p>Jason Boehler 6825 E. Topke St. Tucson, AZ 85715</p> <p>E-mail: jasonboehler5@gmail.com</p>	<p>AZ RLS - 57511 CO PLS - 38776</p>	<p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p>

			The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Dan Boers (1084)	Dan Boers Boers Land Surveying and Mapping, Inc. PO Box 441 Manhattan, MT 59741 406-600-3790 E-mail: boerslandsurveying@outlook.com	ID PLS - 13395 MT PLS - 14732 ND PLS - 5988 SD RLS - 9818 UT PLS - 11483045-2201 WA PLS - 57442 WY PLS - 11751	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Toby Gerard Bolden (1621)	Toby Gerard Bolden 22656 SW Kathy Street Sherwood, OR 97140 503-330-8773 E-mail: tobybolden@gmail.com E-mail: tobyb@centerlineconcepts.com	OR PLS - 60377	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Scott Christopher Bolduc (1465)	Scott Christopher Bolduc Parametrix 150 NW Pacific Park Lane, Suite 110 Bend, OR 97701 541-408-4252 E-mail: SBolduc@parametrix.com E-mail: sbolduc22@gmail.com	ID PLS - 12219 OR PLS - 79288	February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1)
Kevin Bolter (1535)	Kevin Bolter Hetch Hetchy Water and Power 11820 Campo Seco Road Sonora, CA 95370 209-559-5329 E-mail: kbolter@gmail.com E-mail: kbolter@sflower.org	CA PLS - 8511	Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)
Kevin James Bow (1713)	Kevin James Bow DNR Alaska 6621 Lunar Dr. Anchorage, AK 99504 907-350-0970 E-mail: kevin.bow@alaska.gov E-mail: kbow43@yahoo.com	AK PLS - 13011	2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1)

Angela Boyea (1776)	Angela Boyea Towill Inc 8799 Balboa Ave, Suite 140 San Diego, CA 92123 858-384-0088x1601 E-mail: angela.boyea@towill.com E-mail: anablego@hotmail.com	CA PLS - 8143	The Landslide Report (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Relictions in the Public Land Survey System (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
Daniel W. Boyett (1777)	Daniel W. Boyett B&F Engineering, Inc. 928 Airport Road Hot Springs, AR 71913 501-767-2366 E-mail: dannyb@bnfeng.com	AR PLS - 1758 NM PLS - 25533	Introduction to the Geographic Coordinate Database (3) Special Boundary Problems I (3)
William Travis Bradley (1795)	William Travis Bradley Axis Survey and Mapping 15241 NE 90th Street Redmond, WA 98052 206-419-2999 E-mail: travis@axismap.com E-mail: wtravisbradley@gmail.com	WA PLS - 48372	Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Monumentation and the Corner Record (3) Swamp Land Grants, Omitted Area and Island Surveys (1)
Ronald Brand (1007)	Ronald Brand Brand Land Surveying LLC 533 Greenfield Lane Gaylord, MI 49735 989-732-8077 E-mail: rcbrand@gmail.com E-mail: ronbrand@brandlandsurveying.com	MI PLS - 43046	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Peter K. Brands (1052)	Peter K. Brands Pacific Surveying and Engineering 909 Squalicum Way Suite 111 Bellingham, WA 98225 360-671-7387 E-mail: pbrands@psurvey.com	WA PLS - 35147	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Boundary Evidence Standards Documents (1) Discrepancies in the Official Record (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Beth A. Braun (1237)	Beth A. Braun	AL PLS - 29724	Accretions in the Public Land Survey System (1)

	<p>The Mannik & Smith Group</p> <p>2365 Haggerty Road South Canton, MI 48188 412-439-5488</p> <p>E-mail: bbraun@manniksmithgroup.com</p>	<p>AZ PLS - 50148</p> <p>FL PLS - 6696 GA PLS - 3234 IA PLS - 22971</p> <p>IL PLS - 35.003851 IN PLS - LS21800025 KY PLS - 4058</p> <p>LA PLS - 4975 MI PLS - 52461 MN PLS - 50035</p> <p>MO PLS - PLS-2019042215 MS PLS - 25123 NC PLS - L-5225 ND PLS - LS-9103 NE PLS - 706</p> <p>NM PLS - 22095</p> <p>NY PLS - 50730</p> <p>OH PLS - 8444 OK PLS - 1711 PA PLS - 75301 TX PLS - 6187 WI PLS - 3022 WY PLS - 11193</p>	<p>Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Peter James Brennan, Jr (1467)	<p>Peter James Brennan, Jr</p> <p>341 R L Honeycutt Dr</p> <p>Wilmington, NC 28412 910-619-1096</p> <p>E-mail: brennanlandsurveyors@gmail.com</p>	<p>ID PLS - L-16267</p> <p>NC PLS - L-3743</p> <p>NY PLS - 050679 SD PLS - 12343</p> <p>UT PLS - 9233303-2201</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Samuel David Brescia (1359)	<p>Samuel David Brescia</p> <p>Southern Ute Indian Tribe 4907 Pinecroft Dr Farmington, NM 87402 505-716-1038 E-mail: brescia2530@earthlink.net</p>	<p>AZ RLS - 42466</p> <p>CO PLS - 37635</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) 2020_Colorado RMSS Workshop (2) 2020_Colorado RMSS Workshop (TEST) (0) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
WILLIAM FLEMING BREWSTER (1184)	<p>WILLIAM FLEMING BREWSTER Souder Miller</p> <p>5454 Venice Ave. NE</p> <p>Suite D</p> <p>ALBUQUERQUE, NM 87113 505-299-0942 E-mail: wfbrewster@gmail.com E-mail: BILL.BREWSTER@SOUDERMILLER.COM</p>	<p>AZ RLS - 30345 CA PLS - L 6722</p> <p>ID PLS - 8746</p> <p>KS PLS - 1628</p> <p>MO PLS - 2005019231 NM PLS - 10855 NV PLS - 9445 TX RLS - 5058</p> <p>UT PLS - 190107-2201</p>	<p>2015 New Mexico Conference - Hillstrom (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)</p>

			<p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Gordon T Brinker (1070)	<p>Gordon T Brinker</p> <p>521 West Lake View Avenue</p> <p>Wasilla, AK 99654</p> <p>907-373-2844</p> <p>E-mail: g.brinker@lwsurvey.com</p> <p>E-mail: gordon.brinker@yahoo.com</p>	AK PLS - 10351	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Randal H. Brinker (1150)	<p>Randal H. Brinker</p> <p>R&M Consultants, Inc</p> <p>3301 W. 79th Avenue</p> <p>Anchorage, AK 99502</p> <p>907-243-7304</p> <p>E-mail: rhan.brinker@gmail.com</p> <p>E-mail: hbrinker@rmconsult.com</p>	AK PLS - 8852	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Henry Page Broadhurst, Jr (1469)	<p>Henry Page Broadhurst, Jr</p> <p>P.O. Box 1434</p> <p>490 Grand County Road 101</p> <p>Kremmling, CO 80459-1434</p> <p>970-724-0851</p> <p>E-mail: alpsurv@gmail.com</p>	<p>CO PLS - 18974</p> <p>NM RLS - 11393</p> <p>UT PLS - 183694-2201</p>	<p>2018 Denver, CO: Resurveying an Entire GLO Township (2)</p> <p>2019 Rocky Mountain Surveyors Summit (2)</p> <p>2020_Colorado RMSS Workshop (2)</p> <p>2020_Colorado RMSS Workshop (TEST) (0)</p> <p>February 2021 RMSS Virtual Conference Workshop (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p>
Jeffrey F. Brooke (1286)	<p>Jeffrey F. Brooke</p> <p>Wood Rodgers Engineering</p> <p>po box 5051</p> <p>Reno, NV 89513</p> <p>775-622-5436</p> <p>E-mail: jfbrooke12@yahoo.com</p>	<p>CA RLS - 6480</p> <p>NV PLS - 8658</p> <p>NV Other - WRS 1004</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p>

			<p>Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p>
Craig L. Brown (1086)	<p>Craig L. Brown CB & Associates, Inc.</p> <p>PO Box 10355</p> <p>Bozeman, MT 59719 406-539-3436</p> <p>E-mail: craig@cblandsurveyors.com</p>	<p>ID PLS - 13026 MT PLS - 11371LS</p> <p>SD PLS - 9418</p> <p>UT PLS - 6783013-2201</p>	<p>2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Michael Blake Brown (1264)	<p>Michael Blake Brown Topographic Land Surveyors 1400 Everman Parkway</p> <p>Suite 146 Fort Worth, TX, TX 76140</p> <p>817-744-7512 E-mail: mike.brown@topographic.com</p> <p>E-mail: notsoeadly@yahoo.com</p>	<p>AZ RLS - 50150 CO PLS - 38201 IA PLS - P26697</p> <p>KS Other - 1552 LA PLS - 5083</p> <p>ND Other - LS-7382 NE Other - 828</p> <p>NM Other - 18329 NV PLS - 20610</p> <p>OH Other - 8720 OK PLS - 2018 TX Other - 5857</p> <p>UT PLS - 7434320-2201 WY PLS - 13652</p>	<p>2021 RMSS Conference (2) 7 States Western Conference (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1)</p>
Raymond Frank Brown (1361)	<p>Raymond Frank Brown</p> <p>P.O. Box 539</p> <p>305 S. Main</p> <p>Canyonville, OR 97417</p> <p>541-680-8950 E-mail: survey97417@gmail.com</p>	<p>OR PLS - 2391</p> <p>OR Other - CWRE 234</p>	<p>2013 OIT Land Surveyor's Workshop - Delzell (1) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Stanley C Brown (1287)	Stanley C Brown	AK RLS - 7619	<p>2019 Alaska Society of Professional Land Surveyors (2)</p>

	<p>Dept Natural Resources, State of Alaska</p> <p>3022 Madison Way</p> <p>Anchorage, AK 99508</p> <p>907-269-8521 E-mail: leebrown@gci.net</p>		<p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Matthew Gregory Buchanan (1778)	<p>Matthew Gregory Buchanan</p> <p>2251 N Springfield St Buckeye, AZ 85396 623-910-7456 E-mail: Mbuchananrfs@gmail.com</p>	AZ RLS - 59228	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Douglas G. Buck (1574)	<p>Douglas G. Buck</p> <p>PO Box 3080</p> <p>Sonora, CA 95370 209-532-7345 E-mail: 00Buck@comcast.net</p>	CA PLS - 5407	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Brianna J. Buettner (1002)	<p>Brianna J. Buettner Yakama Nation PO Box 151</p> <p>Toppenish, WA 98948</p> <p>509-865-5121x6730 E-mail: Brianna_Buettner@yakama.COM E-mail: pls.yakama@gmail.com</p>	<p>OR PLS - 81170 WA PLS - 41955</p>	<p>2014 LSAW Conference Delzell (1)</p> <p>2014 LSAW Conference Tussio (1)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Larry W. Busby (1164)	<p>Larry W. Busby</p> <p>Delta Land Surveying</p> <p>14900 Avery Ranch Blvd. Suite C200 #241</p>	<p>CO PLS - 29410 NM PLS - 11398 OK PLS - 1680 TX RLS - 4967</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p>

	<p>Austin, TX 78717 512-781-9800</p> <p>E-mail: Larry@DeltaLandSurveying.net</p>		<p>Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
John R. Butcher (1319)	<p>John R. Butcher</p> <p>City of San Diego</p> <p>352 TRAVELODGE DRIVE EL CAJON, CA 92020</p> <p>619-663-2715 E-mail: jbutcher@sandiego.gov</p> <p>E-mail: hpsurveyor@cox.net</p>	<p>AZ RLS - 43005</p> <p>CA PLS - 8240</p> <p>NV PLS - 17363</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) The PLSS Datum and the Local Surveyor (1) Tussio 37 IBLA 135 (1) Working Group - San Diego 2011 (1)</p>
Bryan Campbell (1154)	<p>Bryan Campbell</p> <p>10813 W Hope Dr</p> <p>Sun City, AZ 85351</p> <p>602-757-5439 E-mail: bryanc911@yahoo.com</p>	<p>AZ RLS - 40622</p> <p>CA PLS - L 8687</p> <p>ID PLS - 9321</p> <p>MT PLS - 15281LS NV PLS - 18748 OR PLS - 61349LS TX PLS - 6255</p> <p>WA PLS - 34135</p>	<p>2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Arlee John Carlson (1470)	<p>Arlee John Carlson</p> <p>Sunde land Surveying, LLC</p> <p>9001 E. Bloomington Frwy. Suite 118 Bloomington, MN 55420</p> <p>952-886-3118</p> <p>E-mail: arlee@sunde.com</p>	<p>MN PLS - 44900</p> <p>ND PLS - LS-6373</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p>

			The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Guy Thomas Carlson (1575)	Guy Thomas Carlson Itasca County 20236 Crystal Springs Loop Grand Rapids, MN 55744 218-327-0380 E-mail: guy.carlson@co.itasca.mn.us	MN PLS - 40991	2014 MSPS Winter Seminar - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) DeIzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Nathan Hale Carlson (1165)	Nathan Hale Carlson Westwood 3701 12th St. N. Suite 206 St. Cloud, MN 56303 320-253-9495 E-mail: nate.carlson@westwoodps.com	FL PLS - LS6938 GA PLS - LS003326 IA PLS - 19314 ME PLS - 2431 MN PLS - 45873 NM PLS - 18330 OH PLS - 8418 UT PLS - 8227107-2201	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) DeIzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Troy Andrew Carlson (1816)	Troy Andrew Carlson Storhaug Engineering 510 East Third Avenue Spokane, WA 99202 509-954-6592 E-mail: troy@storhaug.com E-mail: tazcet@hotmail.com	ID PLS - 15434 WA PLS - 48373	
Marc J Carstens (1320)	Marc J Carstens Carstens Surveying W.D.C. Inc. Po Box 1374 Polson, MT 59860 406-883-2672 E-mail: n8182x@hotmail.com	MT PLS - 5940 ND PLS - 7693	Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) DeIzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Lyle J. Casciato (1362)	Lyle J. Casciato Engineering Associates PO Box 1900 902 13th Street Cody, WY 82414 307-587-4911 E-mail: casciato@eaengineers.com	CO PLS - 38509 ID PLS - 14746 MT PLS - 20002 ND PLS - 9397 WY PLS - 12600	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1)

			<p>Nov2015_Discrepancies in the Official Record (2)</p> <p>Special Boundary Problems I (3)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The PLSS Datum and the Local Surveyor (1)</p> <p>Working Group - San Diego 2011 (1)</p>
Kathleen Cassou (1584)	<p>Kathleen Cassou</p> <p>2306 Vista Avenue SE</p> <p>Olympia, WA 98501</p> <p>360-280-7426</p> <p>E-mail: ktcassou@gmail.com</p> <p>E-mail: kcassou@parametrix.com</p>	<p>OR PLS - 72342</p> <p>WA PLS - 27133</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Douglas J. Caster (1517)	<p>Douglas J. Caster</p> <p>American Bridge Company</p> <p>35924 W. 287TH Street</p> <p>Paola, KS 66071</p> <p>913-957-0072</p> <p>E-mail: Dcaster@americanbridge.net</p>	<p>KS PLS - 1505</p> <p>MO PLS - 2008016656</p> <p>WA PLS - 20100526</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Rebecca J Cate (1265)	<p>Rebecca J Cate</p> <p>Forest Service 1</p> <p>215 Melody Ln</p> <p>Wenatchee, WA 98801</p> <p>509-664-9264</p> <p>E-mail: rebecca.cate@usda.gov</p>	<p>WA PLS - 42669</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
J. Anthony Cavell (1037)	<p>J. Anthony Cavell</p> <p>J. Anthony Cavell</p> <p>11646 Rue Concord</p> <p>Baton Rouge, LA 70810</p> <p>225-802-5677</p> <p>E-mail: JAC@GPSman.Com</p>	<p>LA PLS - 4620</p>	<p>2016 Discrepancies in the Official Record (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p>

			<p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Byron Javier Cazar Balarezo (1762)	<p>Byron Javier Cazar Balarezo</p> <p>4080 Pedley Rd. Spc 199 Riverside, CA 92509 909-973-3417 E-mail: bcazar@markthomas.com</p> <p>E-mail: byroncazar@msn.com</p>	CA PLS - 9337	<p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Michael H. Celt (1622)	<p>Michael H. Celt Parametrix 7761 W. Riverside Drive, Ste 201 Boise, ID 83714</p> <p>208-898-0012 E-mail: mcelt@parametrix.com</p>	<p>ID PLS - L-14216</p> <p>OR PLS - 84595PLS</p> <p>UT PLS - 7734556-2201</p>	<p>2015-Idaho Hillstrom presentation (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Andrew Scott Chafer (1208)	<p>Andrew Scott Chafer</p> <p>7528 Phinney Pl San Jose, CA 95139</p> <p>408-728-1537 E-mail: chaferandrew@gmail.com</p>	<p>CA PLS - 8005</p> <p>NV PLS - 23918</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Boundary Evidence Standards Documents (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Discrepancies in the Official Record (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Brent Edward Christensen (1647)	<p>Brent Edward Christensen</p> <p>UniversalPegasus International 2442 West 180 South Provo, UT 84601 801-214-4297 E-mail: fayebrent@gmail.com</p> <p>E-mail: steephillside95@gmail.com</p>	<p>AZ RLS - 64348</p> <p>CO PLS - 0038506</p> <p>ID PLS - 17017</p> <p>MT PLS - 49402</p> <p>NV PLS - 023389</p> <p>OK PLS - 1935</p> <p>UT PLS - 4854808-2201</p> <p>WY PLS - 15338</p>	<p>2018 Western Regional Survey Conference_Workshop (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>UCLS_St. George, UT 2/20/2020 Workshop (2)</p> <p>Utah 2017 "Discrepancies in the Official Record" (2)</p>
John M. Cicon (1409)	<p>John M. Cicon</p> <p>Cicon and Associates LLP</p> <p>1051 Laird Road P.O. Box 541</p>	MT PLS - 4039PLS	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p>

	<p>Chester, MT 59522 406-292-3531</p> <p>E-mail: john.cicon@mtintouch.net E-mail: jcicon@mtintouch.net</p>		<p>Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Rudy S. Cicon (1410)	<p>Rudy S. Cicon Cicon and Associates LLP</p> <p>30 First Street East P.O. Box 541</p> <p>Chester, MT 59522</p> <p>406-759-5826 E-mail: cicon@itstriangle.com</p>	MT PLS - 9963LS	<p>2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
W. Russell Clark (1471)	<p>W. Russell Clark</p> <p>Clark Land Surveying, Inc. 177 S. Tiffany Drive Suite 100 Pueblo West, CO 81007</p> <p>719-633-8533</p> <p>E-mail: russ@clarkls.com</p>	<p>AK PLS - 8853</p> <p>CO PLS - 31548</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) 2020_Colorado RMSS Workshop (TEST) (0) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2021 RMSS Virtual Conference Workshop (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)</p>
Travis Elliott Clement (1827)	<p>Travis Elliott Clement Strand 884 Homestead Dr Highlands Ranch, CO 80126 409-656-3754 E-mail: travisclement81@gmail.com</p>	<p>CO PLS - 38496 ND RLS - LS-10960 TX Other - 6638</p>	
Howard Nelson Cline (1251)	<p>Howard Nelson Cline</p> <p>North Star Surveying, Inc.</p> <p>P.O. Box 668 Gunnison, CO 81230 970-641-4543</p> <p>E-mail: northstr@rmi.net</p>	<p>CO PLS - 23037</p> <p>MT PLS - 17279</p> <p>UT PLS - 163780-2201</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2)</p>

			<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Eric Gordon Coffey (1291)	<p>Eric Gordon Coffey</p> <p>8552. W Paradise Dr.</p> <p>Peoria, AZ 85345</p> <p>E-mail: ericof@msn.com</p>	<p>AZ RLS - 42186</p> <p>NV PLS - 23919</p>	<p>2019 APLS Private-Federal Boundary Determination (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Boundary Evidence Standards Documents (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Discrepancies in the Official Record (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Jeffrey D. Conaway (1637)	<p>Jeffrey D. Conaway</p> <p>Encompass Energy Services</p> <p>128 Front Street</p> <p>Lititz, PA 17543</p> <p>218-390-2706</p> <p>E-mail: j.conaway@encompassservices.com</p>	<p>ME PLS - PLS2448</p> <p>MN PLS - 44879</p> <p>WI PLS - 3020-8</p> <p>WV PLS - 2300</p>	<p>Discrepancies in the Official Record (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>The Landslide Report (2)</p>
Daren L. Cone (1779)	<p>Daren L. Cone</p> <p>Oregon Department of Forestry</p> <p>4751 Astoria St. NE</p> <p>Salem, OR 97305</p> <p>541-973-4970</p> <p>E-mail: daren.l.cone@oregon.gov</p> <p>E-mail: 314stengr@gmail.com</p>	<p>OR PLS - 43362PLS</p> <p>OR PE - 43362PE</p>	<p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p>
Chad Michael Conner (1292)	<p>Chad Michael Conner</p> <p>Widseth Smith Nolting</p> <p>7804 industrial park road</p> <p>Baxter, MN 56425</p> <p>218-316-3632</p> <p>E-mail: chad.conner@widseth.com</p>	<p>IL PLS - 3887</p> <p>MN PLS - 41643</p> <p>WI PLS - 3180</p>	<p>2014 MSPS Winter Seminar - Hillstrom (2)</p> <p>2018 Minneapolis - Discrepancies (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
RYAN GARETT COOK (1269)	<p>RYAN GARETT COOK</p> <p>SUMMIT ENGINEERING CORPORATION</p> <p>5405 MAE ANNE AVENUE</p> <p>RENO, NV 89523</p> <p>775-747-8550</p> <p>E-mail: ryan@summitnv.com</p>	<p>CA PLS - 7924</p> <p>ID PLS - 14519</p> <p>MT PLS - 18936</p> <p>ND PLS - 8347</p> <p>NV PLS - 15224</p> <p>NV Other - WRS 1112</p>	<p>2019 CLSA/NALS Private-Federal Boundary (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p>

	E-mail: verdicook@gmail.com	SD PLS - 11146 UT PLS - 7580460-2201	Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Robert Coombs (1151)	Robert Coombs PO Box 10357 Reno, NV 89510 530-913-7241 E-mail: rhc.1313@yahoo.com	CA PE - 27787 MT Other - 11125 ES	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
Mark F. Corbridge (1586)	Mark F. Corbridge Wyoming Department of Transportation 3813 Klipstein Road Cheyenne, WY 82009 307-760-3502 E-mail: mark.corbridge@wyo.gov E-mail: markcorb57@gmail.com	CO PLS - 25619 WY PLS - 12061	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The Landslide Report (2)
Peter D. Cote (1745)	Peter D. Cote 203 n. Slate Dr. Vail, AZ 85641 520-275-3007 E-mail: rojopedro@msn.com E-mail: pcote@wbgroupp.com	AZ RLS - 44121	Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Special Boundary Problems I (3)
George E.R. Coulombe (1186)	George E.R. Coulombe Coulombe Consulting 3701 Elliot Rd NE Bemidji, MN 56601 218-444-9791 E-mail: cconsult@paulbunyan.net	MN RLS - 15810 ND RLS - LS6262 WY RLS - LS12288	2015 North Dakota: NDSPLS Annual Convention (2) Boundary Evidence Standards Documents (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jim D Crume (1293)	Jim D Crume 2116 N Normal Ave Tempe, AZ 85281 480-845-9035	AZ PLS - 19817	7 States Western Conference (2) Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2)

	E-mail: jcrume@cc4w.net		Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Mineral Surveys (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Douglas P Cruse III (1190)	Douglas P Cruse III AEI Consultants 98 Greenwood Park Way Dawsonville, GA 30534 770-851-7713 E-mail: dtcruse@windstream.net	AL PLS - 21773 AR PLS - 1867 FL PLS - 6818 GA RLS - 2937 KY PLS - 4270 MS PLS - 2837 NC PLS - 4385 SC PLS - 25746 TN RLS - 2181 VA PLS - 3002	Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
John Robert Dahl (1537)	John Robert Dahl 1114 Wisconsin Ave. S. Golden Valley, MN 55426 320-260-0120 E-mail: 1johndahl@gmail.com	CA PLS - 6601 CA PE - 44691 MN PLS - 21824 MN PE - 21824	Dezell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)
Brian Dalager (1322)	Brian Dalager MCDOT 2901 W. Durango Street Phoenix, AZ 85009 602-506-4685 E-mail: briandalager@mail.maricopa.gov	AZ RLS - 33310 NM RLS - 16004	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) Accretions in the Public Land Survey System (1) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3)
Paul Jonathon Darrow (1832)	Paul Jonathon Darrow Wilson Engineering, LLC 805 Dupont St. Suite 7 Bellingham, WA 98225 360-733-6100 E-mail: pdarrow@wilsonengineering.com	WA PLS - 50697	
Leslie E. Davis (1519)	Leslie E. Davis Valley Surveying, LLC 139 Ault Rd Adona, AR 72001 501-328-3316 E-mail: valleysurveying@yahoo.com	AR PLS - 1523 KS PLS - 1607 OK PLS - 1955 WV PLS - 2331 WY PLS - 14763	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The Landslide Report (2)
Bryan de Jesus (1210)	Bryan de Jesus CACI 5511 Mill Race Cir Pace, FL 32571 970-218-4587 E-mail: bryan.dejesus@caci.com	FL PLS - 6668	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Dezell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)

			<p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Steven Craig DeJong (1363)	<p>Steven Craig DeJong</p> <p>Meridian Surveying LLC</p> <p>N4019 VandenBosch Rd Freedom, WI 54130 920-427-6073</p> <p>E-mail: sdejong@meridian-wi.com</p>	WI PLS - 2791	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Samuel Joseph DeLeo (1425)	<p>Samuel Joseph DeLeo</p> <p>KLD, Inc.</p> <p>13 North 11th Avenue</p> <p>St. Cloud, MN 56303 320-259-1266</p> <p>E-mail: deleo@kldland.com</p>	MN PLS - 40341	<p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Warren L. Delles (1623)	<p>Warren L. Delles</p> <p>Mille Lacs County</p> <p>635 2nd St SE Milaca, MN 56353 320-983-8459</p> <p>E-mail: warren.delles@millelacs.mn.gov</p>	<p>MN PLS - 41890</p> <p>NE RLS - 668</p>	<p>2021 RMSS Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
William Glenn Dempsey (1211)	<p>William Glenn Dempsey</p> <p>FS2</p> <p>1490 Cloud Peak Dr. Sparks, NV 89436 775-354-0273</p> <p>E-mail: wgdempsey50@gmail.com</p>	<p>CA PLS - 8349</p> <p>FL PLS - 3693</p> <p>NV PLS - 17187</p> <p>NY PLS - 50284</p> <p>UT PLS - 5647193-2201</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p>

			The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
EDMUND DENNY, JR (1192)	EDMUND DENNY, JR 2200 E. EVERGREEN BLVD VANCOUVER, WA 98661 360-694-3313 E-mail: ed@mgsurvey.com	AZ PLS - 49193 OR PLS - 2662 WA PLS - 32451	2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)
Timothy Jon DeVries (1648)	Timothy Jon DeVries GradyMinor Engineering 6881 Mill Run Cir Naples, FL 34109 239-425-5481 E-mail: devrie23@hotmail.com E-mail: devrie23@gmail.com	FL PLS - 6758	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
David Stanley Dickey (1294)	David Stanley Dickey Salt River Project 116 Saltmine Road Camp Verde, AZ 86322 602-540-4646 E-mail: stan.dickeyjr@srpnet.com	AZ RLS - 32224 NM PLS - 19300	7 States Western Conference (2) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Dorrel Dearing Dickson (1364)	Dorrel Dearing Dickson 20005 74th Ave NE Arlington, WA 98223 E-mail: dodedickson@hotmail.com	WA PLS - 43608	2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments - LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)

			Swamp Land Grants, Omitted Area and Island Surveys (1) Tussio 37 IBLA 135 (1)
Jeffrey John Donahue (1614)	Jeffrey John Donahue WSDOT 7345 Linderson Way SW Tumwater, WA 98501-6504 206-779-5065 E-mail: donahuj@wsdot.wa.gov	WA PLS - 41279	2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) Hasenyager 176 IBLA 252 (1) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Stephen K. Drake (1212)	Stephen K. Drake Lost Coast Land Surveying P.O. Box #5413 Eureka, CA 95502 928-377-0171 E-mail: stephendrake@gmail.com E-mail: lostcoastlandsurveying@gmail.com	AZ PLS - 46472 CA PLS - 9244 MT PLS - 23627	2019 CLS/NALS Private-Federal Boundary (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Boundary Evidence Standards Documents (1) Discrepancies in the Official Record (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Robert Drum (1366)	Robert Drum Colorado Department of Transportation 39 Ute Pass West Rd Durango, CO 81301 970-903-3828 E-mail: robert.drum@state.co.us	CO PLS - 38040	2016 Discrepancies in the Official Record (2) 2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Brady D. Duff (1181)	Brady D. Duff Forest Service 519 Duff Road Lamar, AR 72846 479-214-4450 E-mail: brady.duff@usda.gov E-mail: bdduff1@hotmail.com	AR PLS - 1376	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9)

			<p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
John M. Duffey (1538)	<p>John M. Duffey</p> <p>Duffey Land Surveying</p> <p>43330 Canal Road Ronan, MT 59864 406-676-8835</p> <p>E-mail: duffey@ronan.net E-mail: duffeysurvey@gmail.com</p>	<p>MT PLS - 15624</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Mark W. Duffner (1474)	<p>Mark W. Duffner</p> <p>Barghausen Consulting Engineers, Inc.</p> <p>18215 72nd Avenue South Kent, WA 98032</p> <p>425-656-7458 E-mail: mduffner@barghausen.com</p>	<p>CA PLS - 7062</p> <p>ID PLS - 9905</p> <p>MT RLS - 20489 WA PLS - 38970</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>The Landslide Report (2)</p>
Jeffery Patrick Dugan (1559)	<p>Jeffery Patrick Dugan</p> <p>605 1/2 Capitol Wy S #2</p> <p>Olympia, WA 98501</p> <p>360-870-8225</p> <p>E-mail: jefferydugan@pacbell.net E-mail: jeff.dugan@dnr.wa.gov</p>	<p>WA PLS - 46881</p>	<p>2013 OIT Land Surveyor's Workshop - Delzell (1)</p> <p>2013 OIT Land Surveyor's Workshop - Tussio (1)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
John L. Dunn (1296)	<p>John L. Dunn</p> <p>Rim Rock Consulting, Inc. 129 West 3rd Street #102</p> <p>Moscow, ID 83843 208-883-5339</p> <p>E-mail: rimrock@rimrockconsulting.net</p>	<p>ID PLS - 10162</p> <p>WA PLS - 38492</p>	<p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Thomas Alva Dunn (1833)	<p>Thomas Alva Dunn</p> <p>15919 Heron Trail Tomball, TX 77377</p>	<p>CO PLS - 38582</p> <p>FL PLS - 7136</p> <p>KY PLS - 4409</p> <p>MS PLS - 26983</p>	

	E-mail: tommy@dunnhouse.net	ND PLS - 27207 NM PLS - 26369 OK PLS - 2007 PA PLS - SU075669 TX RLS - 6561	
Jacob d edminster (1811)	Jacob d edminster po box 1274 toledo, WA 98591 360-807-3670 E-mail: edminsterfamily@yahoo.com	WA PLS - 47608	
Hunter J. Edwards (1026)	Hunter J. Edwards Edwards Surveying, PLLC 238 E. South St. Grangeville, ID 83530-2264 208-983-2666 E-mail: surveyingidaho@gmail.com	ID PLS - 9166	Deizell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Rynea L Edwards (1599)	Rynea L Edwards 100 Meadow Drive Chehalis, WA 98532 360-508-5798 E-mail: RYNEAE@GMAIL.COM	WA PLS - 45158	2014 LSAW Conference Deizell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 7 States Western Conference (2) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Identification & Subdivision of Fractional Section (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Scott A. Edwards (1576)	Scott A. Edwards 16518 NE 1st Pl Bellevue, WA 98008 425-681-0119 E-mail: Scott.Edwards.WA@gmail.com	OR PLS - 89562PLS WA PLS - 41024	2014 LSAW Conference Deizell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
William David Edwards (1038)	William David Edwards Edwards Surveying, LLC 8106 Grand Canyon Dr. Corpus Christi, TX 78414 940-393-0820 E-mail: davey@surveytxok.com E-mail: davey.edwards@tamucc.edu	OK PLS - 1612 TX RLS - 5627 TX Other - Licensed State Land Surveyor TX Other - PhD Geosciences/Cadastre	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)

			The Landslide Report (2) Tussio 37 IBLA 135 (1)
Thomas Henry Effinger (1560)	Thomas Henry Effinger E&F Associates 1120 Thornburg Street Box 771530 Steamboat Springs, CO 80477 970-734-5977 E-mail: teffinger33@msn.com	CO RLS - 17651 WY RLS - 8015	2018 Denver,CO: Resurveying an Entire GLO Township (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)
Kevin Eischens (1426)	Kevin Eischens PDC Engineers 2700 Gambell Street Ste. 500 Anchorage, AK 99503 907-743-3200 E-mail: kevineischens@pdceng.com E-mail: keischens@hotmail.com	AK PLS - 11554	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Tony Patrick Elley (1561)	Tony Patrick Elley Gila River Indian Community 4534 East Ivanhoe Street Gilbert, AZ 85295 602-432-8861 E-mail: rts43994@gmail.com	AZ RLS - 43994 CO PLS - 38239 NV PLS - 24552 UT PLS - 8101874-2201	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) The Landslide Report (2) Utah 2017 "Discrepancies in the Official Record" (2)
Jimmy Jason Elmore (1367)	Jimmy Jason Elmore 924 Emma Dr. Cardiff by the Sea, CA 92007 619-459-2295 E-mail: jelmore@hunsakersd.com	AZ PLS - 68806 CA PLS - 8483	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2) The PLSS Datum and the Local Surveyor (1) Working Group - San Diego 2011 (1)
John Kevin Elsbury (1257)	John Kevin Elsbury Rimrock Consulting 796 Panorama Dr. Moscow, ID 83843 208-816-2735 E-mail: jkelsbury@gmail.com	ID PLS - 7731	2015-Idaho Hillstrom presentation (2) Accretions in the Public Land Survey System (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2)

			<p>Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)</p>
Harold Nathin Epperson (1047)	<p>Harold Nathin Epperson</p> <p>H&J Consulting, LLC</p> <p>20165 N. 67th Avenue Suite 122A Glendale, AZ 85308 602-882-2371 E-mail: epperson.hal@gmail.com</p>	<p>AZ PLS - 21765</p> <p>CO PLS - 38071</p> <p>NV PLS - 9831 UT PLS - 7169813</p>	<p>2018 Western Regional Survey Conference_Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)</p>
Michael Ward Erickson (1702)	<p>Michael Ward Erickson</p> <p>Dyer Partnership</p> <p>1330 Teakwood Drive Coos Bay, OR 97420 541-269-0732</p> <p>E-mail: merickson@dypart.com</p>	<p>AK PE - CE 6743</p> <p>OR PLS - 2340</p> <p>OR PE - 13551 WA PLS - 45780</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Deizell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
J.T. Essex (1008)	<p>J.T. Essex</p> <p>Essex Surveying, LLC</p> <p>1350 PK Road Shepherd, MT 59079 406-665-5188 E-mail: jessex@essexsurveying.com</p>	<p>AK PLS - 12661</p> <p>ID PLS - 12946</p> <p>MT PLS - 14184 ND PLS - 5965 SD PLS - 9421 WA PLS - 48753 WY PLS - 12601</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Zamian Z Essex (1755)	<p>Zamian Z Essex</p> <p>39 Lightning Ln Red Lodge, MT 59068</p> <p>E-mail: zessex@essexsurveying.com</p> <p>E-mail: zamianessex@hotmail.com</p>	<p>MT PLS - 40989</p>	<p>2021 RMSS Conference (2) 7 States Western Conference (2) APLS-CLSA-NALS 2020 Conference (2) Discrepancies in the Official Record (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
David Patrick Evans (1242)	<p>David Patrick Evans</p> <p>Glahe & Assoc., Inc</p> <p>303 Church St. Sandpoint, ID 83864</p> <p>208-265-4474</p> <p>E-mail: devans@glaheinc.com</p>	<p>ID PLS - 5087 WA PLS - 20679</p>	<p>2021 RMSS Conference (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3)</p>

			Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
David Robert Evanson (1587)	David Robert Evanson ALTA Survey Company, PC 5090 Lindahl Road Duluth, MN 55811 218-576-2240 E-mail: davee@altasurveyduluth.com	MN PLS - 49505 WI RLS - S-3004	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Matthew Faulkner (1325)	Matthew Faulkner 60305 Tumalo Circle Bend, OR 97702 503-739-1063 E-mail: matt.faulkner@sflands.com	AK PLS - 13311 ID PLS - 14131 MT PLS - 28460 NM PLS - 23780 OR PLS - 75618 WA PLS - 47609	Accretions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
William Richard Fehringer (1427)	William Richard Fehringer 6080 Enterprise Drive Casper, WY 82609 307-995-2620 E-mail: billf@cepi-casper.com	CO PLS - 31152 MT PLS - 15295 ND PLS - 6856 WY PLS - 5528	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Christopher Ferguson (1520)	Christopher Ferguson USDA - FS U.S. Forest Service 401 Fairgrounds Road Rolla, MO 65401 573-341-7439 E-mail: cbferguson@fs.fed.us	AR PLS - 1384 IL PLS - 035-003424 KS PLS - 1322 MO PLS - 2642	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
William Patrick Finke (1297)	William Patrick Finke ESP Associates, Inc. 1156 McKee Farm Lane Belmont, NC 28012 724-255-5502 E-mail: wpfinke@gmail.com	IL PLS - 035-003282 KY PLS - 3028 NC PLS - L-4161 OH PLS - 7144 PA PLS - SU075393 TN PLS - 2536	2021 RMSS Conference (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2)

	E-mail: bfinke@essassociates.com	WV PLS - 892	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Daniel V. Fischer (1027)	<p>Daniel V. Fischer</p> <p>Fischer Land Surveying & Engineering</p> <p>PO Box 66</p> <p>513 Third Street</p> <p>Langdon, ND 58249</p> <p>701-256-5728</p> <p>E-mail: dfischer@utma.com</p>	<p>MN PLS - 26037</p> <p>MN PE - 26037</p> <p>ND PLS - 3856</p> <p>ND PE - 3856</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
John F Fisher (1185)	<p>John F Fisher</p> <p>PG&E</p> <p>3400 Crow Canyon Rd</p> <p>San Ramon, CA 94583</p> <p>707-200-3770</p> <p>E-mail: jf_2019@protonmail.com</p>	<p>CA PLS - 9270</p> <p>ID PLS - 12683</p> <p>WA PLS - 41286</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Boundary Evidence Standards Documents (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p> <p>Working Group - Salt Lake City, Utah 2009 (1)</p>
Robert M. Fitzmaurice (1089)	<p>Robert M. Fitzmaurice</p> <p>17215 NE 98th Ct</p> <p>Redmond, WA 98052</p> <p>425-869-2670</p> <p>E-mail: rmfitzmaurice@gmail.com</p>	<p>AZ PLS - 40692</p> <p>WA PLS - 32437</p>	<p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>APLS-CLSA-NALS 2020 Conference (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p>

			<p>Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Brett Richard Flippo (1428)	<p>Brett Richard Flippo</p> <p>Kennewick Irrigation District 2015 S Ely St Kennewick, WA 99337 602-363-2585 E-mail: bflippo@kid.org</p>	<p>AZ RLS - 48510</p> <p>WA PLS - 20111409</p>	<p>2019 APLS Private-Federal Boundary Determination (2) 2021 RMSS Conference (2) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Greg E. Flowers (1054)	<p>Greg E. Flowers</p> <p>PBS Engineering, Environmental and Survey 1841 Fern Ave Walla Walla, WA 99362</p> <p>509-520-4061</p> <p>E-mail: gnbflowers@charter.net</p> <p>E-mail: gregf@pbsusa.com</p>	<p>AK PLS - 13319 ID PLS - 13371 OR PLS - 02820LS WA PLS - 19619</p>	<p>2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) BLM's Experience with CFedS Produced LDR and COSs (1) February 2018 Las Vegas CFedS Workshop (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Matthew John Fore (1062)	<p>Matthew John Fore</p> <p>Miller Engineers & Associates, Inc.</p> <p>P.O. Box 223 601 Main Street Franklin, LA 70538</p> <p>337-828-1950 E-mail: mfore@millerengineersinc.com</p>	<p>KY PLS - 4284</p> <p>LA PLS - 4941</p> <p>MS PLS - 30074</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Lynee D Forsyth (1624)	<p>Lynee D Forsyth</p> <p>PO Box 2134</p> <p>Kingston, WA 98346</p> <p>360-396-2992 E-mail: lynee.forsyth@navy.mil</p> <p>E-mail: ldsjf11@hotmail.com</p>	<p>WA PLS - 45781</p>	<p>2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Virtual Conference - 3/29/21 (2) Delzell 158 IBLA 238 (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3)</p>

			Longview Fibre Co. 135 IBLA 170 (1) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Travis Paul Foster (1370)	Travis Paul Foster NV5 Global, Inc 205 Arabian Way Nampa, ID 83687 208-919-1590 E-mail: travis.foster@nv5.com E-mail: archeryelk28@gmail.com	ID PLS - 10729 MT PLS - 19457 ND PLS - LS-7985 OR PLS - 54624 WY PLS - 13731	2015-Idaho Hillstrom presentation (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
T. Patrick Fox (1371)	T. Patrick Fox 2981 Winthrop Circle SW Tumwater, WA 98512 360-972-5525 E-mail: BHSurveying@comcast.net	WA PLS - 27192	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Rick A. Foxworthy (1266)	Rick A. Foxworthy ESM Consulting Engineers, LLC 33400 8th Ave S Suite 205 Federal Way, WA 98003 253-838-6113 E-mail: rick.foxworthy@esmcivil.com	OR PLS - 82857 WA PLS - 35142	2014 LSAW Conference Delzell (1) Accretions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Daniel Gregory Francetic (1090)	Daniel Gregory Francetic Entellus, Inc. 3033 N. 44th St., Suite 250 Phoenix, AZ 85018 602-244-2566 E-mail: dfrancetic@entellus.com	AZ RLS - 33874 ID PLS - 18740 NM PLS - 18994 NV PLS - 20262 UT PLS - 8887650	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) 7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Discrepancies in the Official Record (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)

			Utah 2017 "Discrepancies in the Official Record" (2)
Alan David Frank (1091)	<p>Alan David Frank</p> <p>Johnson-Frank & Assoc., Inc.</p> <p>5150 E. Hunter Ave.</p> <p>Anaheim, CA 92807</p> <p>714-777-8877x107</p> <p>E-mail: alanfrank@johnson-frank.com</p>	<p>AZ RLS - 41830</p> <p>CA PLS - 7172</p> <p>NV PLS - 19539</p>	<p>2018 Western Regional Survey Conference_Workshop (2)</p> <p>2019 CLSA/NALS Private-Federal Boundary (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>The PLSS Datum and the Local Surveyor (1)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>Working Group - San Diego 2011 (1)</p>
Roger Alan Frank (1092)	<p>Roger Alan Frank</p> <p>Johnson-Frank & Associates, Inc.</p> <p>5150 E. Hunter Avenue</p> <p>Anaheim, CA 92807</p> <p>714-777-8877</p> <p>E-mail: rogerfrank@johnson-frank.com</p>	<p>CA PLS - 4215</p> <p>ND PLS - 2780</p> <p>NM PLS - 8287</p> <p>NV PLS - 5456</p> <p>SD RLS - 3197</p> <p>UT PLS - 158974-2201</p> <p>WY PLS - 3626</p>	<p>2018 Western Regional Survey Conference_Workshop (2)</p> <p>2019 CLSA/NALS Private-Federal Boundary (2)</p> <p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>The PLSS Datum and the Local Surveyor (1)</p> <p>Working Group - San Diego 2011 (1)</p>
Paul Louis Fridley (1796)	<p>Paul Louis Fridley</p> <p>1150 E. Herndon Ave #174</p> <p>Fresno, CA 93720</p> <p>916-346-6590</p> <p>E-mail: pfridley14@gmail.com</p> <p>E-mail: plf8@pge.com</p>	<p>CA PLS - 9390</p>	<p>Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1)</p> <p>Special Boundary Problems I (3)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Timothy David Fries (1780)	<p>Timothy David Fries</p> <p>HLA Engineering and Land Surveying, Inc.</p> <p>2803 River Rd</p> <p>Yakima, WA 98902</p> <p>509-945-2951</p> <p>E-mail: tfries@hlacivil.com</p> <p>E-mail: timdfries@gmail.com</p>	<p>WA PLS - 44631</p>	<p>2019 LSAW: PLSS Calculations & Case Studies (2)</p> <p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p>
Jacob Stone Frisch (1372)	<p>Jacob Stone Frisch</p> <p>Merrick & Company</p> <p>5970 Greenwood Plaza Blvd.</p> <p>Greenwood Village, CO 80111</p> <p>303-353-3641</p> <p>E-mail: jake.frisch@merrick.com</p> <p>E-mail: jacob.s.frisch@gmail.com</p>	<p>CO PLS - 38149</p> <p>MT Other - 38564</p> <p>OK Other - 1771</p>	<p>2016 Discrepancies in the Official Record (2)</p> <p>2018 Denver,CO: Resurveying an Entire GLO Township (2)</p> <p>2019 Rocky Mountain Surveyors Summit (2)</p> <p>2020_Colorado RMSS Workshop (2)</p> <p>2020_Colorado RMSS Workshop (TEST) (0)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>February 2021 RMSS Virtual Conference Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p>

			<p>Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Eric Irwin Fuller (1693)	<p>Eric Irwin Fuller St. Cloud State University 905 3rd St SW Rice, MN 56367</p> <p>301-448-5984 E-mail: eric-fuller@hotmail.com E-mail: eifuller@stcloudstate.edu</p>	<p>MD PLS - 21053 MN Other - 47224 VA Other - 0403002685</p>	<p>2018 Minneapolis - Discrepancies (2) APLS-CLSA-NALS 2020 Conference (2) Deizell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Ronald Eric Gallagher (1601)	<p>Ronald Eric Gallagher</p> <p>Western Kentucky University</p> <p>9706 East Clarksboro Liberty, MO 64068 816-536-2451 E-mail: ronald.gallagher@wku.edu</p>	<p>KY PLS - PS 3957 OH PLS - PS 7977</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Katherine Christine Gallegos (1602)	<p>Katherine Christine Gallegos T&D Services 9550 San Mateo Blvd NE Suite G</p> <p>Albuquerque, NM 87113 505-321-4277 E-mail: kgallegos@t-d-services.com</p>	<p>AZ RLS - 53472 NM PLS - 22500</p>	<p>2015 New Mexico Conference - Hillstrom (2) Deizell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Charles B Gardiner (1475)	<p>Charles B Gardiner</p> <p>Wood Environment & Infrastructure Solutions</p> <p>550 Northlake Blvd Altamonte Springs, FL 32701</p> <p>407-253-5500 E-mail: charles.gardiner@woodplc.com</p>	<p>FL PLS - LS5046 IN PLS - LS21500006 LA PLS - 5077 MO PLS - 2011017289 NC PLS - L-4598 OH PLS - PS.8614 OK PLS - 1836 SC PLS - 27735</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Mike Gardner (1072)	<p>Mike Gardner MTG 5930 SUMMERHILL ROAD TEXARKANA, TX 75503 251-459-1800 E-mail: mgardnersurveyor@gmail.com</p>	<p>AR PLS - 1537 LA PLS - 4972 OK PLS - 1629 TX RLS - 5760</p>	<p>Deizell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2)</p>

<p>Timothy J. Gaudette (1278)</p>	<p>Timothy J. Gaudette Lemme Engineering</p> <p>3608 W. Bethany Home Rd</p> <p>Phoenix, AZ 85019 602-841-6904</p> <p>E-mail: survey@lemme-eng.com</p>	<p>AZ RLS - 45721 CA PLS - 8690</p> <p>NV PLS - 20720</p>	<p>7 States Western Conference (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
<p>Gwendolyn Gee (1476)</p>	<p>Gwendolyn Gee</p> <p>Gee-O-Logical Surveys</p> <p>10900 Airport Road</p> <p>Columbia, CA 95310</p> <p>510-468-5340 E-mail: gwengeels@gmail.com</p> <p>E-mail: gwengeepls@gmail.com</p>	<p>CA PLS - 6780</p>	<p>2019 CLSA/NALS Private-Federal Boundary (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
<p>Gunnar B. Getchell (1014)</p>	<p>Gunnar B. Getchell</p> <p>Morrison-Maierle, Inc.</p> <p>1 Engineering Place</p> <p>Helena, MT 59602 406-495-3427 E-mail: ggetchell@m-m.net</p>	<p>MT PLS - 9758LS</p> <p>ND PLS - LS-9044</p> <p>WY PLS - LS9785</p>	<p>7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
<p>Frank Gibbons (1298)</p>	<p>Frank Gibbons</p> <p>Gibbons-NBQ, Inc</p> <p>2139 Main Ave. Durango, CO 81301 970-247-0851</p>	<p>CO PLS - 23498</p> <p>NM PLS - 10473</p>	<p>Avulsions in the Public Land Survey System (1) Boundary Evidence Standards Documents (1)</p> <p>Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Discrepancies in the Official Record (1)</p>

	E-mail: fgibbons@gibbons-nbq.com		February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Adam J Gile (1822)	Adam J Gile 1870 Paddock Place fitchburg, WI 53575 608-338-6850 E-mail: gile.adam@yahoo.com	WI PLS - 3162-8	
James Michael Glenzinski (1093)	James Michael Glenzinski Bureau of Land Management 2770 S Los Altos Pl Chandler, AZ 85286 480-772-2922 E-mail: m.glenzinski@cox.net	AZ RLS - 42072 CA PLS - 8982 CO PLS - 38518 NV PLS - 19340 WI RLS - 2667	2019 APLS Private-Federal Boundary Determination (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Pete Goers (1429)	Pete Goers Alliant Engineering, Inc. 733 Marquette Ave. Ste. 700 Minneapolis, MN 55402 E-mail: pgoers@alliant-inc.com	MN PLS - 44110 ND PLS - 8090	2014 MSPS Winter Seminar - Hillstrom (2) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Robert A Goodreau (1213)	Robert A Goodreau 445 Maple Street Kingsford, MI 49802 906-250-6284 E-mail: bgoodreau@outlook.com	MI PLS - 43053 WI PLS - S-1972 WI PE - E-31027	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)

Lee Kent Goss (1787)	Lee Kent Goss CookPLS National Inc. 8917 Chukar Road Yukon, OK 73099 405-365-0519 E-mail: sls.lee@sbcglobal.net	AR PLS - 1798 AZ RLS - 74017 CA PLS - 8331 CO PLS - 38642 KS PLS - 1594 NM PLS - 26662 OK PLS - 1778	Introduction to the Geographic Coordinate Database (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3)
Grant Hampton Gourley (1625)	Grant Hampton Gourley P.O. Box 171 Edgewood, NM 87015 575-518-8144 E-mail: gourleylandssurveys@yahoo.com	AZ RLS - 53254 NM PLS - 18373	Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
James Zachary Gowan (1477)	James Zachary Gowan Flatirons Surveying 9952 Sierra Vista Road Longmont, CO 80504 720-221-2683 E-mail: zgowan@flatironsinc.com	CO PLS - 29038 ID PLS - 12548 ND PLS - 6263 UT PLS - 6403366-2201 WA PLS - 44342	Accretions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Dannie Bryan Green (1430)	Dannie Bryan Green Psomas 1267 West 500 South Circle St George, UT 84770 435-669-8976 E-mail: dgreen@psomas.com	CA PLS - 9465 MT PLS - 30857LS NV PLS - 017962 UT PLS - 376078-2201	2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Robert Wayne Green (1539)	Robert Wayne Green Consolidated Land Services, Inc. 2113 Highway 62 East Mountain Home, AR 72653 870-425-6161 E-mail: rgreen@clsi-mtnhome.com	AR PLS - 1180 MO RLS - 2607	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Kevin Wayne Gregory (1562)	Kevin Wayne Gregory	AR PLS - 1578	Accretions in the Public Land Survey System (1)

	<p>Consolidated Land Services, Inc.</p> <p>2113 Hwy 62 East #2 Mountain Home, AR 72653 870-425-6161 E-mail: kgregory@clsi-mtnhome.com</p>	<p>MO PLS - 2018041552</p>	<p>Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Stephen J. Grimaldi (1274)	<p>Stephen J. Grimaldi</p> <p>USFS</p> <p>P.O. Box 6</p> <p>Bryant Pond , ME 04219 207-381-0255</p> <p>E-mail: sgblmwork@gmail.com</p> <p>E-mail: stephen.grimaldi@usda.gov</p>	<p>ID PLS - L-12354</p> <p>ME PLS - PLS20002375</p> <p>NV PLS - 021784</p> <p>OR PLS - 79889PLS</p> <p>VT PLS - 024.0132653</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Rien Groenewoud (1267)	<p>Rien Groenewoud</p> <p>NorthStar Engineering Group, Inc.</p> <p>620 12th Street Modesto, CA 95354</p> <p>209-524-3525 E-mail: rien@nseng.net</p>	<p>AZ RLS - 49319</p> <p>CA PLS - 6946</p> <p>UT PLS - 5936928-2201</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Mineral Surveys (2) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Chad Aaron Gulick (1735)	<p>Chad Aaron Gulick</p> <p>Nathan D. Maier Consulting Engineers, Inc. 12377 Merit Drive, Suite 700 Dallas, TX 75251 972-746-3476</p> <p>E-mail: cgulick@ndmce.com</p>	<p>AR PLS - 1881</p> <p>AZ RLS - 72472</p> <p>KS PLS - 1703</p> <p>LA PLS - 5091</p> <p>MS PLS - 31299</p> <p>NM PLS - 21052</p> <p>OK PLS - 1718</p> <p>TX RLS - 6021</p>	<p>Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p>
Rodney V. Gunderson (1299)	<p>Rodney V. Gunderson</p> <p>Minnesota Department of Transportation</p> <p>3920 Hwy 2 West Bemidji, MN 56601</p>	<p>MN PLS - 41204</p>	<p>2014 MSPS Winter Seminar - Hillstrom (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1)</p>

	218-755-6523 E-mail: Rod.Gunderson@dot.state.mn.us		Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jonathan R. Gustafson (1197)	Jonathan R. Gustafson Stantec 16590 Hearthiside Way Lakeville, MN 55044 651-295-3279 E-mail: jon.gustafson@stantec.com	CA PLS - L 9301 MN PLS - 46566 NM PLS - 23201	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Stephen K. Haddock (1478)	Stephen K. Haddock Witness Tree Surveying P.O. Box G Pilot Rock, OR 97868 541-443-2922 E-mail: witnessree@eoni.com	OR PLS - 56295LS WA PLS - 50700	2011 Annual CFedS Workshop Presenter (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The PLSS Datum and the Local Surveyor (1) Tussio 37 IBLA 135 (1) Working Group - San Diego 2011 (1)
James Aaron Hall (1746)	James Aaron Hall McLane Consulting 47446 Wispen Ave Kenai, AK 99611 907-953-5886 E-mail: hall_james_a@alaska.net	AK PLS - 85032 NV PLS - 20133	Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Joseph M Hall (1828)	Joseph M Hall Jackson County 2288 Highgate st. unit 11 Medford , OR 97501 541-778-5389 E-mail: halljoe1978@gmail.com E-mail: halljh@jacksoncounty.org	OR PLS - 86832	
Russell O. Halverson (1374)	Russell O. Halverson Bolton & Menk 1314 Mayflower Drive Northfield, MN 55057 507-301-2029 E-mail: russha@bolton-menk.com E-mail: russ.halverson@yahoo.com	MN RLS - 41813 WI RLS - 2581-8	2014 MSPS Winter Seminar - Hillstrom (2) 2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3)

			Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1)
Chris Dalton Hamilton (1194)	Chris Dalton Hamilton Hamilton Land Surveying P.O. Box 694 207 West Ramshorn Dubois, WY 82513 307-455-2070 E-mail: hamilton@wyoming.com	CO PLS - 26595 ID PLS - 14857 MT PLS - 10804 SD RLS - C-7487 UT PLS - 176719 WY PLS - 5297	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Thomas Allen Hannah (1804)	Thomas Allen Hannah Whitson Engineers 10 Ivy Street Monterey, CA 93940 831-915-6744 E-mail: thannah@whitsonengineers.com E-mail: tommytunes50@hotmail.com	CA PLS - 8312	Longview Fibre Co. 135 IBLA 170 (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
David Francis Hanrion (1479)	David Francis Hanrion USDA Forest Service 115 E 900 N Richfield, UT 84701 775-292-9088 E-mail: david.hanrion@usda.gov E-mail: dhanrion@gmail.com	CA PLS - 8020 NV PLS - 16949 UT PLS - 289581	2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) Utah 2017 "Discrepancies in the Official Record" (2)
Jared Hansmann (1540)	Jared Hansmann Survey Innovation Group 7444 W. Tonopah Dr. Glendale, AZ 85308 402-417-3748 E-mail: jaredhansmann@msn.com E-mail: jaredh@sigsurveyaz.com	AZ PLS - 60697	Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Timothy Hanson (1279)	Timothy Hanson Niobrara Valley Consultants L.L.C. PO Box 716 1105 trail drive Valentine, NE 69201 402-376-2691 E-mail: thanson.nvcllc95@gmail.com	NE RLS - 491 SD RLS - 6774	2021 RMSS Conference (2) 7 States Western Conference (2) APLS-CLSA-NALS 2020 Conference (2) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Gregory Lynn Harbeson (1480)	Gregory Lynn Harbeson 1714 North 10th Street	CO PLS - 6245 ID PLS - 13004	2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1)

	<p>Washougal, WA 98671 208-721-8975</p> <p>E-mail: gregharbeson@aol.com</p>	<p>WA PLS - 53043</p>	<p>2015 - LSAW Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Identification & Subdivision of Fractional Section (2) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments - LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
James Michael Hart (1094)	<p>James Michael Hart</p> <p>BoundaryHunters LLC</p> <p>31318 N 1st PL</p> <p>Phoenix, AZ 85085</p> <p>619-797-7443 E-mail: jmhart55@gmail.com E-mail: boundaryhuntersLLC@outlook.com</p>	<p>AR PLS - 953</p> <p>AZ PLS - 57999</p> <p>CA PLS - 8023</p> <p>ND PLS - LS-8622</p> <p>NE RLS - 733 NM PLS - 21651 OK PLS - 1783</p> <p>OR PLS - 86747 SD PLS - 11539 UT PLS - 8051637-2201</p>	<p>2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) 7 States Western Virtual Conference - 3/29/21 (2) Boundary Evidence Standards Documents (1)</p> <p>CIM Quiz (1) Discrepancies in the Official Record (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) The PLS Datum and the Local Surveyor (1) Working Group - Salt Lake City, Utah 2009 (1)</p> <p>Working Group - San Diego 2011 (1)</p>
Colin Dale Harvey (1792)	<p>Colin Dale Harvey</p> <p>Harvey Land Surveying, Inc. 461 E. Dartmouth Drive Casa Grande, AZ 85122 520-371-1642 E-mail: coleharvey@harveysurveying.com</p>	<p>AZ RLS - 42017</p> <p>CO PLS - 38181 ND PLS - LS-8816 NV PLS - 20264 UT PLS - 7223620-2201</p>	<p>Introduction to the Geographic Coordinate Database (3) Special Boundary Problems I (3)</p>
Zachary Hassler (1698)	<p>Zachary Hassler</p> <p>Mammoth Survey Co Inc 3045 Tampico Dr. Billings, MT 59101</p> <p>E-mail: zac.hassler@gmail.com E-mail: zhassler@mammothsurvey.com</p>	<p>CO PLS - 38622</p> <p>MT PLS - 29090 ND PLS - 9549 WY PLS - 14827</p>	<p>Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The Landslide Report (2)</p>
Sheryl Hatcher (1589)	<p>Sheryl Hatcher 4648 Harrier Drive Klamath Falls, OR 97601</p> <p>E-mail: sheryl.hatcher@gmail.com</p>	<p>AZ RLS - 32227 CA Other - LLS 7082 NM Other - PS 16604</p> <p>NV PLS - 9515 OR PLS - 91669</p>	<p>2015 New Mexico Conference - Hillstrom (2) Deizell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Gary L. Hatle (1482)	<p>Gary L. Hatle</p> <p>Apex Surveying, Inc.</p> <p>P.O. Box 1072</p> <p>Riverton, WY 82501 307-856-1647</p> <p>E-mail: ghatle@apexsurveying.com</p>	<p>CO PLS - 18984</p> <p>WY PLS - 2338</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1)</p>

			<p>Nov2015_Discrepancies in the Official Record (2)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p>
Steven Tod Haug (1276)	<p>Steven Tod Haug 1150 N Curtis Rd</p> <p>Boise, ID 83706</p> <p>208-378-6210</p> <p>E-mail: shaug@usbr.gov</p>	ID PLS - 12461	<p>2015-Idaho Hillstrom presentation (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Douglas Neil Haywood (1095)	<p>Douglas Neil Haywood</p> <p>BLM</p> <p>7810 Gate Creek Dr Anchorage, AK 99502</p> <p>703-674-9164</p> <p>E-mail: dhaywood@blm.gov</p>	AK PLS - 9942	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Alan Heady (1715)	<p>Alan Heady</p> <p>13118 Smart Road</p> <p>Lee's Summit, MO 64086</p> <p>816-809-9409</p> <p>E-mail: aheady@tb-engr.com</p> <p>E-mail: alan.HEADY@outlook.com</p>	<p>KS PLS - 1079</p> <p>MO PLS - 2312</p>	<p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Eric L Hearon (1781)	<p>Eric L Hearon</p> <p>KLJ</p> <p>2933 Spruce Dr. Cheyenne, WY 82001</p> <p>775-772-5104</p> <p>E-mail: eric.hearon@kljeng.com</p> <p>E-mail: eric.hearon@yahoo.com</p>	<p>CO PLS - 38725</p> <p>ND PLS - 9654</p> <p>NV PLS - 12138</p> <p>WY PLS - 17229</p>	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Special Boundary Problems I (3)</p>
Michael J. Heberlein (1433)	<p>Michael J. Heberlein</p> <p>1268 Gils Way</p> <p>Cross Plains, WI 53528</p> <p>608-798-4870</p> <p>E-mail: mick.heberlein@dot.wi.gov</p>	<p>MI PLS - 56348</p> <p>WI PLS - 2615-8</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p>

			<p>Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Rick L Henry (1097)	<p>Rick L Henry 3024 W 26TH ST JOPLIN, MO 64804</p> <p>E-mail: rickhenry_us@yahoo.com</p>	MO PLS - 2305	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Brian Kenneth Henson (1626)	<p>Brian Kenneth Henson</p> <p>Multnomah County 38954 Proctor Blvd., No. 355 Sandy, OR 97055</p> <p>E-mail: BKHLANDSURVEYING@GMAIL.COM</p>	<p>ID PLS - 8899</p> <p>NV PLS - 013600 OR PLS - 02855 WA PLS - 34139</p>	<p>Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Oregon: PLSO Annual Conference – Jan 21-23, 2015 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Marshall L. Hetlet (1412)	<p>Marshall L. Hetlet Lounsbury & Associates, Inc</p> <p>PO Box 3172 Ferndale, WA 98248</p> <p>E-mail: m.hetlet@lounsburyinc.com</p>	<p>AK PLS - 9108 MT PLS - 31352</p> <p>ND PLS - 9949</p> <p>OR PLS - 83086</p> <p>WA PLS - 38976</p>	<p>2014 LSAW Conference Delzell (1) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Identification & Subdivision of Fractional Section (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Paul James Hickey (1817)	<p>Paul James Hickey 7051 W. Cambridge Drive Wasilla, AK 99623 907-232-3738 E-mail: pjhickey1986@yahoo.com</p>	AK PLS - 7202	<p>7 States Western Virtual Conference - 3/29/21 (2)</p>
Tyrone Hicks (1376)	<p>Tyrone Hicks</p> <p>1087 Jefferson Way</p>	NV PLS - 12063	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1)</p>

	<p>Forest, VA 24551 702-480-7178 E-mail: tyhicks4u@hotmail.com E-mail: tyhicks4u@gmail.com</p>		<p>Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
James A. Hildenbrand (1696)	<p>James A. Hildenbrand</p> <p>Harmsen LLC 603 South First Street Mount Vernon, WA 98273</p> <p>E-mail: JimH@harmsoninc.com</p>	WA PLS - 53688	<p>2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Conference (2) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Longview Fibre Co. 135 IBLA 170 (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Royce Hill (1671)	<p>Royce Hill</p> <p>Bureau of Land Management</p> <p>351 Allender RD</p> <p>Ryderwood, WA 98581 503-808-6392 E-mail: r1hill@blm.gov E-mail: roycehill@earthlink.net</p>	<p>ID PLS - 12394</p> <p>OR PLS - 2289</p> <p>WA PLS - 24785</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Michael R. Hoge (1327)	<p>Michael R. Hoge</p> <p>Clackamas County Surveyors Office</p> <p>15028 Evans Valley Rd NE</p> <p>Silverton, OR 97381</p> <p>503-951-1817</p> <p>E-mail: mikerhoge@gmail.com E-mail: mikehoge@clackamas.us</p>	OR PLS - LS 2782	<p>2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Christopher Dean Hoglund (1756)	Christopher Dean Hoglund	CA PLS - 8534	<p>2018 Western Regional Survey Conference_Workshop (2)</p>

	<p>Westwood Professional Services</p> <p>12701 Whitewater Drive</p> <p>Suite #300 Minnetonka, MN 55343 952-906-7453</p> <p>E-mail: chris.hoglund@westwoodps.com</p>	<p>CO PLS - 38656</p> <p>IA PLS - 18762</p> <p>IL PLS - 035003903 IN PLS - 21400013 KY PLS - 4125</p> <p>MN PLS - 43932 MT PLS - 62639 NV PLS - 20599 NY PLS - 050733-1 OR PLS - 87134 RI PLS - 2514 SD PLS - 9160 TN PLS - 3069</p>	<p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Kenneth Gordon Holmbeck (1483)	<p>Kenneth Gordon Holmbeck</p> <p>19207 Carson St. NW</p> <p>PO Box 811 Elk River, MN 55330 763-639-0171 E-mail: kenholmbeck@yahoo.com</p>	<p>MN PLS - 18890</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Matthew Holtsclaw (1328)	<p>Matthew Holtsclaw</p> <p>PO Box 2023</p> <p>Camden, SC 29020</p> <p>E-mail: mbhcfeds@gmail.com</p>	<p>CO PLS - 0038718</p> <p>NC PLS - L-4653</p> <p>OK PLS - 1917</p> <p>TN RLS - 2668</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Steven Andrew Hooks (1378)	<p>Steven Andrew Hooks</p> <p>6215 Park Leaf Walk</p> <p>Buford, GA 30518 912-674-8296 E-mail: stevenahooks@gmail.com</p>	<p>GA RLS - 3083</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>

<p>Patricia Louise Hooyer (1063)</p>	<p>Patricia Louise Hooyer State of Alaska DOT/PF 4111 Aviation Ave Anchorage, AK 99502 907-269-0713 E-mail: Louise.hooyer@alaska.gov</p>	<p>AK PLS - LS-6109</p>	<p>William D. Brown 137 IBLA 31 (1) 2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
<p>Christina M. Hopp (1413)</p>	<p>Christina M. Hopp N5641 County Road J Ellsworth, WI 54011 651-212-0101 E-mail: hopp_chris@hotmail.com</p>	<p>CO PLS - 38741 MN PLS - 46173 ND PLS - LS-28181 SD RLS - 14173 WI PLS - 2893-008</p>	<p>2014 MSPS Winter Seminar - Hillstrom (2) 2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
<p>Michael John Horne (1073)</p>	<p>Michael John Horne Farpoint Land Services LLC 1131 76 E, Suite 101 Anchorage, AK 99503 907-250-0402 E-mail: mhorne.ak@gmail.com</p>	<p>AK PLS - LS 5318</p>	<p>Hillstrom 180 IBLA 388 (2) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
<p>George C Horton (1247)</p>	<p>George C Horton State of Alaska, Dept. of Natural Resources 550 West 7th Avenue, Suite 650 Anchorage, AK 99501-3576 907-269-8610 E-mail: george.horton@alaska.gov</p>	<p>AK PLS - 10396</p>	<p>2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>

Benjamin James Hron (1757)	Benjamin James Hron 1873 Brentwood Pointe Franklin, TN 37067 615-393-9771 E-mail: hron.ben@gmail.com E-mail: bhron@cecinc.com	AK PLS - 13010 OR PLS - 92723 WI PLS - 2983	Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Philipp Hummel (1541)	Philipp Hummel 7074 S. Revere Parkway Centennial, CO 80112 E-mail: huph73@gmail.com	AZ RLS - 53887 CO PLS - 38155 ID PLS - 15114 NE PLS - 739 SD PLS - 11462 UT PLS - 8446416-2201	2021 RMSS Conference (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Aaron Hummert (1770)	Aaron Hummert Sauber Engineering, Inc. 1901 31st Street NW Mandan, ND 58554 701-426-8624 E-mail: hummertsurveying@gmail.com E-mail: ahummert@sauberengineering.com	MN PLS - 54377 MT PLS - 30982 ND PLS - 7512 SD RLS - 11271 WI PLS - 3157-8 WY PLS - 16357	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Specifications for Land Descriptions (1) Deizell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Gregory Alan Hunter (1435)	Gregory Alan Hunter Maricopa County Department of Transportation 2901 W Durango St Phoenix, AZ 85009 602-506-4679 E-mail: GreggHunter@mail.maricopa.gov	AZ RLS - 35865	2019 APLS Private-Federal Boundary Determination (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Jesse Hunter (1329)	Jesse Hunter Maricopa County Department of Transportation 2901 West Durango Street Phoenix, AZ 85009 602-828-3225 E-mail: jesse.hunter@maricopa.gov E-mail: jhunter@az-hunters.com	AZ RLS - 48362 UT PLS - 7420172	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) 7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Boundary Evidence Standards Documents (1) Discrepancies in the Official Record (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)
Desiree Lynn Hurst (1639)	Desiree Lynn Hurst PO Box 210097 Bedford, TX 76095 214-282-9422 E-mail: desilu44d@netscape.net E-mail: dhurst@ypassociates.com	IL PLS - 035.003948 NM PLS - 22257 OK PLS - 1951 TX RLS - 6230	February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)
Dane Mark Ince (1099)	Dane Mark Ince www.SanFranciscoSurveyingCompany.com 201 harrison street #828 san francisco, CA 94105	CA PLS - 8142	Deizell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1)

	<p>415-321-9300 E-mail: surveyor@sanfranciscosurveyingcompany.com E-mail: surveyor@sfsvco.com</p>		<p>Monumentation and the Corner Record (3) Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
John D Ingraham (1627)	<p>John D Ingraham</p> <p>MMI</p> <p>315 n 25th st</p> <p>Suite 102</p> <p>Billings, MT 59101</p> <p>E-mail: jingraham@m-m.net</p>	MT PLS - 14736	<p>2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)</p>
Joshua F Ivaniszek (1484)	<p>Joshua F Ivaniszek</p> <p>Chilkat Surveying & Mapping,LLC</p> <p>10654 Porter Lane</p> <p>Juneau, AK 99801</p> <p>907-957-1908 E-mail: jfivanis@mtu.edu E-mail: chilkat.surveying@gmail.com</p>	AK PLS - 12314	<p>2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Brenda J James (1758)	<p>Brenda J James</p> <p>U.S. Fish & Wildlife</p> <p>911 NE 11th Ave. Portland, OR 97232</p> <p>E-mail: brenda_james@fws.gov E-mail: brenda.james@q.com</p>	<p>ID PLS - 15369</p> <p>MT PLS - 38685</p> <p>OR PLS - 77593 WA PLS - 49913</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) The Landslide Report (2)</p>
James Lee Janisse (1829)	<p>James Lee Janisse</p> <p>Jones Carter</p> <p>24023 Western Meadow San Antonio, TX 78261 805-234-1823 E-mail: jjanisse@jonescarter.com E-mail: janissejay@hotmail.com</p>	<p>AL PLS - 39346 AZ PLS - 68179 CO PLS - 0038704 FL Other - LS7294 LA PLS - 5231 MS PLS - PS-31300 NM PLS - 25664 NV PLS - 028034 OK PLS - 2015 TX RLS - 6663 UT PLS - 11814508-2201</p>	
Peter Warren Jenkins (1330)	<p>Peter Warren Jenkins</p> <p>Minnesota Department of Transportation 395 John Ireland Boulevard</p> <p>MS 630</p> <p>St. Paul, MN 55155 651-366-3504</p> <p>E-mail: peter.jenkins@state.mn.us</p>	<p>MN PLS - 22683</p> <p>WI PLS - 2208</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2) 2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3)</p>

			<p>Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Gerald Jennings (1249)	<p>Gerald Jennings</p> <p>PO Box 670729</p> <p>Chugiak, AK 99567 907-538-1556</p> <p>E-mail: gj502003@yahoo.com</p>	AK PLS - 6471-S	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Craig A. Jensen (1300)	<p>Craig A. Jensen</p> <p>4328 E. Sunrise Drive</p> <p>Phoenix, AZ 85044-1005</p> <p>E-mail: caj4@cox.net</p>	<p>AZ RLS - 17288</p> <p>NM PLS - 20685</p>	<p>2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Boundary Evidence Standards Documents (1)</p> <p>Discrepancies in the Official Record (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Mark Johannes (1262)	<p>Mark Johannes</p> <p>Compass Surveying & Mapping, LLC 8015 Chancellor Dr. Colorado Springs, CO 80920 719-354-4120</p> <p>E-mail: mark@csamllc.com</p>	<p>AZ RLS - 54330</p> <p>CO PLS - 32439</p> <p>KS PLS - 1360</p> <p>NE RLS - 615</p>	<p>Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Benjamin R. Johnson (1689)	<p>Benjamin R. Johnson</p> <p>DOI/BLM</p>	<p>AZ RLS - 60130</p> <p>UT PLS - 9864647-2201</p>	<p>2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1)</p>

	<p>HCR 60 Box 87</p> <p>Mona, UT 84645</p> <p>801-623-8242</p> <p>E-mail: bjohnsoncfeds@gmail.com</p>		<p>Avulsions in the Public Land Survey System (1)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Utah 2017 "Discrepancies in the Official Record" (2)</p>
Craig E. Johnson (1182)	<p>Craig E. Johnson Sambatek</p> <p>404 2nd Avenue NW</p> <p>Buffalo, MN 55313 763-300-4877</p> <p>E-mail: cjohnson@sambatek.com</p>	MN PLS - 44530	<p>2014 MSFS Winter Seminar - Hillstrom (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Robby Lynn Johnson (1102)	<p>Robby Lynn Johnson</p> <p>Bennett-Morris & Associates Land Surveying PC</p> <p>11252 North County Road 3370 Stratford , OK 74872</p> <p>580-399-6460</p> <p>E-mail: rjohnson@okrpls.com</p>	OK PLS - 1539	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Robert C. Johnson (1485)	<p>Robert C. Johnson</p> <p>6572 Astorville Ct.</p> <p>Las Vegas, NV 89110</p> <p>702-501-9560</p> <p>E-mail: rcjohnson1947@gmail.com</p>	<p>NV PLS - 10114</p> <p>NV Other - 1203</p>	<p>2018 Western Regional Survey Conference_Workshop (2)</p> <p>2019 CLS/NALS Private-Federal Boundary (2)</p> <p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Thomas Johnson (1380)	<p>Thomas Johnson</p> <p>Apex Surveying, Inc</p> <p>407 W. Adams Riverton, WY 82501</p> <p>307-856-1647</p> <p>E-mail: tjohnson@apexsurveying.com</p>	<p>CO PLS - 31930</p> <p>WY PLS - 8972</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Nov 2015_PLSW_Tussio (1)</p> <p>Nov2015_Discrepancies in the Official Record (2)</p>

			<p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Robert Michael Jones (1486)	<p>Robert Michael Jones</p> <p>Wood E&S</p> <p>1300 Foxfire Drive Apopka, FL 32712 407-463-2787 E-mail: mike.jones2@woodplc.com E-mail: rjones469@embarqmail.com</p>	<p>AL PLS - 16447</p> <p>CA PLS - 8707</p> <p>FL PLS - 4201 GA PLS - 2367 MS PLS - 3172 TX PLS - 6271</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Russell Jones (1301)	<p>Russell Jones</p> <p>4207 21st Ave</p> <p>Missoula, MT 59803</p> <p>E-mail: rustyjones.co@gmail.com</p>	<p>CO PLS - 25950</p> <p>ID PLS - 11712</p> <p>MT PLS - 63072</p>	<p>2019 MARLS Private-Federal Boundary Determination (2)</p> <p>2019 MARLS Specifications for Land Descriptions (1)</p> <p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Steven A Jones (1009)	<p>Steven A Jones</p> <p>DLZ</p> <p>2211 East Jefferson</p> <p>South Bend, IN 46615 574-245-1672 E-mail: sjones@dlz.com</p>	<p>AL PLS - 30979</p> <p>FL PLS - 6824</p> <p>IL PLS - 3589</p> <p>IN PLS - 20200010 KY PLS - 4359 MI PLS - 56304 MO PLS - 2010000244 OH PLS - 8464</p> <p>WI PLS - 2660</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Thomas A Judge (1764)	<p>Thomas A Judge</p> <p>Forsgren Associates, Inc.</p>	<p>ID PLS - 13934</p> <p>NV PLS - 24540</p>	<p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p>

	4826 N. Leather Way Boise, ID 83713 208-703-8872 E-mail: jplsidoaho@gmail.com E-mail: tjudge@forsgren.com	OR PLS - 91215 UT PLS - 4854556 WA PLS - 51794	Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2)
Evelyn R Kalb (1487)	Evelyn R Kalb 1605 Lone Rock Rd. Glide, OH 97443 503-910-9051 E-mail: kalb@chesebro-kalb.com	OR PLS - 2456	7 States Western Conference (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Oregon: PLSO Annual Conference – Jan 21-23, 2015 (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
Lawrence J. Kane (1577)	Lawrence J. Kane 120 Airport Road North Haverhill, NH 03774 603-243-0383 E-mail: lka9ne@gmail.com	AZ RLS - 60691 CO PLS - 38392 ME PLS - 1239 NH Other - 630 NY RLS - 050555	Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)
William L. Karr (1488)	William L. Karr Chippewa County Surveyor Retired (retired) 28705 S. M-129 Pickford, MI 49774 906-647-6224 E-mail: wlkarr51@gmail.com	MI PLS - 4001027450	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Ryan Louis Kearney (1793)	Ryan Louis Kearney USDA Forest Service 24 Fort Missoula Road Missoula, MT 59804 406-600-1836 E-mail: ryan.l.kearney@usda.gov E-mail: ryan.kearney@live.com	ID PLS - 17777 MT PLS - 49115 NE PLS - 752 SD PLS - 11513 WY PLS - 14644	Hillstrom 180 IBLA 388 (2) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)
Trent J Keenan (1438)	Trent J Keenan Diamondback Land Surveying, LLC 6140 Brent Thurman Way Suite 200 Las Vegas, NV 89148 702-596-3257 E-mail: trent@db-ls.com E-mail: tkeenan@diamondbacklandsurveying.com	AZ RLS - 42460 CA PLS - 8396 NV PLS - 16802 UT PLS - 5790532-2201 WA PLS - 49281	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
John David Keller (1834)	John David Keller Audubon Field Solutions 6317 E 111th Place Tulsa, OK 74137	AK PLS - 1860 CO PLS - 38674 IA PLS - P25900 IL PLS - 035.004035	

	806-418-5253 E-mail: kellersurveying@gmail.com E-mail: jkeller@auduboncompanies.com	KS PLS - 1518 MO PLS - 2019030295 NE PLS - 809 OK PLS - 1189 TX Other - 4157 WY PLS - 18254	
Daniel Ray Kenczka (1332)	Daniel Ray Kenczka Thomas, Dean, & Hoskins 1800 River Dr N Great Falls, MT 59401 406-761-3010 E-mail: Dan.Kenczka@tdengineering.com	MT PLS - 15625 ND PLS - LS-7971	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Brett R. Kennedy (1189)	Brett R. Kennedy Stockwell Engineers 201 Walnut Street Yankton, SD 57078 605-665-8092 E-mail: bkennedy@stockwellengineers.com	CO PLS - 30457 IA PLS - 13806 KS PLS - 1230 MN PLS - 40449 MT PLS - 22301 ND PLS - 4389 NE PLS - 512 SD PLS - 5350 WY PLS - 12704	2014 South Dakota SPLS Presentation - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Clyde Jay King (1492)	Clyde Jay King ASM PO Box 86 buckhorn, NM 88025 575-535-2608 E-mail: cking@absurv.com	AZ RLS - 28728 CO PLS - 33190 NM PLS - 13979 UT PLS - 366504-2201	Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Mineral Surveys (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2)
David M. King (1003)	David M. King 7205 Santa Fe Trl. NW Albuquerque, NM 87120 505-507-7748 E-mail: dking256@comcast.net	NM PLS - 10282	2015 New Mexico Conference - Hillstrom (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2)

			<p>Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Eric Shane King (1697)	<p>Eric Shane King White Hawk Engineering & Design, LLC 1389 Howard Dr</p> <p>Davis, OK 73030 405-698-9919 E-mail: sking@whitehawkmail.com E-mail: okpls1542@gmail.com</p>	OK PLS - 1542	<p>Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Galen L. King (1333)	<p>Galen L. King</p> <p>Alaska Dept. of Natural Resources, Survey Section 3700 Airport Way</p> <p>Fairbanks, AK 99709-4699</p> <p>907-451-2758</p> <p>E-mail: larry.king@alaska.gov</p>	AK PLS - 9326	<p>2019 Alaska Society of Professional Land Surveyors (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
William Joseph Kinney (1771)	<p>William Joseph Kinney 704 Indiana Ave. Collinsville, IL 62234 618-367-6357 E-mail: wjkinney@hotmail.com</p>	IL PLS - 035.004049	Non-Rectangular Surveys (9)
Paul Frederick Klemperer (1722)	<p>Paul Frederick Klemperer</p> <p>Trihydro Corporation 2632 Pasquinel Dr.</p> <p>Fort Collins, CO 80526</p> <p>970-488-0509 E-mail: pklemperer@trihydro.com</p>	<p>CO PLS - 33193</p> <p>MT PLS - 19987 WY PLS - 9557</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) Accretions in the Public Land Survey System (1) February 2021 RMSS Virtual Conference Workshop (2) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) The 2009 Manual of Surveying Instructions (2)</p>
Derek James Klinkenborg (1203)	<p>Derek James Klinkenborg</p> <p>American Surveying & Mapping</p> <p>10301 Catalina Overland Park, KS 66207 913-800-1556 E-mail: djklinkenborg@gmail.com</p> <p>E-mail: dklink_dklink@yahoo.com</p>	<p>AL RLS - 34933</p> <p>AR PLS - 1471</p> <p>AZ RLS - 51451 CA PLS - 9125 CO PLS - 38295 FL PLS - 7297</p> <p>ID PLS - 13442 KS PLS - 1151 KY PLS - 3999</p> <p>MO PLS - 2484 MS PLS - 3140 MT PLS - 19702 NC PLS - 5037</p> <p>ND PLS - 6216</p> <p>NE PLS - 627 NV PLS - 20891 OH PLS - 8675 OK PLS - 1549</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>

		SD PLS - 9663 TN PLS - 2840 TX RLS - 6377 UT PLS - 7298483-2201 VA PLS - 003203 WA PLS - 56652 WI PLS - 3040-8 WV PLS - 2214 WY PLS - 16554	
Bob Ray Knuth (1439)	Bob Ray Knuth P.O. Box 434 Vader, WA 98593 707-599-3336 E-mail: Bob_Knuth@dnr.wa.gov E-mail: Bob_Knuth_PLS@yahoo.com	CA PLS - L7938 OR PLS - 02866PLS WA PLS - 36618	Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Robert Kohler (1721)	Robert Kohler Basin Electric Power Cooperative 1309 E. Divide Ave Bismarck, ND 58501 E-mail: rkohler@becp.com	ND PLS - LS-6718 NE PLS - 798 SD PLS - 12276 WY PLS - LS 17109	Accretions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2) Specifications for Descriptions of Land (1) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Helmut Richard Korstick (1542)	Helmut Richard Korstick Chaudhary & Associates 1205 Trombetta St. Santa Rosa, CA 95407 707-571-8128 E-mail: helmut@chaudhary.com E-mail: handnkorstick@yahoo.com	CA PLS - 7739	Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)
Scott C Koterba (1005)	Scott C Koterba UINTA Engineering and Land Surveying 616 5th Street SW Sidney, MT 59270 406-366-3050 E-mail: skoterba@uintahgroup.com	MT PLS - 10801 LS ND PLS - LS-9500	7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Joe Kraft (1805)	Joe Kraft Snohomish County	AZ RLS - 48225 CA PLS - L 9517	7 States Western Virtual Conference - 3/29/21 (2) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1)

	8022 174th Place NE Arlington, WA 98223 602-370-5757 E-mail: joe.krafrlts@gmail.com	ID PLS - L 18333 NV PLS - 23671 WA PLS - 55514	Landslides & Moving Monuments – LSAW WA 2019 (1) The 2009 Manual of Surveying Instructions (2)
Kenneth Allen Krenke (1105)	Kenneth Allen Krenke Northland Exploration Surveys, Inc. 528 West Aspen Avenue Flagstaff, AZ 86001-5308 928-774-5058 E-mail: kkrenke@aspen528.com	AZ RLS - 14671 CO PLS - 18463 NM RLS - 10301	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) 7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Boundary Evidence Standards Documents (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Kevin A. Krohe (1640)	Kevin A. Krohe 1555 Gravel Springs Circle Jacksonville, IL 62650 E-mail: kkrohe@artisancivil.com	IL PLS - 035-003761 IL PE - 062.0681149 MO PLS - 2015000229 WI PLS - 2978-8	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)
Brandon L Kupitz (1788)	Brandon L Kupitz 212 Chicago Mine Rd. Wakefield, MI 49968 906-364-1397 E-mail: bkupitz@gmail.com E-mail: bkupitz@coleman-engineering.com	MI PLS - 4001069933 WI PLS - 3135-8	Introduction to the Geographic Coordinate Database (3) Special Boundary Problems I (3)
Gilbert Jeans Laas (1382)	Gilbert Jeans Laas David Evans and Associates, Inc. 815 west north st bellingham, WA 98225 425-259-4099 E-mail: gjla@deainc.com	WA PLS - 42674	2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)
Erielle Lamb (1675)	Erielle Lamb 509 NW 45th Street Vancouver, WA 98660 E-mail: erielle.lamb@usda.gov	OR PLS - 89906 WA PLS - 20100531	2019 LSAW: PLSS Calculations & Case Studies (2) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Theodore G Lambert (1650)	Theodore G Lambert Lambert Consulting LLC	OR PLS - 2294 OR PE - 32146	Advanced Topics and Cases in Mineral Surveys (2) February 2018 Las Vegas CFedS Workshop (2)

	1011 Jerome Ave Astoria, OR 97103 503-710-8018 E-mail: lambert.five@gmail.com E-mail: lambertconsultingllc@gmail.com	WA PLS - 26254	Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) The Landslide Report (2)
Andrew Stephen Lammons (1830)	Andrew Stephen Lammons Lammons Land Surveying LLC 1950 S 8th St. W Missoula, MT 59801 406-830-6359 E-mail: Alammons87@gmail.com E-mail: Andrew@lammonslandsurveying.com	ID PLS - 18481 MT PLS - 50664	
Steven Lampen (1772)	Steven Lampen 220 Hoover Boulevard Holland, MI 49423 616-292-3908 E-mail: slampen@hollandengineering.com	IL PLS - 035.003124 IN PLS - LS20300010 MI PLS - 37279 MN PLS - 44074 ND PLS - LS-8515 OH PLS - PS.8176 PA PLS - SU075313 VA PLS - 0403003350 WI PLS - 2610-8 WV PLS - 2307	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
Tom Latimer (1077)	Tom Latimer Orion Surveys P.O. Box 15025 Fritz Creek, AK 99603 907-399-7028 E-mail: tominak@gmail.com E-mail: latimer@xyz.net	AK PLS - 10603	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jeremy Adam Lawson (1603)	Jeremy Adam Lawson 10047 Mozelle Lane Dardanelle, AR 72834 501-499-1859 E-mail: jeremy.lawson@craftontull.com	AR PLS - 1741 KS PLS - 1584 KY PLS - 4261 MO PLS - 2016000166 OK PLS - 1916	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Tussio 37 IBLA 135 (1)
Jared Allen Lay (1255)	Jared Allen Lay J Bar T Engineers LLC 1093 Helena Avenue Helena, MT 59601 406-449-1306 E-mail: jared@jbartengineers.com E-mail: jlayoftheland@gmail.com	ID PLS - L-16166 MT PLS - 17305	Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
Dennis W. Layton (1628)	Dennis W. Layton Heritage Surveying 1895 Village Center Circle Las Vegas, NV 89134 702-474-6277 E-mail: dlayton@hs4maps.com E-mail: dlayton@cox.net	AZ RLS - 39799 CA PLS - 8987 CO PLS - 38358 FL PLS - 7291 ID PLS - 15304 KY PLS - 4355 ND PLS - 7663	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3)

		NV PLS - 11829 NV Other - 1119 NY PLS - 50920 SD PLS - 11147 UT PLS - 8096911 WA PLS - 53031	Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
David C. Lee (1057)	David C. Lee Indian Health Service P.O. Box 323 Taylor, AZ 85939 307-939-3061 E-mail: pls9007@hotmail.com E-mail: david.lee@ihs.gov	AK PLS - 10610 AZ PLS - 70954 CO PLS - 38128 ID PLS - 10897 MT PLS - 16276 WY PLS - 9007	AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) CIM Quiz (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1) Working Group - Salt Lake City, Utah 2009 (1)
Jason Matthew Lee (1782)	Jason Matthew Lee Otter Tail Power 1334 Minnesota Ave E. Fergus Falls, MN 56537 218-770-8492 E-mail: jmlee@otpc.com	MN PLS - 48258 ND PLS - LS-10734 SD PLS - 12395	Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
Vernen Kalani Lee (1441)	Vernen Kalani Lee Merrick & Company 709 Bidwill Street Suite 200 Fairbanks, AK 99701 907-450-7617 E-mail: vern.lee@merrick.com	AK PLS - 13318 AZ RLS - 47302 CO PLS - 37998 KS PLS - 1536 MT PLS - 19211 ND PLS - 6929 NE PLS - 678 NV PLS - 19729 OR PLS - 85504 SD PLS - 10688 WA PLS - 48380	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Carey Paul Lege (1723)	Carey Paul Lege UniversalPegasus International 305 S. Church St. Dayton, TX 77535 E-mail: carey.lege@hii-upi.com	KY PLS - 4061 OK PLS - 1899 SD Other - 12156	Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) William D. Brown 137 IBLA 31 (1)
Jason D Levanen (1383)	Jason D Levanen Arrow Survey Group, Inc. 27 Home Ranch Circle Sheridan, WY 82801 307-751-7543 E-mail: jason.levanen@arrowsgi.com	CO PLS - 38159 MI PLS - 49299 MT PLS - 17281 ND PLS - 6548 NE PLS - 770 NM PLS - 23202 SD PLS - 9868 UT PLS - 9272125 WY PLS - 10287	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)

			The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Nancy H. Lewis (1218)	Nancy H. Lewis 4910 Emerson Ave. S. Minneapolis, MN 55419 612-396-1660 E-mail: lewnacy@gmail.com	MN PLS - 46170	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Scott H. Lewis (1335)	Scott H. Lewis Granite Engineering & Surveying LLC 741 North Day Street Powell, WY 82435 307-754-7170 E-mail: Scott.Lewis@Granite-ES.com	MT Other - 13050 PELS WY Other - 6207 PELS	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Steven G. Lewis (1106)	Steven G. Lewis Olsson 702 Main Joplin, MO 64801 417-781-0643 E-mail: slewis@olsson.com	AR PLS - 1571 KS PLS - 1338 MO PLS - 2514 OK PLS - 1464	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) William D. Brown 137 IBLA 31 (1)
John Libby (1578)	John Libby White Surveying Company 9936 E 55th Place Tulsa, OK 74146 918-663-6924 E-mail: john@whitesurvey.com E-mail: john_libby@sbcglobal.net	OK PLS - 1806 TX RLS - 6120	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jason A. Lightbown (1677)	Jason A. Lightbown DOI BLM 39733 Cassidy CT Sandy, OR 97055	OR PLS - 90545	APLS-CLSA-NALS 2020 Conference (2) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1)

	E-mail: jlightbown@blm.gov E-mail: jaybown@hotmail.com		LSAW Fall Conference CFedS Presenter, Vancouver WA (2) Mineral Surveys (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Marshall Wayne Lindeen (1219)	Marshall Wayne Lindeen 8301 Hood Mesa Trail Farmington, NM 87402 505-270-0161 E-mail: mlindeen@ufsnm.com	CO PLS - 27271 NM PLS - 17078 UT PLS - 7217687 WY PLS - 6640	2015 New Mexico Conference - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Kevin F. Lindow (1524)	Kevin F. Lindow Lindow Surveying & Mapping, LLC 1301 Park Ave S. PO Box 448 Park Rapids, MN 56470 218-237-0065 E-mail: kevin@lindowssurveying.com	MN PLS - 47924	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Nathan R. Link (1831)	Nathan R. Link WA. State Dept. of Natural Resources 4361 J Hwy. 25 N. Northport, WA 99157 509-690-0081 E-mail: nrlink85@gmail.com E-mail: nate.link@dnr.wa.gov	WA PLS - 45412	
Preston A Liptack (1703)	Preston A Liptack Mi-Tech Services, Inc. 5707 Schofield Avenue Weston, WI 54476 E-mail: pliptack@mi-tech.us E-mail: paliptack@gmail.com	MN PLS - 53602 WI PLS - 3063-8	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Vernon Charles Little (1147)	Vernon Charles Little P.O. Box 511 Ben Lomond, CA 95005 831-278-0479 E-mail: benlomondvem88@gmail.com	AZ RLS - 44953 CA PLS - 8701 NV PLS - 13930 UT PLS - 4892453-2201 WY PLS - 13343	2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9)

			<p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Jason Lloyd (1818)	<p>Jason Lloyd</p> <p>22828 Grand View Drive</p> <p>Poteau, OK 74953</p> <p>E-mail: jason@lloydlandsurveying.com</p> <p>E-mail: avoidthelloyd@hotmail.com</p>	OK PLS - 1971	
Vincent Logan (1716)	<p>Vincent Logan</p> <p>Port of Portland</p> <p>7200 NE Airport Way</p> <p>Portland, OR 97218</p> <p>503-415-6392</p> <p>E-mail: vincent.logan@portofportland.com</p>	<p>CA PLS - 8015</p> <p>CO PLS - 38218</p> <p>ID PLS - 11950</p> <p>OR PLS - 76712</p> <p>WA PLS - 43615</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Michael E. Long (1566)	<p>Michael E. Long</p> <p>Wood Rodgers, Inc.</p> <p>3301 C Street, Bldg 100-B</p> <p>Sacramento, CA 95816</p> <p>916-326-5894</p> <p>E-mail: mlong@woodrogers.com</p>	<p>AZ RLS - 29880</p> <p>CA PLS - 6815</p> <p>ID PLS - 12639</p> <p>NV PLS - 11186</p> <p>OR PLS - 02884</p> <p>UT PLS - 351953-2201</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Kurt Luebke (1006)	<p>Kurt Luebke</p> <p>DJ&A, P.C.</p> <p>2000 Maple Street</p> <p>Missoula, MT 59808</p> <p>406-721-4320</p> <p>E-mail: kurtl@djanda.com</p>	<p>AK PLS - 13018</p> <p>CO PLS - 38489</p> <p>ID PLS - 11748</p> <p>MN PLS - 51730</p> <p>MT PLS - 13237</p> <p>ND PLS - 9287</p> <p>NM PLS - 25337</p> <p>OK PLS - 1954</p> <p>OR PLS - 70938</p> <p>SD RLS - 11541</p> <p>UT PLS - 7369533-2201</p> <p>WA PLS - 44638</p> <p>WY PLS - 14546</p>	<p>2015-Idaho Hillstrom presentation (2)</p> <p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>CIM Quiz (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Steven A. Lund (1107)	<p>Steven A. Lund</p> <p>Northern Engineering</p> <p>820 8th Street</p> <p>Greeley, CO 80550</p>	<p>CO PLS - 34995</p> <p>NE RLS - 685</p> <p>SD RLS - 6252</p>	<p>2016 Discrepancies in the Official Record (2)</p> <p>2018 Denver,CO: Resurveying an Entire GLO Township (2)</p> <p>2019 Rocky Mountain Surveyors Summit (2)</p> <p>Deizell 158 IBLA 238 (1)</p>

	<p>970-488-1113 E-mail: stevel@northernengineering.com E-mail: scanlund@comcast.net</p>		<p>Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Bradley Ryan Lymanrover (1337)	<p>Bradley Ryan Lymanrover 55 Storm King Rd Port Angeles, WA 98363 360-457-5961 E-mail: brlymanrover@gmail.com</p>	WA PLS - 28071	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Tallak Daniel Maakestad (1108)	<p>Tallak Daniel Maakestad HDL Engineering Consultants, LLC 17620 Pioneer Drive Eagle River, AK 99577 907-529-4324 E-mail: tmaakestad@hdlalaska.com E-mail: tuckmaakestad@yahoo.com</p>	<p>AK PLS - 9235 AR PLS - 1238 AZ PLS - 13012 CA PLS - L 6270 OR PLS - 2429</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Paul H Mabry (1109)	<p>Paul H Mabry 3351 Fernside Blvd Alameda, CA 94501 253-678-2229 E-mail: paulhmabry@gmail.com</p>	<p>CA PLS - 8797 FL PLS - 6374 ID PLS - 11830 OR PLS - 77368 WA PLS - 41036</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) The PLSS Datum and the Local Surveyor (1) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1) Working Group - San Diego 2011 (1)</p>
Leland A. MacDonald (1220)	<p>Leland A. MacDonald Leland A. MacDonald & Associates, LLC 3765 Riverside Drive</p>	OR PLS - 53226	<p>2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) Accretions in the Public Land Survey System (1)</p>

	McMinnville, OR 97128 503-472-7904 E-mail: lee@macdonaldsurveying.com		Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Bruce A. MacLearnsberry (1443)	Bruce A. MacLearnsberry MacLearnsberry, Inc. 1100 NW Thompson Road Poulsbo, WA 98370 206-842-5514 E-mail: bruce@sealandsurvey.com	ID PLS - 14821 WA PLS - 32439	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)
Jonathan D Maddox (1789)	Jonathan D Maddox 803 Bobwhite Court Lincoln, CA 95648 503-812-7593 E-mail: maddoxjond@gmail.com	CA PLS - 9257 WA PLS - 57240	2019 CLSA/NALS Private-Federal Boundary (2) Non-Rectangular Surveys (9)
Jason E. Main (1748)	Jason E. Main Ackerman Surveying & Associates, Inc. 1907 17th Street Southeast Minot, ND 58701 701-857-9160 E-mail: jason.main@ackermansurveying.com	ID PLS - L-18233 IN PLS - LS20900184 MN PLS - 54370 MT PLS - PEL-LS-LIC-40988 ND PLS - LS-8134 SD PLS - 12784	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Melvin Lyle March (1526)	Melvin Lyle March March Surveying PO Box 572 304 Shavano Circle Florissant, CO 80816 719-748-3654 E-mail: marchsurveying@aol.com	CO PLS - 15672	February 2021 RMSS Virtual Conference Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
George Yuri Marchenko (1248)	George Yuri Marchenko Wallace Group 612 Clarion Court San Luis Obispo, CA 93401 805-544-4011 E-mail: georgem@wallacegroup.us E-mail: gvcm555@yahoo.com	CA PLS - 6964	2018 Western Regional Survey Conference_Workshop (2) 2019 CLSA/NALS Private-Federal Boundary (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)

			<p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Steven Richard Marien (1444)	<p>Steven Richard Marien The Mohegan Tribe 13 Crow Hill Road Uncasville, CT 06382</p> <p>860-862-6217 E-mail: smarien@moheganmail.com E-mail: smarien1@gmail.com</p>	CT RLS - 70125	<p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Mason Kent Marker (1604)	<p>Mason Kent Marker</p> <p>Duryea and Associates</p> <p>13580 Spring Lake Road</p> <p>Klamath Falls, OR 97603</p> <p>541-591-9157 E-mail: masonmarker@gmail.com</p>	OR PLS - 51455PLS	<p>2013 OIT Land Surveyor's Workshop - Delzell (1)</p> <p>2013 OIT Land Surveyor's Workshop - Tussio (1)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Anthony J Martin (1724)	<p>Anthony J Martin</p> <p>Russell Surveyors & Associates Inc. 6820 S. Highway 17 Alamosa, CO 81101 719-587-3630x1104 E-mail: tonymartin@bresnan.net</p>	CO PLS - 38317	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2)</p> <p>2019 Rocky Mountain Surveyors Summit (2)</p> <p>2020_Colorado RMSS Workshop (2)</p> <p>2020_Colorado RMSS Workshop (TEST) (0)</p> <p>Discrepancies in the Official Record (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Carol Anne Martin (1494)	<p>Carol Anne Martin</p> <p>5617 Tattersall Terrace</p> <p>Sugar Hill, GA 30518</p> <p>678-910-5703 E-mail: mistral97@gmail.com</p>	GA PLS - 2544	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Kevin James Martin (1725)	<p>Kevin James Martin Bartlett & West, Inc.</p> <p>3456 E. Century Ave. Bismarck, ND 58503</p> <p>E-mail: kevin.martin@bartwest.com</p>	<p>CA PLS - 8345</p> <p>IA PLS - P24804</p> <p>MN PLS - 51382</p> <p>MT PLS - 24751</p> <p>ND PLS - LS-7062</p> <p>SD PLS - 11621</p>	<p>Discrepancies in the Official Record (2)</p> <p>NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Tussio 37 IBLA 135 (1)</p>

Steven J. Mathis (1567)	<p>Steven J. Mathis</p> <p>Robert S. Shotts Inc.</p> <p>267 East Third Street PO Box 83 Lebanon, MO 65536</p> <p>417-588-7877 E-mail: sjmathis@me.com E-mail: stevenjosephmathis@gmail.com</p>	<p>AR PLS - 1799</p> <p>MO PLS - 2005019224</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Craig Kenichi Matsueda (1111)	<p>Craig Kenichi Matsueda</p> <p>Wallace Morris Kline Surveying</p> <p>5740 SOUTH ARVILLE STREET #206</p> <p>Las Vegas , NV 89118</p> <p>702-466-4083</p> <p>E-mail: ckm56monkey@yahoo.com</p> <p>E-mail: cmatsueda@wmksurveying.com</p>	<p>CA PLS - 6820</p> <p>NV PLS - 17022</p>	<p>2018 Western Regional Survey Conference_Workshop (2)</p> <p>2019 CLSA/NALS Private-Federal Boundary (2)</p> <p>2021 RMSS Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Matthew Brian Mayberry (1726)	<p>Matthew Brian Mayberry</p> <p>P.O. Box 3457</p> <p>9177 N. Hess street Hayden, ID 83835 208-772-2745</p> <p>E-mail: mmayberry@ats-1.com</p>	<p>AK PLS - 13017</p> <p>ID PLS - 8962</p> <p>MT PLS - 13770</p> <p>ND PLS - 7973</p> <p>WA PLS - 38036</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
John McBride (1736)	<p>John McBride</p> <p>P.O. Box 95 28097 Dewey Rd. Edgemont, SD 57735 605-662-6344</p> <p>E-mail: andersenengineersinc@goldenwest.net</p>	<p>NE RLS - 661</p> <p>SD RLS - 5906</p>	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p>
Earnest Marion McCarty (1709)	<p>Earnest Marion McCarty</p> <p>US Army Corps of Engineers 502 Eighth Street Huntington, WV 25701</p> <p>304-399-5957 E-mail: earnest.m.mccarty@usace.army.mil E-mail: e.m.mccarty.jr@gmail.com</p>	<p>KY PLS - 3666</p> <p>OH PLS - 8443</p> <p>PA PLS - SU057606</p> <p>TN PLS - 2140</p> <p>WV PLS - 1001</p>	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
John David McCauley (1339)	<p>John David McCauley</p> <p>136 SE 5th ST</p> <p>TROUTDALE, OR 97060</p> <p>971-303-1797</p> <p>E-mail: jmccaule@blm.gov</p>	<p>CO PLS - 28278</p> <p>OR PLS - 2728</p> <p>WA PLS - 42693</p>	<p>2013 OIT Land Surveyor's Workshop - Delzell (1)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p>

	E-mail: tampicoelk368@gmail.com		<p>Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) SME Review IBLA Cases (3) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
William W. McClintock (1155)	<p>William W. McClintock</p> <p>McClintock Land Associates, Inc.</p> <p>16942 N. Eagle River Loop Rd Eagle River, AK 99577</p> <p>907-694-4499 E-mail: bmccclintock@mappingalaska.com</p>	AK PLS - 5480	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Steven Craig McCormack (1737)	<p>Steven Craig McCormack</p> <p>121 River Oaks Drive Unit B</p> <p>Durango, CO 81303</p> <p>E-mail: scm@caddisaerial.com</p> <p>E-mail: stevemccormackhome@gmail.com</p>	<p>AZ RLS - 49927</p> <p>CO PLS - 22574</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Deizell 158 IBLA 238 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The Landslide Report (2)</p>
Christopher J. McCrimmon (1222)	<p>Christopher J. McCrimmon</p> <p>225 E. Main St.</p> <p>P.O. Box 408 Marion, MI 49665 231-743-3000</p> <p>E-mail: cmccrimmon1cm@aol.com</p>	MI PLS - 47962	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Deizell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Craig R McCullough (1765)	<p>Craig R McCullough</p> <p>4 Rivers Surveying Inc. 1310 Shady Lane Emmett, ID 83617 855-477-6901 E-mail: cmccullough@4rivers-surveying.com</p>	<p>AK PLS - AELL14827</p> <p>ID PLS - 6901 NM PLS - 23109 NV PLS - 020711 OR PLS - 69260 WY PLS - 12314</p>	<p>Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3)</p>
Timothy John McDaniel (1446)	<p>Timothy John McDaniel Apex Engineering</p> <p>3019 North 21st Street</p> <p>Tacoma, WA 98406 253-948-8995 E-mail: man_ambrym@yahoo.com</p>	<p>ID PLS - 15812 OR PLS - 92094</p> <p>WA PLS - 45792</p>	<p>2014 LSAW Conference Deizell (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2)</p>

	E-mail: mcdaniel@apexengineering.net		<p>Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Christopher Patrick McDonald (1162)	<p>Christopher Patrick McDonald</p> <p>22301 East Vallejo Street Queen Creek, AZ 85142</p> <p>E-mail: rls45547@earthlink.net E-mail: cpmcdona@blm.gov</p>	AZ RLS - 45547	<p>Boundary Evidence Standards Documents (1)</p> <p>Discrepancies in the Official Record (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) Tussio 37 IBLA 135 (1)</p>
Kevin Bennett McGuire (1704)	<p>Kevin Bennett McGuire</p> <p>PO Box 1891 Post Falls, ID 83877</p> <p>E-mail: mcgukevi@isu.edu</p>	<p>AZ RLS - 60032</p> <p>CO PLS - 38490 ID PLS - 17263 ND PLS - LS-10816 WA PLS - 54100</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Robert, Jr. Lee Meadows (1783)	<p>Robert, Jr. Lee Meadows Matrix Design Group</p> <p>2695 Sunbird Drive Colorado Springs, CO 80918 723-494-3486 E-mail: bob_meadows@matrixdesigngroup.com E-mail: rmeadows75@gmail.com</p>	<p>CO PLS - 34977 IN PLS - 21000229</p> <p>KS PLS - 1551 WI PLS - 1801</p>	<p>2020_Colorado RMSS Workshop (2) Introduction to the Geographic Coordinate Database (3) Special Boundary Problems I (3)</p>
Karen F Meckel (1496)	<p>Karen F Meckel kfmconsulting, llc 1191 Granite Springs Rd, Tr 2</p> <p>Cheyenne, WY 82009 307-220-7941</p> <p>E-mail: kfmconsulting@gmail.com E-mail: karmec1@yahoo.com</p>	<p>CO PLS - 38001 NM PLS - 18054</p>	<p>2015 New Mexico Conference - Hillstrom (2) 2016 Discrepancies in the Official Record (2) 2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Mineral Surveys (2) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Michael Robert Merritt (1727)	<p>Michael Robert Merritt</p> <p>Terrane</p> <p>763 Vesper Way</p> <p>Camano Island, WA 98282 530-949-4343</p> <p>E-mail: mikem@terrane.net</p>	<p>ID PLS - L-18160</p> <p>NV PLS - 20784</p> <p>OR PLS - 85254</p> <p>WA PLS - 48761</p>	<p>2019 LSAW: PLSS Calculations & Case Studies (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) Identification & Subdivision of Fractional Section (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2)</p>

Eric Daniel Meyer (1579)	Eric Daniel Meyer Meyer Land Surveying 45246 hwy 44 Parker, SD 57053 605-310-9401 E-mail: sdbirdog@yahoo.com	IA PLS - 21003 MN PLS - 48998 ND PLS - 6880 NE PLS - 699 SD PLS - 9592	2014 South Dakota SPLS Presentation - Hillstrom (2) 2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2)
Brian Robert Meyers (1651)	Brian Robert Meyers R & M Consultants, Inc. 2421 Nancy cir Anchorage, AK 99516 907-250-6347 E-mail: bmeyers@rmconsult.com E-mail: meyers_99@yahoo.com	AK PLS - 13008	Discrepancies in the Official Record (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Dale P Meyers (1497)	Dale P Meyers Ada County Development Services 200 W. Front St. BOISE, ID 83702 208-861-4722 E-mail: dmeyers@adaweb.net	ID PLS - 13553	2015-Idaho Hillstrom presentation (2) 2019 LSAA: PLSS Calculations & Case Studies (2) Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Mineral Surveys (2) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Kelly Lee Miller (1710)	Kelly Lee Miller EAGLE COUNTY GOVERNMENT P.O. Box 850 Eagle, CO 81631 970-328-3566 E-mail: kelly.miller@eaglecounty.us	CO PLS - 37958	2016 Discrepancies in the Official Record (2) 2018 Denver, CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) Avulsions in the Public Land Survey System (1) February 2021 RMSS Virtual Conference Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3)
David Joseph Moksi (1414)	David Joseph Moksi 1927 Buckingham Lane Petaluma, CA 94954 253-314-2815 E-mail: davidj2ski@gmail.com	WA PLS - 40019	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Brenda G. Moore (1010)	Brenda G. Moore	CO PLS - 33647	Accretions in the Public Land Survey System (1)

	<p>P.O.Box 133 Buffalo Gap, SD 57722 701-609-9594 E-mail: brendagmoore@gmail.com E-mail: brenda.moore@energiekontor.com</p>	<p>ID PLS - 17041 MT PLS - 16036 ND PLS - 8066 SD RLS - 10019</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Matthew D. Morris (1342)	<p>Matthew D. Morris Morris Land Surveys, P.L.L.C. P.O. Box 513 Choteau, MT 59422 E-mail: mattm@morrislandsurveys.com</p>	<p>ID PLS - 14391 MT PLS - 16968 WY PLS - 14680</p>	<p>2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) 7 States Western Virtual Conference - 3/29/21 (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Chad Ryan Moser (1591)	<p>Chad Ryan Moser Electrical Consultants Inc. 3658 W. 5350 S. Roy, UT 84067 801-776-3452 E-mail: chadmoser@gmail.com</p>	<p>AZ PLS - 59125 CO PLS - 0038546 ID PLS - 13613 MO PLS - 2012000097 ND PLS - 6830 OR PLS - 83494 UT PLS - 350503</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) UCLS_St. George, UT 2/20/2020 Workshop (2) Utah 2017 "Discrepancies in the Official Record" (2)</p>
Richard L. Mulliken (1798)	<p>Richard L. Mulliken Pettigrew & Associates 100 E. Navajo Drive Suite 100 Hobbs, NM 88240 970-433-3546 E-mail: rmulliken@pettigrew.us</p>	<p>CO PLS - 33201 NM PLS - 16873 UT PLS - 9859024-2201</p>	<p>February 2021 RMSS Virtual Conference Workshop (2) Non-Rectangular Surveys (9)</p>
Timothy Lane Mullikin (1114)	<p>Timothy Lane Mullikin Dryden & LaRue 57722 Icy Bay Dr., Apt. 2567 Homer, AK 99603</p>	<p>AK PLS - 7615 CA PLS - 8362 NV PLS - 18135</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1)</p>

	<p>907-841-3371 E-mail: tmullikin@drydenlarue.com E-mail: mullikinak@gmail.com</p>		<p>Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Michael W Nadeau (1115)	<p>Michael W Nadeau Meridian Engineering, Inc. 1628 W 11010 S Suite 102 South Jordan, UT 84095 801-569-1315 E-mail: mnadeau@merid-eng.com E-mail: mwnadeau@gmail.com</p>	<p>CO PLS - 38774 ID PLS - 15877 NV PLS - 20267 UT PLS - 4938744</p>	<p>2018 Western Regional Survey Conference Workshop (2) 2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) Utah 2017 "Discrepancies in the Official Record" (2) William D. Brown 137 IBLA 31 (1) Working Group - Salt Lake City, Utah 2009 (1)</p>
Gregg Neitsch (1116)	<p>Gregg Neitsch North State Land Surveying 1511 Kylynn Court Mt. Shasta, CA 96067 530-340-3991 E-mail: gregg@nslsurvey.com E-mail: nsurvey@4fast.net</p>	<p>CA PLS - 7991 ID PLS - 18482 NV PLS - 22065 OR PLS - 77662</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Roger Dale Nelson (1343)	<p>Roger Dale Nelson Bohannon Huston Inc. 2422 Elkhorn Ranch Street Parker, CO 80138 303-589-1875 E-mail: RNelson@bhinc.com</p>	<p>CO PLS - 33200 FL PLS - LS6865 ID PLS - 12401 KS PLS - LS-1434 LA PLS - 4887 MT PLS - 17510 NC PLS - L-4273 ND PLS - LS-6217 NE PLS - LS-701 OK PLS - 1895 SD RLS - 9424 WY PLS - LS 11464</p>	<p>2016 Discrepancies in the Official Record (2) 2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) Boundary Evidence Standards Documents (1)</p> <p>Discrepancies in the Official Record (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p>
Gerald Matt Nichols (1691)	<p>Gerald Matt Nichols</p>	<p>CO PLS - 38026</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2)</p>

	<p>Survey Systems</p> <p>27204 Armadillo Way</p> <p>Evergreen, CO 80439</p> <p>303-679-8122</p> <p>E-mail: mnichols@surveysystems.net</p> <p>E-mail: knichols@surveysystems.net</p>	<p>WA PLS - 54472</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>February 2021 RMSS Virtual Conference Workshop (2)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p>
William L. Nielson (1199)	<p>William L. Nielson</p> <p>William Nielson, Land Surveyor</p> <p>PO BOX 9359</p> <p>Ketchikan, AK 99901</p> <p>907-821-8205</p> <p>E-mail: wnielson@kpunet.net</p>	<p>AK PLS - 9685</p> <p>CA PLS - 5806</p> <p>CO PLS - 31553</p> <p>HI PLS - 14281</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Mineral Surveys (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Aaron Norby (1304)	<p>Aaron Norby</p> <p>Kadmas Lee & Jackson</p> <p>4585 Coleman Street</p> <p>Bismarck, ND 58503</p> <p>701-355-8721</p> <p>E-mail: aaron.norby@kljeng.com</p>	<p>MN PLS - 46162</p> <p>MT PLS - 18578</p> <p>ND PLS - 5589</p> <p>SD PLS - 8943</p> <p>TX RLS - 5077</p> <p>WY PLS - 12557</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
James T Nordlund (1799)	<p>James T Nordlund</p> <p>Nordlund and Associates, Inc</p> <p>813 E Ludington Ave</p> <p>Ludington, MI 49431</p> <p>231-843-3485</p> <p>E-mail: jimandkay3@charter.net</p> <p>E-mail: jimnr@nordlundandassociates.com</p>	<p>MI RLS - 16345</p> <p>MI PE - 16345</p>	<p>Hillstrom 180 IBLA 388 (2)</p> <p>Standards for Boundary Evidence (3)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Scott Clement North (1385)	<p>Scott Clement North</p> <p>Merrick</p> <p>3575 Koger Blvd. Suite 235</p> <p>Duluth, GA 30096</p> <p>404-416-3675</p> <p>E-mail: scott.north@merrick.com</p> <p>E-mail: scott.north@gmail.com</p>	<p>AL PLS - 31340</p> <p>AR PLS - 1778</p> <p>FL PLS - LS7046</p> <p>GA RLS - 3176</p> <p>KY PLS - 4143</p> <p>LA PLS - 5098</p> <p>MS PLS - 3208</p> <p>NC PLS - L-5038</p> <p>SC PLS - 33461</p> <p>TN PLS - 2948</p> <p>TX Other - 6556</p> <p>VA RLS - 3102</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p>

			<p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Gavin M Oak (1246)	<p>Gavin M Oak</p> <p>A G O Land Surveying, LLC</p> <p>1015 NE Hostmark Street</p> <p>#103 Poulsbo, WA 98370 360-779-4299 E-mail: gavin@agols.com</p>	<p>WA PLS - 45168</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Jason W. Oberg (1568)	<p>Jason W. Oberg Blattner Energy, Inc</p> <p>392 County Road 50</p> <p>Avon, MN 56310 320-248-8198 E-mail: jasono@blattnerenergy.com</p>	<p>AR PE - 17670 AZ PE - 64190</p> <p>CA PE - 82983</p> <p>CO PE - 50784 GA PE - 39840 HI PLS - 12942</p> <p>HI PE - 15582 IA PE - 24086 KS PLS - 1506</p> <p>KS PE - 24639 MA PE - 50729 ME PLS - 2426</p> <p>MN PLS - 45872</p> <p>MN PE - 45872</p> <p>MN Other - 1597826 (PMP) MS PE - 25339 ND PE - 27064 NM PE - 22687 NV PLS - 19641 NV PE - 19641 OK PE - 28313 TX PE - 119400 UT PE - 10202470-2202 VA PE - 0402058385 WV PE - 24557</p>	<p>2014 MSPS Winter Seminar - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Gregory Allen Obrigewitch (1652)	<p>Gregory Allen Obrigewitch</p> <p>1513 Prairie Hawk Dr.</p> <p>Bismarck, ND 58503</p> <p>E-mail: greg.obrigewitch@nacoal.com</p>	<p>MT PLS - 15848</p> <p>ND PLS - 4114</p> <p>SD RLS - 7628</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Quentin Obrigewitsch (1344)	<p>Quentin Obrigewitsch</p> <p>Kadmas Lee & Jackson</p> <p>1463 I-94 Business Loop East</p>	<p>MT PLS - 21102</p> <p>ND PLS - LS-5999</p> <p>SD RLS - 9664</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1)</p>

	Dickinson, ND 58601 701-483-1284 E-mail: quentin.obrigewitsch@kljeng.com		Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Adadewa Okutu (1766)	Adadewa Okutu Seminole Tribe of Florida adadewa@yahoo.com 6300 Stirling Road Hollywood, FL 33024 954-258-3761 E-mail: adadewa@yahoo.com E-mail: adadewaokutu@semtribe.com	FL Other - 6912	Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3)
Amy Suzanne Orange-Posma (1616)	Amy Suzanne Orange-Posma State of Alaska 7731 Island Dr Anchorage, AK 99504 907-269-8524 E-mail: amy.orange-posma@alaska.gov	AK PLS - 12647	2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Kurt Orban (1605)	Kurt Orban WMO Surveying 269 Primrose Way Shoshone, ID 83352 775-385-3382 E-mail: kurtorban@yahoo.com	AZ RLS - 48864 CO PLS - 38221 ID PLS - 16858 ND PLS - 8135 NV PLS - 17828 SD RLS - 11878 UT PLS - 6540347-2201	7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1) UCLS_St. George, UT 2/20/2020 Workshop (2)
Andrew Orosco Jr (1612)	Andrew Orosco Jr San Pasqual Band of Mission Indians 16400 Kumeyaay Way Valley Center, CA 92082 760-445-8285 E-mail: andrewo@sanpasqualtribe.org	CA PLS - 9122	February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
Douglas Haig Ort (1306)	Douglas Haig Ort Wilson & Company 990 Broadway Suite 220 Denver, CO 80209 720-235-9593 E-mail: dhortii@wilsonco.com E-mail: doug6815@hotmail.com	CO PLS - 37066 ID PLS - 17666 MT PLS - 29330 ND PLS - 7858 UT PLS - 11191332 WY PLS - 13682	2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) Accretions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Stoddard Jacobsen and Robert C. Downer (2)

			The 2009 Manual of Surveying Instructions (2)
Ethan James Ostby (1819)	Ethan James Ostby NECI PO Box 46 Bridger, MT 59014 406-702-0690 E-mail: ethanostby@yahoo.com E-mail: ethan_ostby@neciusa.com	MT PLS - 57155	7 States Western Virtual Conference - 3/29/21 (2)
Jacobo J. Pacheco (1117)	Jacobo J. Pacheco Colliers Engineering & Design Inc 2703 Broadbent Pkwy NE Ste B Albuquerque, NM 87107 505-433-6383 E-mail: jacobo.pacheco@colliersengineering.com	NM PLS - 17822	Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
David Lee Page (1728)	David Lee Page Page Surveying & Associates P.O. Box 1867 124 S. 8th Ave Durant, OK 74702 580-239-0176 E-mail: david@pagesurveying.net	OK PLS - 1566	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Standards for Boundary Evidence (3)
Kirk J Pangus (1173)	Kirk J Pangus HILGARTWILSON, LLC 2141 E Highland Ave Suite 250 Phoenix, AZ 85016 602-490-0535 E-mail: kpangus@hilgartwilson.com E-mail: kjpangus@gmail.com	AZ PLS - 19344 CA PLS - 5731 CO PLS - 38222 ID PLS - 15630 NV PLS - 10844 OK PLS - 1749 TX RLS - 6282 UT PLS - 7797201-2201	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Renee B Parent (1835)	Renee B Parent 690 26 1/2 Road Grand Junction, CO 81506 970-631-2300 E-mail: reneep@gjcity.org	CO PLS - 38266	
Steven Douglas Parker (1738)	Steven Douglas Parker NV5 14205 Westchester Dr Colorado Springs, CO 80921 719-641-3355 E-mail: land_surveyist@hotmail.com E-mail: sparker@f-w.com	CO PLS - 38053 KS PLS - 1631	2018 Denver, CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) The 2009 Manual of Surveying Instructions (2)
John Steven Parrish (1044)	John Steven Parrish Private Surveyor 7589 Lighthouse Ln	AZ PLS - 15575 CA PLS - 5050 CO PLS - 38398	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Boundary Evidence Standards Documents (1)

	Reno, NV 89511-1023 775-224-3122 E-mail: surveyorx10@gmail.com	ID PLS - 903 ND PLS - 10050 NM PLS - 8943 NV PLS - 9475 SD PLS - 12581 UT PLS - 149053-2201 WY PLS - 4526	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Benjamin Ryan Pastor (1836)	Benjamin Ryan Pastor ESM 33400 8th Avenue South Suite 205 Federal Way, WA 98003 206-643-0160 E-mail: ben.pastor@esmcivil.com	WA PLS - 54153	
Thomas W. Patrick (1386)	Thomas W. Patrick Community Sciences Corp PO Box 1328 Corrales, NM 87048 505-897-0000x118 E-mail: tompatrick@communitysciences.com	AZ RLS - 37420 CO PLS - 37986 NM PLS - 12651 OR PLS - 2466	2015 New Mexico Conference - Hillstrom (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Peter Elliott Paulus (1800)	Peter Elliott Paulus 945 Schillinger Road S Apt. 4903 Mobile, AL 36695 251-304-4929 E-mail: coachpete.writeshistory.42@gmail.com E-mail: paulusp223@gmail.com	CO PLS - 38318	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1)
James L Payne (1641)	James L Payne Drennan Surveying Services 751 W Jackson St. Marshfield, MO 65706 417-766-9099 E-mail: jlpayne@gmail.com	AR PLS - 1698 KS PLS - 1641 MO PLS - 2008000727 NE RLS - 806 OK PLS - 1866	Delzell 158 IBLA 238 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Randall Richard Payne (1629)	Randall Richard Payne White Hawk Engineering & Design, LLC 2204 S. Eastern Avenue Moore, OK 73160 405-627-4026 E-mail: rpayne@whitehawkmail.com E-mail: okpls1811@gmail.com	OK PLS - 1811	Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Karl L Pearson (1188)	Karl L Pearson Kiewit Infrastructure Co. 1541 County Road 16560 Deport, TX 75435	AL PLS - 38984 AZ RLS - 35832 CO PLS - 38399 ID PLS - 13688	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2)

	956-298-3092 E-mail: karl.pearson@kiewit.com	KY PLS - 4033	Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Timothy Robert Pecha (1711)	Timothy Robert Pecha BDK Engineering, LLC 1105 Koala Ave Omak, WA 98841 509-826-2800 E-mail: Tim@bdk-engineering.com	CA PE - C44901 WA PLS - 33096 WA PE - 33096	2021 RMSS Conference (2) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Parneli J. Perkins (1041)	Parneli J. Perkins Vertical Surveying Inc. 65855 61st Street Bend, OR 97701 541-388-4472 E-mail: pperkins@verticalsurveying.com	OR PLS - 2699 OR Other - CWRE 442	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Christopher Drew Pesnell (1448)	Christopher Drew Pesnell Maptech, Inc. 3181 Greenfield Road Jackson, MS 39208 601-664-1666 E-mail: cdpesnell@maptech-survey.com	AL PLS - 38870 AR PLS - 1643 GA PLS - 3456 KY PLS - 4009 MS PLS - 3021 OK PLS - 1728 TN RLS - 3015	Discrepancies in the Official Record (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Brian M. Peterson (1544)	Brian M. Peterson Peterson & Associates 32081 Henkle Way Philomath, OR 97370 541-602-0553 E-mail: pasurveying@peak.org	OR PLS - 60065	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The Landslide Report (2)
Lloyd Eldon Pew (1416)	Lloyd Eldon Pew Pew Surveying, LLC	AZ RLS - 33866	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1)

	<p>P.O.Box 18211 Fountain Hills, AZ 85269 480-239-1807</p> <p>E-mail: lpew@pew-ls.com</p>		<p>Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
D. Scott Phillips (1569)	<p>D. Scott Phillips</p> <p>Phillips Engineering and Land Surveying, LLC</p> <p>2752 Point Drive Monroe, LA 71201 318-340-6204</p> <p>E-mail: dscottphillips@msn.com</p>	<p>AK RLS - 13842</p> <p>AR PLS - 1586</p> <p>FL RLS - 6909 LA PLS - 4912 MS PLS - 3053</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Eric Phillips (1592)	<p>Eric Phillips</p> <p>10309 N Atwater St</p> <p>Hayden, ID 83835</p> <p>E-mail: ephilang2@gmail.com E-mail: eric.b.phillips@usda.gov</p>	<p>CA PLS - 8959</p> <p>ID PLS - 18641</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Michael Anthony Picha (1692)	<p>Michael Anthony Picha</p> <p>T2 Utility Engineers</p> <p>1812 Furness Street Maplewood, MN 55109</p> <p>612-214-3153 E-mail: pichaam@gmail.com E-mail: michael.picha@t2ue.com</p>	<p>MN PLS - 51712 OH PLS - 8745</p> <p>WI RLS - 3056-8</p>	<p>2018 Minneapolis - Discrepancies (2) Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) February 2021 RMSS Virtual Conference Workshop (2) Hillstrom 180 IBLA 388 (2) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Emily K. Pierce (1607)	<p>Emily K. Pierce</p> <p>W6454 Robin Lane Tomahawk, WI 54487 715-544-8033 E-mail: emerdoodle@yahoo.com E-mail: epierce@berntsen.com</p>	<p>WI RLS - 2728</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
James Jetter Pittman (1729)	<p>James Jetter Pittman</p> <p>U.S. Fish and Wildlife Service 2183 Duck Cove Road</p>	<p>AL PLS - 40337</p> <p>GA RLS - LS003392 KY PLS - 4385</p>	<p>Accretions in the Public Land Survey System (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3)</p>

	Camden, SC 29020 803-310-3127 E-mail: jetter3246@gmail.com E-mail: james_pittman@fws.gov	NC PLS - L-3341 SC PLS - 14815 TN RLS - 3258	Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Michael Dennis Pniewski (1417)	Michael Dennis Pniewski Lucas County Engineer's Office 1049 S. McCord Rd Holland, OH 43528 419-213-2860 E-mail: mdpniewski@yahoo.com	CA PLS - 8738 OH PLS - 8361	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Timothy Franklin Poole (1529)	Timothy Franklin Poole Atwell Group 7718 E. Boise St. Mesa, AZ 85207 480-322-8651 E-mail: tpoole@atwell-group.com E-mail: tpoole62@gmail.com	AZ RLS - 28227	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Michael B. Posada (1767)	Michael B. Posada Anderson Perry & Assoc. Inc. 1901 North Fir Street La Grande, OR 97850 541-963-8309 E-mail: mposada@andersonperry.com	ID PLS - 11006 OR Other - 57868 CWRE OR PLS - 2849 LS WA PLS - 41295	2019 LSAW: PLSS Calculations & Case Studies (2) Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Specifications for Descriptions of Land (1)
Wes Potridge (1500)	Wes Potridge 10255 Suncrest Drive Leavenworth, WA 98826 509-670-6504 E-mail: dirtyface55@gmail.com	AK PLS - 13312 ID PLS - 12269 MT PLS - 10996 WA PLS - 22964	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jacob D. Powell (1749)	Jacob D. Powell AKS Engineering and Forestry 17300 Brant Dr Bend, OR 97707 E-mail: jdpowellgocats@gmail.com E-mail: powellj@aks-eng.com	MT PLS - 30592 OR PLS - 90744 WA PLS - 55830	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Standards for Boundary Evidence (3)
Jeremy M. Powell (1501)	Jeremy M. Powell Powell CWM, Inc. 3200 S. State Route 291 Bldg. 1	KS PLS - 1473 MO PLS - 2007000084	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2)

	<p>Independence, MO 64057</p> <p>816-343-4800 E-mail: jpowell@powellcwm.com</p>		<p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
James M Powers (1031)	<p>James M Powers</p> <p>Red Plains Surveying Co</p> <p>1917 S. Harvard Oklahoma City, OK 73128 405-603-7842</p> <p>E-mail: mick@rpsurveying.com</p>	<p>AK PLS - 13313</p> <p>AL PLS - 31342</p> <p>AR PLS - 1521</p> <p>AZ PLS - 41095</p> <p>CA PLS - 8541</p> <p>CO PLS - 35594</p> <p>CT PLS - 70509</p> <p>FL PLS - 7356</p> <p>GA PLS - 3435</p> <p>HI PLS - 14609</p> <p>KS PLS - 1452</p> <p>KY PLS - 3851</p> <p>ME PLS - 2608</p> <p>MO PLS - 2012000099</p> <p>MS PLS - 32430</p> <p>MT PLS - 19532</p> <p>NC RLS - L-4797</p> <p>ND PLS - 6050</p> <p>NE PLS - 671</p> <p>NV PLS - 15072</p> <p>OK PLS - 1484</p> <p>OR PLS - 95937</p> <p>PA PLS - SU075639</p> <p>SD PLS - 9553</p> <p>TN PLS - 2761</p> <p>TX RLS - 5593</p> <p>UT PLS - 5659228-2201</p> <p>VI PLS - 1376-LS</p> <p>VT PLS - 024.0132659</p> <p>WA PLS - 20100534</p> <p>WI PLS - 3013-08</p> <p>WV PLS - 2393</p> <p>WY PLS - 17689</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Steven D Powers (1277)	<p>Steven D Powers</p> <p>1692 Mangrove Ave., #420</p> <p>Chico, CA 95926</p> <p>E-mail: stvpowers@hotmail.com</p>	<p>CA PLS - L8572</p> <p>MO PLS - 2006016639</p>	<p>7 States Western Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>APLS-CLSA-NALS 2020 Conference (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Chad Pringle (1617)	<p>Chad Pringle</p>	<p>CO PLS - 38349</p>	<p>2018 Denver, CO: Resurveying an Entire GLO Township (2)</p>

	<p>840 W 1st Ave Broomfield, CO 80020</p> <p>E-mail: chadpringle5@gmail.com</p> <p>E-mail: chad.pringle@merrick.com</p>	<p>NM PLS - 22764 UT PLS - 10547350-2201</p>	<p>2019 Rocky Mountain Surveyors Summit (2) 2020 Colorado RMSS Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
David S. Proctor (1449)	<p>David S. Proctor CSI/Thornton Surveying POB 1611</p> <p>Port Orchard, WA 98366</p> <p>360-874-9031 E-mail: dave@csisurveying.com E-mail: dsp@thorntonis.com</p>	<p>SD RLS - 11272 WA PLS - 38986</p>	<p>2014 LSAW Conference Delzell (1) 7 States Western Conference (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
David L. Putt (1502)	<p>David L. Putt</p> <p>PUTT LAND SURVEYING, INC.</p> <p>4817 E. 5th Street</p> <p>Tucson, AZ 85711 520-790-8373 E-mail: dputt@puttsurveying.com</p>	<p>AZ RLS - 13019 CA PLS - 5861 NM PLS - 8526 NV RLS - 7885</p>	<p>2018 Western Regional Survey Conference_Workshop (2) 7 States Western Virtual Conference - 3/29/21 (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p>
Ryan L. Quigley (1730)	<p>Ryan L. Quigley</p> <p>State of Alaska DOT&PF</p> <p>889 Cardigan Circle</p> <p>Anchorage, AK 99503 907-269-0561 E-mail: ryan.quigley@alaska.gov</p>	<p>AK PLS - 12649</p>	<p>2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Relictions in the Public Land Survey System (1) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Rob D Rasmussen (1593)	<p>Rob D Rasmussen</p> <p>USFS 910 W. Gurley St. #38 Prescott, AZ 86305 559-760-9411 E-mail: robin.rasmussen@usda.gov E-mail: rsqidaho@gmail.com</p>	<p>AZ RLS - 14677 CA PLS - 4633</p>	<p>Accretions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Michael C. Ray (1122)	<p>Michael C. Ray Edge Integrity</p>	<p>AR PLS - 1582 CO PLS - 38247</p>	<p>Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2)</p>

	<p>RR 1 Box 91</p> <p>Nowata, OK 74048 918-361-9672 E-mail: mray@edgeintegrity.com E-mail: michael.c.ray@outlook.com</p>	<p>KS PLS - 1464</p> <p>OK PLS - 1653 TX PLS - 6866 UT PLS - 10070969-2201</p>	<p>Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Jeffrey James Redfern (1630)	<p>Jeffrey James Redfern</p> <p>Farnsworth Group 115 Verde Lane Durango, CO 81301</p> <p>970-259-3964 E-mail: jredfern@f-w.com E-mail: ferndog80@hotmail.com</p>	<p>CO PLS - 27937</p> <p>UT RLS - 4917487-2201</p>	<p>2018 Denver, CO: Resurveying an Entire GLO Township (2) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2)</p>
James Gregory Reichhoff (1613)	<p>James Gregory Reichhoff</p> <p>D.R. Strong Consulting Engineers</p> <p>620 7th Avenue Kirkland, WA 98033 719-650-8068</p> <p>E-mail: j_reichhoff@yahoo.com E-mail: james.reichhoff@drstrong.com</p>	<p>CA PLS - 9203</p> <p>CO PLS - 38030</p> <p>OR PLS - 87117PLS WA PLS - 50708 WI PLS - 2262-8</p>	<p>2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) 2021 RMSS Conference (2) 7 States Western Conference (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Robert A Reid (1158)	<p>Robert A Reid WA DNR 225 S Silke Rd Colville, WA 99114</p> <p>509-685-2726 E-mail: robert.reid@dnr.wa.gov</p>	<p>WA PLS - 42440</p>	<p>2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) Discrepancies in the Official Record (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Timothy John Reilly (1546)	<p>Timothy John Reilly 211 San Felipe Drive Imperial, CA 92251 619-850-3624 E-mail: treilly.progression@gmail.com</p>	<p>CA PLS - L 8759</p>	<p>Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Phil Reimer (1348)	<p>Phil Reimer</p> <p>Farr West Engineering</p> <p>5510 Longley Lane</p> <p>Reno, NV 89511 775-853-7250 E-mail: preimer@farrwestengineering.com E-mail: phil@virtualcyclist.com</p>	<p>AZ RLS - 48078</p> <p>CA PLS - 6391</p> <p>NV PLS - 13869</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1)</p>

			<p>Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Donald Rericka (1759)	<p>Donald Rericka SAM LLC 29W278 Helen Avenue West Chicago, IL 60185 630-800-8194</p> <p>E-mail: donr2001@yahoo.com</p>	<p>IL PLS - 035-003465 WI PLS - 3186-8</p>	<p>Monumentation and the Corner Record (3) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)</p>
Michael T. Reynolds (1124)	<p>Michael T. Reynolds Michael T. Reynolds, PLS 621 N. Elks Road Tishomingo, OK 73460 580-387-9677</p> <p>E-mail: tobyholly@sbcglobal.net</p>	<p>OK PLS - 1651</p>	<p>Discrepancies in the Official Record (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Trevor Darragh Rice (1594)	<p>Trevor Darragh Rice D. Woolley & Associates, Inc. 2832 Walnut Avenue</p> <p>A</p> <p>Tustin, CA 92780 714-734-8462 E-mail: trice@dwoolley.com</p>	<p>CA PLS - 8862</p>	<p>Non-Rectangular Surveys (9) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p>
Michael Riley (1806)	<p>Michael Riley</p> <p>P.O Box 183 Cedar City, UT 84721</p> <p>E-mail: michael.riley@usda.gov E-mail: loreto_lizard@outlook.com</p>	<p>CO PLS - 24329</p> <p>ID PLS - 8775 NV PLS - 27344 UT PLS - 11536681</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) Resurveying an Entire GLO Township (2)</p>
Robert Christopher Rinfret (1825)	<p>Robert Christopher Rinfret DJ&A, P.C. 2000 Maple Street Missoula, MT 59808 406-721-4320 E-mail: bob@djanda.com E-mail: rrinfret@gmail.com</p>	<p>AZ PLS - 61602 ID PLS - 20069 MT PLS - 38990 NY RLS - 050991 WI RLS - 3088-8</p>	<p>7 States Western Virtual Conference - 3/29/21 (2)</p>
Steve E Roberts (1308)	<p>Steve E Roberts</p> <p>Renaissance Infrastructure Consulting</p> <p>132 Abbie Ave Kansas City, KS 66103</p> <p>913-787-4773 E-mail: sroberts@ric-consult.com</p>	<p>AR RLS - 1296</p> <p>CO PLS - 29051</p> <p>IA RLS - 17747 KS PLS - 902</p> <p>LA PLS - 5146 MO PLS - 2496 ND RLS - 6295</p> <p>NE RLS - 495 OK PLS - 1363 SD RLS - 5830</p> <p>TX RLS - 6475 WI PLS - 3015-8</p>	<p>Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Anthony Joseph Robinson (1547)	<p>Anthony Joseph Robinson</p> <p>CRW Engineering Group, LLC</p> <p>3940 Arctic Blvd. Anchorage, AK 99503 907-562-3252</p> <p>E-mail: arobinson@crweng.com</p>	<p>AK PLS - 12316</p> <p>OH PLS - 8120</p>	<p>7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Tussio 37 IBLA 135 (1)</p>

Chris Robinson (1653)	Chris Robinson Westlake Consultants 15115 SW Sequoia Pkwy Tigard, OR 97224 503-684-0652 E-mail: crobinson@westlakeconsultants.com	AR PLS - 1693 CO PLS - 38528 ND PLS - 8608 OR PLS - 96451 SD RLS - 11879 WY PLS - 15122	Accretions in the Public Land Survey System (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
D. Mark Roedel (1125)	D. Mark Roedel PO Box 9726 Kalispell, MT 59904 406-721-4320 E-mail: landmark@centurylink.net E-mail: markr@djanda.com	MT PLS - 10999LS	BLM's Experience with CFedS Produced LDR and COSs (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Eric Roeser (1391)	Eric Roeser Egan, Field, & Nowak 1229 Tyler Street NE Suite 100 Minneapolis, MN 55413 612-466-3379 E-mail: eroeser@efnsurvey.com	IL PLS - 035-003958 MN PLS - 47476 MO PLS - 2016019009 ND PLS - 8790 SD PLS - 11712 WI RLS - 2899 WY PLS - 12555	2014 MSFS Winter Seminar - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Dona J Rogers (1035)	Dona J Rogers Retired BLM Cadastral ORWA P.O. Box 357 Brightwood, OR 97011 E-mail: dona_rogers@yahoo.com	NV PLS - 11192	2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) 2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) CIM Quiz (1) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Working Group - Salt Lake City, Utah 2009 (1)
Ernest Dee Rowley (1530)	Ernest Dee Rowley Landmark Surveying, Inc 4646 South 3500 West West Haven, UT 84041 801-731-4075 E-mail: ernest@landmarksurveyutah.com	IL PLS - 035.003453 NV PLS - 010319 UT PLS - 171781-2201	2018 Western Regional Survey Conference_Workshop (2) Hasenyager 176 IBLA 252 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3)

	E-mail: ernest.rowley@hotmail.com		The Landslide Report (2) Utah 2017 "Discrepancies in the Official Record" (2)
Steve Rude (1631)	Steve Rude 665 Palm Beach Road Dickinson, ND 58601 701-225-6564 E-mail: steve.rude@ae2s.com	MT PLS - 15276LS ND PLS - LS-6261 UT PLS - 10692488-2201	Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Dale Christopher Rush (1739)	Dale Christopher Rush 10590 Rutledge Street Parker, CO 80134 303-518-0158 E-mail: drush@azteconsultants.com E-mail: rushelkrl@gmail.com	CO PLS - 33204	2019 Rocky Mountain Surveyors Summit (2) Hillstrom 180 IBLA 388 (2) Identification & Subdivision of Fractional Section (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)
Jeffrey John Safford (1126)	Jeffrey John Safford TSAC Engineering 16885 Via Del Campo Court San Diego, CA 92127 858-762-9617 E-mail: jsafford1957@gmail.com	CA PLS - L 6703	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)
Ernie Salazar (1042)	Ernie Salazar Pueblo of Isleta 5239 CHUCKWAGON TRAIL NW ALBUQUERQUE, NM 87120 505-869-5281 E-mail: poi94003@isletapueblo.com	NM PLS - 15270 TX RLS - 5884	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Buku Saliz (1813)	Buku Saliz Fixed Height LLC 225 w 23rd ave ANCHORAGE, AK 99503 907-280-9456 E-mail: buku@fixedheight.com	AK PLS - AELL14837	
Leonides J Sandoval (1504)	Leonides J Sandoval Klein & Associates Inc. 555 Dairy Way Road Hood River, OR 97031 541-399-2939 E-mail: lsandoval@gorge.net	ID PLS - 13686 MT PLS - 14519 OR PLS - 58608 WA PLS - 44349	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)

			The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Kathryn C. Schalk (1717)	Kathryn C. Schalk PO Box 6152 Olympia, WA 98507 E-mail: kathryn.schalk@dnr.wa.gov E-mail: kschalk@hotmail.com	HI PLS - 14465 WA PLS - 49918	2018 Western Regional Survey Conference_Workshop (2) 2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Identification & Subdivision of Fractional Section (2) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1)
Karl F Scherbel (1223)	Karl F Scherbel Surveyor Scherbel, Ltd. Box 5374 Etna, WY 83118 307-887-7890 E-mail: karl.scherbel1@gmail.com	ID PLS - LS 13493 WY PLS - LS 11810	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Elizabeth Schleif (1814)	Elizabeth Schleif USDA Forest Service 626 E Wisconsin Ave Suite 6W Milwaukee, WI 53202 262-573-2303 E-mail: elizabeth.schleif@usda.gov E-mail: elizschleif@gmail.com	WI PLS - 2579 WV PLS - 842	
Brian Lee Schmalz (1159)	Brian Lee Schmalz Laramie Land Surveying 2161 Polk Street Laramie, WY 82070 307-460-0801 E-mail: brian@laramielandsurveying.com E-mail: brianschmalz@yahoo.com	CO PLS - 38227 MT PLS - 14017 ND PLS - 6809 SD RLS - 10272 WY PLS - 11268	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)

Quentin Nathaniel Schukar (1801)	<p>Quentin Nathaniel Schukar</p> <p>Sherrill Associates 316 North Main Street Edwardsville, IL 62025</p> <p>E-mail: qns@sherrillassoc.com E-mail: qschuk@yahoo.com</p>	<p>IL PLS - 035-003989</p> <p>IN PLS - LS22000002</p>	<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Special Boundary Problems I (3)</p>
Monnie Sears (1127)	<p>Monnie Sears</p> <p>Allgeier, Martin and Associates</p> <p>7231 East 24th Street P.O. Box 2627</p> <p>Joplin, MO 64804 417-438-0728</p> <p>E-mail: searsfamily@mail.com E-mail: monnie.sears@amce.com</p>	<p>AR RLS - 1263</p> <p>KS RLS - 1284</p> <p>MO RLS - 2422</p> <p>OK RLS - 1359</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Carl F. Shangraw (1129)	<p>Carl F. Shangraw</p> <p>Aldebaran Consultants, PLLC</p> <p>210 Blossom Ave Cadillac, MI 49601 616-821-6842</p> <p>E-mail: shangrac@ferris.edu</p> <p>E-mail: shangraw.carl@gmail.com</p>	<p>MI PLS - 25872</p> <p>WI PLS - 1773</p>	<p>2021 RMSS Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>APLS-CLSA-NALS 2020 Conference (2)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Loren K. Shanks (1225)	<p>Loren K. Shanks</p> <p>Uintah Engineering & Land Surveying</p> <p>3313 35th Avenue Suite B Evans, CO 80620</p> <p>970-590-8515</p> <p>E-mail: lshanks@uintahgroup.com</p>	<p>CO PLS - 28285</p> <p>KS PLS - 1581</p> <p>NE RLS - 697</p> <p>OK PLS - 1824</p> <p>WY PLS - 9954</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Deizell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
James H Sharp (1394)	<p>James H Sharp</p> <p>HDL Alaska</p> <p>P.O. Box 190051 Anchorage, AK 99519-0051</p>	<p>AK PLS - 4015-S</p>	<p>2019 Alaska Society of Professional Land Surveyors (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p>

	<p>907-351-1199</p> <p>E-mail: jsharp@HDLAlaska.com E-mail: jsharp@alaska.net</p>		<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The Landslide Report (2)</p>
Robert S. Shotts (1311)	<p>Robert S. Shotts Robert S. Shotts, Inc. P. O. Box 83 267 East Third Street Lebanon, MO 65536</p> <p>417-588-7877 E-mail: bob@shottsync.com</p>	<p>AR PLS - 1208 CO PLS - 28287 IL PLS - 35003094 KS PLS - 1107 MO PLS - 1941</p>	<p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Heather Lare' Sides (1633)	<p>Heather Lare' Sides</p> <p>LJA Surveying, Inc.</p> <p>16834 Empire Gold Drive Cypress, TX 77433 281-513-5710</p> <p>E-mail: hlarem@gmail.com E-mail: hsides@lja.com</p>	<p>ND PLS - 10237</p> <p>TX RLS - 5997</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Mark P. Sidler (1226)	<p>Mark P. Sidler</p> <p>LEMME Associates AZ</p> <p>8607 N 59th Ave B-4 Glendale, AZ 85302 602-841-6904 E-mail: MARCUS@LEMME-ENG.COM</p>	<p>AZ RLS - 28232</p> <p>CA PLS - 8691</p> <p>CO PLS - 38581 NM RLS - 20523</p> <p>NV PLS - 20718</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Benjamin Thomas Sidor (1684)	<p>Benjamin Thomas Sidor USDA Forest Service</p> <p>1950 Benchmark Lane Whitefish, MT 59937 406-231-0132</p> <p>E-mail: benjamin.sidor@gmail.com E-mail: bsidor@fs.fed.us</p>	<p>MT PLS - 39515</p>	<p>2019 MARLS Non-Rectangular Surveys (1)</p> <p>2019 MARLS Private-Federal Boundary Determination (2)</p> <p>2019 MARLS Specifications for Land Descriptions (1)</p> <p>2019: MARLS - Fraudulent Surveys or Not (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Kent E. Sielbach (1227)	<p>Kent E. Sielbach</p> <p>Morrison-Maierle, Inc.</p> <p>315 N. 25th Street Suite 102 Billings, MT 59101 406-656-6000</p>	<p>MT PLS - 10567</p> <p>WY PLS - 11754</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Advanced Topics and Cases in Mineral Surveys (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p>

	E-mail: ksielbach@m-m.net		<p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Lawrence A Signani (1349)	<p>Lawrence A Signani</p> <p>WHPacific</p> <p>1008 Loraine St Enumclaw, WA 98022</p> <p>206-391-3504 E-mail: lsignani@whpacific.com</p>	WA PLS - 11422	<p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Standards for Boundary Evidence (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Keith A. Sikes (1505)	<p>Keith A. Sikes</p> <p>Morrison Shipley Engineers, Inc.</p> <p>2407 SE Cottonwood Street</p> <p>Bentonville, AR 72712</p> <p>479-273-2209 E-mail: ksikes@morrisonshipley.com E-mail: ksikesmse@gmail.com</p>	<p>AR PLS - 1507</p> <p>KS PLS - 1524</p> <p>OK PLS - 1700</p>	<p>2021 RMSS Conference (2)</p> <p>7 States Western Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Andrew Joseph Silbernagel (1655)	<p>Andrew Joseph Silbernagel</p> <p>DOWL</p> <p>378 Camrin Loop</p> <p>Creswell, OR 97426 541-954-8571</p> <p>E-mail: asilbernagel@dowl.com</p>	<p>ID PLS - 20578</p> <p>OR PLS - 79198</p> <p>OR PE - 79198</p> <p>WA PLS - 57447</p>	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p>
Michael L. Sjolín (1570)	<p>Michael L. Sjolín</p> <p>American Surveying & Environmental, LLC</p> <p>4056 148th Ave NE Redmond, WA 98052</p> <p>E-mail: msjolin@asesurvey.com</p>	WA PLS - 45174	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>

			Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Curtis Alan Skarphol (1130)	Curtis Alan Skarphol Houston Engineering, Inc. 17135 54th St SE Horace, ND 58047-9600 701-237-5065 E-mail: cskarphol@houstoneng.com E-mail: cskarphol@msn.com	MN RLS - 42303 ND RLS - 4723 SD RLS - 7922	2015 North Dakota: NDSPLS Annual Convention (2) 2018 Minneapolis - Discrepancies (2) 2021 RMSS Conference (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Mineral Surveys (2) Monumentation and the Corner Record (3) NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Aaron Skattum (1807)	Aaron Skattum Cass County Highway Department 8343 Sautbine Rd NW Walker, MN 56484 701-361-8623 E-mail: aaron.skattum@co.cass.mn.us E-mail: zoogie778@gmail.com	MN PLS - 54139 ND RLS - 6153	Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Greg Paul Skinner (1731)	Greg Paul Skinner Chickasaw Nation 11600 County Road 3630 Ada, OK 74820 580-272-5441 E-mail: cornerstonesurveying@gmail.com E-mail: greg.skinner@chickasaw.net	CO PLS - 27616 OK PLS - 1458	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) The Landslide Report (2)
Matthew S. Slagle (1263)	Matthew S. Slagle Slagle Survey Services P.O. Box 751 Eagle, CO 81631 970-471-1499 E-mail: matthew@slaglesurvey.com	CO PLS - 34998	2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)
Brock J Slaugh (1694)	Brock J Slaugh Timberline Engineering and Land Surveying 9935 E 8000 N P O Box 91 Lapoint, UT 84039 435-828-6154 E-mail: bjs@timberlinels.com	CO PLS - 38443 UT PLS - 8704293	Advanced Topics and Cases in Mineral Surveys (2) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) Utah 2017 "Discrepancies in the Official Record" (2)

Nickolas G. Smith (1418)	Nickolas G. Smith Coordinare 1914 East 9400 South Suite 239 Sandy, UT 84093 702-704-3002 E-mail: nsmith@coordinare.com E-mail: divernsmith@yahoo.com	AZ PLS - 51744 CA PLS - 9057 NV PLS - 022604 UT PLS - 7124739-2201	2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Reily Herbert Smith (1768)	Reily Herbert Smith Private Practice 541 Linda Lane Brookings, OR 97415 541-373-8120 E-mail: reilysmith@hotmail.com E-mail: pls4841@gmail.com	CA PLS - 4841 OR PLS - 02542 OR Other - 370CWRE	2019 CLSA/NALS Private-Federal Boundary (2) Discrepancies in the Official Record (2) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Richard Glenn Smith (1506)	Richard Glenn Smith Johnson-Frank & Associates, Inc. 5150 E. Hunter Ave. Anaheim, CA 92807 714-777-8877 E-mail: richsmith@johnson-frank.com	CA PLS - 7556	Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Ryan Neale Smith (1740)	Ryan Neale Smith A-Line Land Surveying, LLC 591 SE Ellis Road Shelton, WA 98584 360-485-7426 E-mail: alinelandsurveying@gmail.com	WA PLS - 53033	Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3)
Joseph Matthew Solomon (1507)	Joseph Matthew Solomon High Mesa Consulting Group 6010-B Midway Park Blvd NE Albuquerque, NM 87109 505-345-4250 E-mail: jsolomon@highmesacg.com	NM PLS - 15075 OK PLS - 1847 UT PLS - 9765668-2201	2021 RMSS Conference (2) 7 States Western Conference (2) Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Robert R Spear Jr. (1268)	Robert R Spear Jr. Spear Land Surveying, Inc. 6935 Hardwood Road Republic, MI 49879 906-371-0585 E-mail: rspearps@sbcglobal.net	MI PLS - 43069 WI PLS - 2544	Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1)
Jim Speck (1131)	Jim Speck Speck Engineering	AR PLS - 1395 AR PE - 10177	Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2)

	<p>8500 Bethel Road</p> <p>Shawnee, OK 74804 405-964-2910 E-mail: jim.speck@gmail.com E-mail: jim@speckengineering.com</p>	<p>OK PLS - 1536</p> <p>OK PE - 20040</p>	<p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Jacob Spees (1397)	<p>Jacob Spees</p> <p>W6053 Garnet Drive</p> <p>Appleton, WI 54915</p> <p>E-mail: jakespees@gmail.com</p>	WI PLS - 2925-008	<p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Keith W. Spencer (1454)	<p>Keith W. Spencer</p> <p>PO Box 1149</p> <p>4825 2nd St</p> <p>Empire, CA 95319</p> <p>209-988-5834 E-mail: Keith@keithwspencer.net E-mail: cals6406@yahoo.com</p>	CA PLS - 6406	<p>7 States Western Virtual Conference - 3/29/21 (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Earl Dean Spires, Jr. (1132)	<p>Earl Dean Spires, Jr. Myers Engineering, Inc.</p> <p>525 West Honey Creek Drive Terre Haute, IN 47802 812-208-5268</p> <p>E-mail: spires3531@gmail.com E-mail: espires@myersengineering.com</p>	<p>IL PLS - 035003531</p> <p>IN PLS - LS29900015</p>	<p>2021 RMSS Conference (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>

			The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Marc Edward Sprague (1398)	Marc Edward Sprague Red Maple Land Surveying, LLC 300 West Galena Street Bessemer, MI 49911 906-364-5755 E-mail: redmaplels@charter.net E-mail: fluffy200@charter.net	MI PLS - 55940 WI RLS - 2876	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jay Springer (1036)	Jay Springer Milk River Engineering Inc. P.O. Box 2532 302 4th Street Havre, MT 59501 E-mail: mrejay@havremt.net	MT PLS - 9929ES MT PE - 9929ES	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Specifications for Land Descriptions (1) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Nathaniel T. Stadler (1183)	Nathaniel T. Stadler Bolton & Menk, Inc. 3432 Baneberry Cir Shakopee, MN 55379 612-756-0957 E-mail: nate.stadler@bolton-menk.com	MN PLS - 43934 ND PLS - LS-9240 SD RLS - 11880	2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Tom Stark (1175)	Tom Stark Robert Peccia and Associates	AK PLS - 13841 ID PLS - 10294	Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2)

	<p>3147 Saddle Drive Helena, MT 59601 406-447-5020 E-mail: tstark@rpa-hln.com</p>	<p>MT PLS - 12249LS</p>	<p>Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1)</p>
Nicholas Ray Stattelman (1619)	<p>Nicholas Ray Stattelman AE2S 4170 28th Ave S Fargo, ND 58104 218-230-4358 E-mail: nick.stattelman@ae2s.com E-mail: sheryl.todd@ae2s.com</p>	<p>MN PE - 49835 MN RLS - 49835 ND RLS - LS-8218 SD RLS - 11623</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2) 2018 Minneapolis - Discrepancies (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Justin Wheeler Stefanik (1656)	<p>Justin Wheeler Stefanik KLJ 5240 Collins Drive Helena, MT 59602 406-439-4169 E-mail: justin.stefanik@kljeng.com E-mail: justin.stefanik@hotmail.com</p>	<p>MT PLS - 32881</p>	<p>Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) William D. Brown 137 IBLA 31 (1)</p>
Richard Stein (1837)	<p>Richard Stein 1901 N. Fir St La Grande, OR 97850 E-mail: rstein@andersonperry.com</p>	<p>NV PLS - 16932 OR PLS - 49593PLS OR PE - 49593PE</p>	
Randall S. Stelzner (1193)	<p>Randall S. Stelzner Inberg-Miller Engineers 124 East Main Street Riverton, WY 82501 307-856-8136 E-mail: rstelzner@inberg-miller.com</p>	<p>CO RLS - 18263 ID RLS - 5717 MT RLS - 14745 ND RLS - 7724 WI RLS - 1495 WY RLS - 5134</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) CIM Quiz (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1) Working Group - Salt Lake City, Utah 2009 (1)</p>
L. Kelley Stevenson (1176)	<p>L. Kelley Stevenson U. S. Fish and Wildlife Service</p>	<p>CA PLS - 8221 CO PLS - 38231</p>	<p>2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1)</p>

	<p>201 Cedar Ave. Castle Rock, CO 80104 970-568-6916 E-mail: larry_stevenson@fws.gov E-mail: lk_stevenson@yahoo.com</p>	<p>NV PLS - 16641 UT RLS - 4938755-2201 WY RLS - 13152</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Alan William Stoll (1509)	<p>Alan William Stoll DOWL Po Box 241004 Anchorage, AK 99524 907-232-6667 E-mail: wstoll@dowl.com</p>	<p>AK PLS - 12041-S AZ PLS - 66729 CA PLS - 9504 CO PLS - 0038615 ID PLS - 18239 NV PLS - 25866 OR PLS - 92358 TX PLS - 6800 UT PLS - 10964714-2201 WA PLS - 57446</p>	<p>2019 Alaska Society of Professional Land Surveyors (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
James Todd Stovall (1608)	<p>James Todd Stovall 7065 W Ann Rd Ste 130-338 Las Vegas, NV 89130 702-419-3432 E-mail: todd.s@taneycorp.com E-mail: stovalljt@gmail.com</p>	<p>AZ RLS - 25088 CA PLS - 7760 CO PLS - 38196 ND PLS - 7667 NV PLS - 9992 UT PLS - 6045236-201</p>	<p>2019 CLS/NALS Private-Federal Boundary (2) 2021 RMSS Conference (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
John Phillip Strohming (1531)	<p>John Phillip Strohming Pacific Overland Engineering & Surveying 635 Via Columbia Vista, CA 92081 760-415-2584 E-mail: JohnPStroh@yahoo.com</p>	<p>CA PLS - 8219 CA PE - 55187</p>	<p>February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Eric B. Stuart (1230)	<p>Eric B. Stuart Surveying And Mapping, LLC 7005 Greenland Rd Walnut Hill, FL 32568 850-685-1149 E-mail: Eric.Stuart@sam.biz</p>	<p>AL PLS - 29101 AR PLS - 1779 FL PLS - 6707 GA RLS - 3261 LA PLS - 5046 MO PLS - 2016000170 MS PLS - 3119</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1)</p>

		<p>NC PLS - 5032 SC PLS - 27744 TN RLS - 2902</p> <p>TX RLS - 6237</p>	<p>Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Robin Steven Suber (1802)	<p>Robin Steven Suber Usace</p> <p>3625 Ms Hwy 9 Ackerman, MS 39735 662-285-8269 E-mail: Robin.Suber@usace.army.mil E-mail: Stymie.rss@gmail.com</p>	<p>AL PLS - 24323 KY PLS - 4259</p> <p>MS PLS - 02830</p>	<p>Hillstrom 180 IBLA 388 (2) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2)</p>
Sean L. Suttles (1643)	<p>Sean L. Suttles</p> <p>Lochmueller Group, Inc. 7099 russell place chandler, IN 47610 812-459-6211 E-mail: ssuttles@lochgroup.com E-mail: spikebla241@wowway.com</p>	<p>IL PLS - 3674</p> <p>IN PLS - 20300029 KY PLS - 3961 MO PLS - 2014000199</p>	<p>Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Paul R. Svenson (1399)	<p>Paul R. Svenson WLC Engineering Surveying & Planning 200 Pronghorn Casper, WY 82601</p> <p>307-266-2524 E-mail: psven@wlcwyo.com</p>	<p>CO PLS - 38561 ID PLS - 15350 WY PLS - 10272</p>	<p>Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
David Lawrence Swanson (1741)	<p>David Lawrence Swanson</p> <p>Swanco Inc. 3949 Cedarwood Lane Johnstown, CO 80534</p> <p>605-929-8353 E-mail: dswanson50@live.com</p>	<p>AZ RLS - 39706</p> <p>CO PLS - 36070 NE RLS - 523</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) 2020_Colorado RMSS Workshop (2) 2020_Colorado RMSS Workshop (TEST) (0) February 2021 RMSS Virtual Conference Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p>
Joanne Marie Swanson (1790)	<p>Joanne Marie Swanson</p> <p>Orca Land Surveying, Inc. 2002 State Street</p> <p>Everett, WA 98201 509-721-1905 E-mail: themulesaregone@yahoo.com</p>	<p>OR PLS - 02696</p> <p>WA PLS - 34671 WY PLS - 14614</p>	<p>2019 LSAW: PLSS Calculations & Case Studies (2) Discrepancies in the Official Record (2) Stoddard Jacobsen and Robert C. Downer (2)</p>
Joshua Charles Tatman (1548)	<p>Joshua Charles Tatman 19591 agria way trabuco canyon, CA 92679</p> <p>E-mail: josh.tatman@gmail.com</p>	<p>AK PLS - 13839 AZ RLS - 53888 CA PLS - 8858 CO PLS - 38583 WA PLS - 50990</p>	<p>Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>

Philip Vaughn Taylor (1455)	Philip Vaughn Taylor Axiom Surveying & Mapping 4801 Patricia Drive Eureka, CA 95503 707-672-4887 E-mail: Phil.Taylor@consultant.com	CA PLS - 7925 OR PLS - 77097	Tussio 37 IBLA 135 (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Jeremiah Teague (1401)	Jeremiah Teague 1123 E Hampton Street Tucson, AZ 85719 520-260-3629 E-mail: j.o.teague@gmail.com E-mail: jteague@psomas.com	AZ RLS - 18557 NV RLS - 8857	2018 Western Regional Survey Conference_Workshop (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Adam C Teale (1313)	Adam C Teale Midland Surveying Inc 501 N Market Maryville, MO 64468 660-582-8633 E-mail: ateale@midlandsurvey.com	AR PLS - 1868 IA PLS - 17685 ID PLS - 17551 IL PLS - 3864 KY PLS - 4274 MO PLS - 2004001336 MT PLS - 51808 OK PLS - 1914 UT PLS - 10536842-2201	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
James Gerard Temple (1350)	James Gerard Temple CEI Engineering Associates 3108 SW Regency Parkway Suite 2 Bentonville, AR 72712 501-339-5073 E-mail: jtemple@ceieng.com E-mail: jamestemple1956@gmail.com	AR PLS - 1021 AZ RLS - 37521 CA PLS - 7812 CO PLS - 38232 GA RLS - 2813 IA PLS - 13645 KS PLS - 1121 LA PLS - 4816 MO RLS - 2517 NM PLS - 13615 NV PLS - 016203 OK RLS - 1234	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)

		OR PLS - 69244LS TX RLS - 6296 WA PLS - 38991 WY PLS - 14749	
Alec Khalil Thomas (1718)	Alec Khalil Thomas River City Consultants 744 Horizon Ct. Suite 110 Grand Junction, CO 81506 970-589-1195 E-mail: alec_23@msn.com E-mail: athomas@rccwest.com	CO PLS - 38274 NM PLS - 24164	2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) 2020_Colorado RMSS Workshop (TEST) (0) February 2021 RMSS Virtual Conference Workshop (2) Hasenyager 176 IBLA 252 (1) Identification & Subdivision of Fractional Section (2) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)
William McKinley Thomas, III (1022)	William McKinley Thomas, III 136 C N.W. Miami, OK 74354 918-544-8114 E-mail: b_thomas@att.net	OK PLS - 1342	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Shawn Michael Thomasson (1657)	Shawn Michael Thomasson Interstate Engineering 13138 Loon Lane Lake Park, MN 56554 701-799-4055 E-mail: shawn.thomasson@interstateeng.com E-mail: ndsurveyor@gmail.com	ND PLS - 5900 SD PLS - 9665	Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) NDSPLS Annual Conference Feb. 6, 2020 – Fargo, ND (2) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Adam C Thompson (1456)	Adam C Thompson Interstate Engineering 3235 Talon Road Spearfish, SD 57783 605-642-4772 E-mail: adam.thompson@interstateeng.com	CO PLS - 38721 MT PLS - 20341 ND PLS - 6175 SD RLS - 9823 WY PLS - 13153	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) Introduction to the Geographic Coordinate Database (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3)
John Walter Thompson (1733)	John Walter Thompson Forty North, LLC 53575 County Road NN Wray, CO 80758 970-466-0552 E-mail: fortynorthllc@gmail.com	CO PLS - 38321 NE RLS - 758	Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Terry W Throesch (1532)	Terry W Throesch USDA - FS U.S. Forest Service #4 Confederate Ridge Rd. Doniphan, MO 63935 573-996-2153 E-mail: terry.throesch@usda.gov	AR PLS - 1270 MO PLS - 2010000248	APLS-CLSA-NALS 2020 Conference (2) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)

Scott C. Throm (1701)	<p>Scott C. Throm 6401 S. Boston St. Unit C205</p> <p>Greenwood Village, CO 80111 630-234-8322 E-mail: scott.throm@att.net</p>	<p>AZ RLS - 60798 CO PLS - 38432</p>	<p>The Landslide Report (2)</p> <p>2016 Discrepancies in the Official Record (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Identification & Subdivision of Fractional Section (2)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Non-Rectangular Surveys (9)</p> <p>Specifications for Descriptions of Land (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Glen William Thurow (1549)	<p>Glen William Thurow Maser Consulting, P.A.</p> <p>2703 Broadbent Pkwy. NE Suite B Albuquerque, NM 87107 505-274-8571</p> <p>E-mail: gthurow@maserconsulting.com</p> <p>E-mail: gthurow@outlook.com</p>	<p>NM PLS - 11394</p>	<p>2015 New Mexico Conference - Hillstrom (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Special Boundary Problems I (3)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p>
Karen F. Tilton (1023)	<p>Karen F. Tilton</p> <p>R&M Consultants, Inc.</p> <p>212 Front Street</p> <p>Suite 150 Fairbanks, AK 99701 907-452-5270 E-mail: ktilton@rmconsult.com</p>	<p>AK PLS - LS 7339</p>	<p>2019 Alaska Society of Professional Land Surveyors (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Joseph Todaro (1133)	<p>Joseph Todaro</p> <p>13834 n del webb blvd Sun City, AZ 85351 623-580-0219 E-mail: todaro5@cox.net</p>	<p>AZ RLS - 36563</p>	<p>2019 APLS Private-Federal Boundary Determination (2)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Monumentation and the Corner Record (3)</p> <p>Non-Rectangular Surveys (9)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p> <p>Specifications for Descriptions of Land (1)</p> <p>Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p> <p>Tussio 37 IBLA 135 (1)</p> <p>William D. Brown 137 IBLA 31 (1)</p>
Scott L. Toldness (1271)	<p>Scott L. Toldness Glahe & Associates, Inc. 303 Church Street</p> <p>Sandpoint, ID 83864 208-265-4474</p> <p>E-mail: stoldness@glaheinc.com</p>	<p>ID PLS - 6603 MT PLS - 14744 OR PLS - 90216</p> <p>WA PLS - 31456</p>	<p>2021 RMSS Conference (2)</p> <p>7 States Western Conference (2)</p> <p>Accretions in the Public Land Survey System (1)</p> <p>APLS-CLSA-NALS 2020 Conference (2)</p> <p>Avulsions in the Public Land Survey System (1)</p> <p>BLM's Experience with CFedS Produced LDR and COSs (1)</p> <p>Delzell 158 IBLA 238 (1)</p> <p>Discrepancies in the Official Record (2)</p> <p>February 2018 Las Vegas CFedS Workshop (2)</p> <p>Hasenyager 176 IBLA 252 (1)</p> <p>Hillstrom 180 IBLA 388 (2)</p> <p>Introduction to the Geographic Coordinate Database (3)</p> <p>Longview Fibre Co. 135 IBLA 170 (1)</p> <p>Monumentation and the Corner Record (3)</p> <p>Relictions in the Public Land Survey System (1)</p> <p>Resurveying an Entire GLO Township (2)</p> <p>Special Boundary Problems I (3)</p>

			<p>Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Grant Dickson Tolton (1020)	<p>Grant Dickson Tolton Mid-Mountain Surveyors, Inc. 4 Mid-Mountain Lane Republic, WA 99166</p> <p>509-775-3563</p> <p>E-mail: gtolton@mid-mtn.com</p>	<p>ID PLS - 9444 WA PLS - 20865</p>	<p>2014 LSAW Conference Delzell (1) 2014 LSAW Conference Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Douglas B. Toney (1634)	<p>Douglas B. Toney Bowman Consulting</p> <p>1295 W Washington St #108</p> <p>Tempe, AZ 85281</p> <p>E-mail: dtoney@bowmanmcg.com</p>	<p>AZ RLS - 55030</p>	<p>Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1)</p>
Vincent James Townsend (1826)	<p>Vincent James Townsend Land Development Consultants 5513 138th PL SE Everett, WA 98208 425-478-2190 E-mail: vincetownsend@gmail.com E-mail: vtownsend@ldccorp.com</p>	<p>CA PLS - 9441 OR PLS - 91373 WA PLS - 52841</p>	
Curt D. Traina (1404)	<p>Curt D. Traina</p> <p>13022 54th Ave SE</p> <p>Everett, WA 98208</p> <p>E-mail: ctraina@protonmail.com</p>	<p>CA PLS - 8683 WA PLS - 54741</p>	<p>2019 LSAW: PLSS Calculations & Case Studies (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Advanced Topics and Cases in Mineral Surveys (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Jacobsen-Downer (The Rest of the Story) LSAW 2019 (1) Landslides & Moving Monuments – LSAW WA 2019 (1) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Michael John Trunk (1351)	<p>Michael John Trunk Trunk Surveying, LLC</p> <p>306 7th Ave. S</p> <p>Princeton, MN 55371 763-447-7106 E-mail: michaeltrunk@hotmail.com</p>	<p>MN RLS - 18434 WI RLS - 1914-8</p>	<p>2014 MSPS Winter Seminar - Hillstrom (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3)</p>

			<p>Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Sean P Twomey (1272)	<p>Sean P Twomey McElhanney</p> <p>36 Davy Crescent</p> <p>British Columbia Kitimat, BC V8C1C5 250-639-4506 E-mail: stwomey@hotmail.com E-mail: stwomey@mcelhanney.com</p>	<p>AZ RLS - 44568 UT PLS - 7745525-2201</p>	<p>Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Carlos Urena (1690)	<p>Carlos Urena</p> <p>PBLA Surveying</p> <p>118 Crabapple Dr. Pomona, CA 91767 626-512-4934</p> <p>E-mail: c.los.32@gmail.com E-mail: curena@pbla.biz</p>	<p>AZ PLS - 53161 CA PLS - 8234 NV PLS - 21975 WA PLS - 53443</p>	<p>2019 CLSA/NALS Private-Federal Boundary (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Brian L Van Aller (1061)	<p>Brian L Van Aller</p> <p>Van Aller Surveying P.O. Box 757 Carlsborg, WA 98324</p> <p>360-683-3438 E-mail: vansurv@olyopen.com</p>	<p>WA PLS - 35986</p>	<p>Accretions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Corbin L. Van Nest (1581)	<p>Corbin L. Van Nest</p> <p>Bulloch Brothers Engineering Inc.</p> <p>145 Quail Run St. Mesquite, NV 89027-6272 702-204-3129 E-mail: surveyor_cv@hotmail.com.com E-mail: surveyor_cv@hotmail.com</p>	<p>NV PLS - 14349 UT PLS - 343629</p>	<p>2018 Western Regional Survey Conference_Workshop (2) Advanced Topics and Cases in Mineral Surveys (2) Delzell 158 IBLA 238 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) UCLS_St. George, UT 2/20/2020 Workshop (2)</p> <p>Utah 2017 "Discrepancies in the Official Record" (2)</p>
David Joseph VanDenBerghe (1533)	<p>David Joseph VanDenBerghe</p> <p>Geodetic Designs, Inc. 2300 N. Grand River Ave.</p> <p>Lansing, MI 48906 517-908-0008</p> <p>E-mail: david.vandenbergh@geodeticdesigns.com</p>	<p>IL PLS - 035.003812 IN PLS - 20800142 MI PLS - 4001051489 WI PLS - S-3139</p>	<p>Accretions in the Public Land Survey System (1) APLS-CLSA-NALS 2020 Conference (2) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1)</p>

			<p>Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Aaron Brent Vanderslice (1791)	<p>Aaron Brent Vanderslice 11474 South Douglas Ave Jenks, OK 74037 918-638-0218 E-mail: avanderslice@mcn-nsn.gov E-mail: aaronslice@yahoo.com</p>	OK PLS - 1842	<p>Monumentation and the Corner Record (3) Standards for Boundary Evidence (3)</p>
Christopher Gerhardt Vandrey (1734)	<p>Christopher Gerhardt Vandrey 4411 Stoneyglen Court Moorpark, CA 93021 650-787-7351 E-mail: chris.vandrey@gmail.com</p>	CA PLS - 8783	<p>Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)</p>
Dennis Michael VanRyckeghem (1315)	<p>Dennis Michael VanRyckeghem Bureau of Reclamation 9217 W. Hutton Dr. Sun City, AZ 85351 480-254-0406 E-mail: dvanr50@gmail.com E-mail: dvanryckeghem@usbr.gov</p>	<p>AZ RLS - 36564 MO RLS - 2013000046 NM RLS - 18995</p>	<p>Boundary Evidence Standards Documents (1) Discrepancies in the Official Record (1) February 2018 Las Vegas CFedS Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) William D. Brown 137 IBLA 31 (1)</p>
Steven Blaine Varriano (1459)	<p>Steven Blaine Varriano Tait & Associates, Inc. P.O. BOX 783 LOVELAND, CO 80539 970-613-1447 E-mail: svarriano@tait.com</p>	<p>CO PLS - 30126 MN PLS - 53176 ND PLS - LS-7837 WY PLS - 12707</p>	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) Hillstrom 180 IBLA 388 (2) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p>
Lindsey Sue Vaughan (1510)	<p>Lindsey Sue Vaughan GPS Inc. 2603 Blueberry Rd Anchorage, AK 99503 315-546-4519 E-mail: lindseyvaughan@gps-ak.com</p>	AK RLS - L12318	<p>2019 Alaska Society of Professional Land Surveyors (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1)</p>
Carl S Vender (1352)	<p>Carl S Vender 6029 Linck Circle Shepherd, MT 59079-4416 406-373-0997 E-mail: grandpavender@yahoo.com</p>	<p>MT PLS - 5931S ND PLS - 1222 SD PLS - 8939</p>	<p>2015 North Dakota: NDSPLS Annual Convention (2) 2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Accretions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)</p>

			Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Samuel R Ward (1760)	Samuel R Ward APS Survey & Mapping 13221 SE 26th Street Suite A Bellevue, WA 98005 425-746-3200 E-mail: samw@apssm.com	WA PLS - 52843	Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Longview Fibre Co. 135 IBLA 170 (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Fred M Warner (1231)	Fred M Warner fred.warner@ch2m.com 15510 183 Place NE Woodinville, WA 98072 425-788-4072 E-mail: fred.warner@ch2m.com	WA PLS - 44652	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Keith Watkins (1572)	Keith Watkins 8 E Lake Rd Hamilton, NY 13346 315-825-8447 E-mail: keithawatkins@gmail.com E-mail: kwatkins@colgate.edu	NY RLS - 050825 WI RLS - 2680	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)
Matthew L. Weeks (1461)	Matthew L. Weeks 3131 Arizona Dr. Bismarck, ND 58503 701-471-8973 E-mail: mweeks@compassrosend.com E-mail: matt.weeks@interstateeng.com	MT PLS - PLS 17797 ND PLS - PLS 3626 SD PLS - PLS 8258 WY PLS - PLS 10552	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) William D. Brown 137 IBLA 31 (1)
Patricia Ann Weinreis (1785)	Patricia Ann Weinreis Luce County Remon. Rep. 902 Tahquamenon Blvd.	MI PLS - 4001053091	Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Special Boundary Problems I (3)

	Newberry, MI 49868 E-mail: pawein@sbcglobal.net		
Adam Raymond Weirich (1809)	Adam Raymond Weirich 2565 C Street San Diego, CA 92102 760-815-8576 E-mail: adam.weirich@tsacengineering.com E-mail: adamweirich@gmail.com	CA PLS - 9182	Non-Rectangular Surveys (9)
James Wengler (1059)	James Wengler Wengler Surveying & Mapping 703 East Eighth Street Port Angeles, WA 98362 360-457-9600 E-mail: james@wenglersurveying.com	WA PLS - 26304	2013 OIT Land Surveyor's Workshop - Delzell (1) 2013 OIT Land Surveyor's Workshop - Tussio (1) 2015 - LSAW Hillstrom (2) 2019 LSAW: PLSS Calculations & Case Studies (2) BLM's Experience with CFedS Produced LDR and COSs (1) Hasenyager 176 IBLA 252 (1) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) William D. Brown 137 IBLA 31 (1)
Richard L. Wentworth (1659)	Richard L. Wentworth R&K Land Surveying PO Box 606 Willow, AK 99688 E-mail: rwkew@mtaonline.net E-mail: rklandsurveying@gmail.com	AK PLS - 11004	2021 RMSS Conference (2) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) The 2009 Manual of Surveying Instructions (2) William D. Brown 137 IBLA 31 (1)
Antonio Schroeder Westerlund (1719)	Antonio Schroeder Westerlund 9422 N Backer Ave Fresno, CA 93720 916-430-0599 E-mail: antoniowesterlund@gmail.com	CA PLS - 9399	Discrepancies in the Official Record (2) Hillstrom 180 IBLA 388 (2) Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2)
CLAUDIA MICHELLE WESTERLUND (1742)	CLAUDIA MICHELLE WESTERLUND 9422 N. Backer Ave Fresno, CA 93720 559-412-9920 E-mail: CLAUDIAWESTERLUND@GMAIL.COM	CA PLS - 9433	Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hillstrom 180 IBLA 388 (2) Jan 24, 2020 Fresno Stoddard-Jacobsen Presentation (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)
William T. Whelan (1635)	William T. Whelan Whelan Land Surveys 2343 Savoy Place Steamboat Springs, CO 80487 970-846-6264 E-mail: whelanlandsurveys@gmail.com	CO PLS - 38277	2018 Denver, CO: Resurveying an Entire GLO Township (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) February 2018 Las Vegas CFedS Workshop (2) February 2021 RMSS Virtual Conference Workshop (2) Introduction to the Geographic Coordinate Database (3) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Special Boundary Problems I (3)

			Specifications for Descriptions of Land (1) The 2009 Manual of Surveying Instructions (2)
Keith Whisenhunt (1808)	Keith Whisenhunt Project Delivery Group 200 Hawthorne Avenue SE Suite A-100 Salem, OR 97301 E-mail: keithw@pdgnw.com	CA PLS - L 9518 OR PLS - 62679PLS WA PLS - 56910	7 States Western Conference (2) Longview Fibre Co. 135 IBLA 170 (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1)
Walter E. White (1235)	Walter E. White SHN Eng. & Geologists 275 Market Ave. Coos Bay, OR 97420 541-266-9890 E-mail: wwwhite@shn-engr.com	OR PLS - 55547	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) BLM's Experience with CFedS Produced LDR and COSs (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Todd M Whittaker (1135)	Todd M Whittaker Ralph L Wadsworth 166 E 14000 S, Suite 200 Draper, UT 84020 801-553-1661 E-mail: twhittaker@wadsco.com	AK RLS - 12648 AZ RLS - 47008 CO PLS - 38537 ID PLS - 13125 MT PLS - 19484 ND PLS - LS7968 NV PLS - 020908 UT PLS - 4939194 WY PLS - 12291	2018 Western Regional Survey Conference_Workshop (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) CIM Quiz (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Nov 2015_PLSW_Tussio (1) Nov2015_Discrepancies in the Official Record (2) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Stoddard Jacobsen and Robert C. Downer (2) The 2009 Manual of Surveying Instructions (2) UCLS_St. George, UT 2/20/2020 Workshop (2) Utah 2017 "Discrepancies in the Official Record" (2)
Cory Wilhelm (1743)	Cory Wilhelm 812 Wright Way Miles City, MT 59301 E-mail: wilhelmlandsurveying@outlook.com	MT PLS - 60940	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Relictions in the Public Land Survey System (1) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) William D. Brown 137 IBLA 31 (1)
John Adam Wilhelm (1462)	John Adam Wilhelm Merrick & Company 24012 E Moraine Pl Aurora, CO 80016 303-502-0036 E-mail: john.wilhelm@merrick.com	AK RLS - 14455 CO PLS - 37043	2016 Discrepancies in the Official Record (2) 2018 Denver,CO: Resurveying an Entire GLO Township (2) 2019 Rocky Mountain Surveyors Summit (2) 2020_Colorado RMSS Workshop (2) 2020_Colorado RMSS Workshop (TEST) (0) February 2021 RMSS Virtual Conference Workshop (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9)

			Special Boundary Problems I (3) The Landslide Report (2)
Christopher Wilk (1463)	Christopher Wilk Pinal County Public Works PO BOX 727 Florence, AZ 85132 480-390-7102 E-mail: cwilkcfd@cox.net E-mail: christopher.wilk@pinalcountyz.gov	AZ RLS - 49218	2018 Western Regional Survey Conference_Workshop (2) 2019 APLS Private-Federal Boundary Determination (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Standards for Boundary Evidence (3)
Jon Christopher Wilkinson (1405)	Jon Christopher Wilkinson Morrison-Maierle 167 Gemstone Dr. Belgrade, MT 59714 406-570-6304 E-mail: plumbobmt@msn.com	MT PLS - 16411 UT PLS - 7276002-2201	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) 7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2)
Stewart J. Willis (1550)	Stewart J. Willis SJW Land Surveying, Inc. PO Box 1223 Bigfork, MT 59911 406-529-8171 E-mail: stewart.willis@usda.gov E-mail: sjwsinc@yahoo.com	ID PLS - 18600 MT PLS - 19929 WA PLS - 46902	2019 MARLS Non-Rectangular Surveys (1) 2019 MARLS Private-Federal Boundary Determination (2) 2019 MARLS Specifications for Land Descriptions (1) 2019: MARLS - Fraudulent Surveys or Not (1) Accretions in the Public Land Survey System (1) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) The 2009 Manual of Surveying Instructions (2)
James C. Willson (1420)	James C. Willson Site Consulting, Inc. 3460 Angel Ln Placerville, CA 95667 530-306-4086 E-mail: jwillson@siteconsultinginc.com	CA PLS - 4663 CA PE - C38947 NV PLS - 21018 OR PLS - 85634 UT PLS - 7935814	2018 Western Regional Survey Conference_Workshop (2) 2019 CLS/NALS Private-Federal Boundary (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2) Tussio 37 IBLA 135 (1)
Dallas Wayne Wilson (1406)	Dallas Wayne Wilson 26076 Stansbery Street Conifer, CO 80433 303-549-1031 E-mail: dallas76@gmail.com E-mail: dwilson@survwest.com	AZ RLS - 57780 CO PLS - 38058 ID PLS - 14422 MT Other - 18961 ND Other - 7549 NM Other - 20599 SD RLS - 9871 TX Other - 6301 UT PLS - 7512121-2201 WY PLS - 11783	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Delzell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1)

			<p>Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
David Andrew Wilson (1645)	<p>David Andrew Wilson</p> <p>470 hill st</p> <p>Boulder, CO 80302</p> <p>303-598-6790 E-mail: davecosnowboarder@gmail.com</p>	CO PLS - 38280	<p>2018 Denver,CO: Resurveying an Entire GLO Township (2) Identification & Subdivision of Fractional Section (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9)</p>
TIMOTHY J. WOLF (1551)	<p>TIMOTHY J. WOLF</p> <p>ArtisanSurveying.com</p> <p>P.O. Box 396</p> <p>196 Gold St. Pioche, NV 89043 702-339-8729</p> <p>E-mail: TWolf@ArtisanSurveying.com</p>	<p>AK PLS - 13316</p> <p>NV PLS - 9677</p> <p>NV Other - WRS 954</p> <p>UT PLS - 7266939 WI PLS - 2916-8</p>	<p>7 States Western Virtual Conference - 3/29/21 (2) Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Deizell 158 IBLA 238 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Standards for Boundary Evidence (3) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>
Jerry Charles Woodrow (1138)	<p>Jerry Charles Woodrow</p> <p>David Evans & Associates 30830 Palo Alto Drive Redlands, CA 92373 909-322-6690</p> <p>E-mail: jcwo@deainc.com</p>	CA PLS - 6714	<p>Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2)</p>
Corey M Woodruff (1234)	<p>Corey M Woodruff Stuntzner Engineering & Forestry, LLC 2318-B Pacific Ave.</p> <p>Forest Grove, OR 97116 503-357-5717 E-mail: coreywoodruff@stuntzner.com</p>	OR PLS - 62978LS	<p>Deizell 158 IBLA 238 (1) Discrepancies in the Official Record (2) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Longview Fibre Co. 135 IBLA 170 (1) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)</p>
Richard Wright (1191)	<p>Richard Wright</p> <p>R/W Consulting</p> <p>PO Box 400 Disney, OK 74340 918-520-0385 E-mail: fire19er@gmail.com</p>	<p>AR PLS - 1086</p> <p>KS PLS - 860</p> <p>OK PLS - 1199</p>	<p>Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Discrepancies in the Official Record (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2)</p> <p>The 2009 Manual of Surveying Instructions (2)</p> <p>The Landslide Report (2)</p>

Stewart Justin Wright (1660)	Stewart Justin Wright Las Vegas Valley Water District 725 Barrie Court Henderson, NV 89002 702-908-9893 E-mail: justin.wright@lvvwd.com E-mail: justin_wright_@hotmail.com	AZ RLS - 43351 NV PLS - 19197	William D. Brown 137 IBLA 31 (1) 2018 Western Regional Survey Conference_Workshop (2) 2019 CLSA/NALS Private-Federal Boundary (2) AZ-CA-NV Virtual Conference (Aug. 22, 2020) (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) Special Boundary Problems I (3) Specifications for Descriptions of Land (1)
Kristopher Wroolie (1761)	Kristopher Wroolie Westwood Professional Services 16260 Birchwood Lane Brainerd, MN 56401 218-851-2955 E-mail: kris.wroolie@westwoodps.com	ID RLS - 15252 MN RLS - 49563 ND RLS - LS-7723 OK RLS - 1864 OR RLS - 92080 SD RLS - 11352 VT RLS - 024.0131273 WY RLS - 15249	2018 Western Regional Survey Conference_Workshop (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Resurveying an Entire GLO Township (2) The 2009 Manual of Surveying Instructions (2)
Michael John Zoltek (1196)	Michael John Zoltek Woolpert, Inc. 2110 SW 38th Ter Cape Coral, FL 33914 585-754-6500 E-mail: mike.zoltek@gmail.com E-mail: mike.zoltek@woolpert.com	AL PLS - 25291 AZ RLS - 53351 CA PLS - 8878 CO PLS - 38433 CT PLS - 70378 FL PLS - 5751 GA RLS - 2976 ID PLS - 14353 KY PLS - 4245 LA PLS - 4994 MS PLS - 3088 NC PLS - L-5094 ND PLS - 6646 NJ PLS - 24GS04341300 NM PLS - 20558 NV PLS - 21183 NY RLS - 50883 OR Other - 88009RPP PA PLS - SU075435 SC PLS - 27462 SD PLS - 10187 TN PLS - 2836 TX RLS - 6221 WA PLS - 50992 WI PLS - 3039-8 WV PLS - 2219	Accretions in the Public Land Survey System (1) Avulsions in the Public Land Survey System (1) Deizell 158 IBLA 238 (1) February 2018 Las Vegas CFedS Workshop (2) Hasenyager 176 IBLA 252 (1) Hillstrom 180 IBLA 388 (2) Introduction to the Geographic Coordinate Database (3) Monumentation and the Corner Record (3) Non-Rectangular Surveys (9) Relictions in the Public Land Survey System (1) Resurveying an Entire GLO Township (2) Specifications for Descriptions of Land (1) Stoddard Jacobsen and Robert C. Downer (2) Swamp Land Grants, Omitted Area and Island Surveys (1) The 2009 Manual of Surveying Instructions (2) The Landslide Report (2) Tussio 37 IBLA 135 (1) William D. Brown 137 IBLA 31 (1)